Expedited Settlement Offer Worksheet

Deficiencies Form

Consult instructions regarding eligibility criteria and procedures prior to use

version 10.3.4



	LEGAL NAME AND MAILING ADDRESS OF OPERATOR	Telephone Numbe	r NPDES Per	mit Number	r.
1	John Burggraf	801-292-1411	UTR370389	1	
i 1	Hughes General Contractors				
	900 North Redwood Rd.	Inspector Name;	Stephanie D	elong	
	North Selt Lake, UT 84054	Inspector Agency:	US EPA		
		Entrance Interview	Conducted:	Yes	
		Exit Interview Cond	ucted:	Yes	
	LOCATION AND ADDRESS OF SITE	Exit Interview given	to: Larry Woodi	uff, Tim Sob	otka, J. Noorda
2	Logan High School - Hughes General Contractors	Exit Interview time:	11:00	Date:	07/12/2016
	162 W 100 S				
	Logan, UT 84321				
	FACILITY DESCRIPTION / CONTACT NAMES				
	Name of Site Contact (ESO Worksheet recipient):	John Burggraf			
		John Burggraf,			
	Name of Authorized Official (40 CFR 122.22):		1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 -		
1	Inspection Date:				
	Start Construction Date:	03/22/2015			
	Estimated Completion Construction Date:	12/21/2017			
	If Unpermitted, Number of Months Unpermitted:				
	Name of Receiving Water Body (Indicate whether 303(d) listed):				
	Acres Currently Disturbed Acres to be Disturbed in Whole Common Plan:	13,75	13:75		
	Has Operator Pagineted Palatal Erstvilly or TMDL Walver per 44 CER 122 26(b)(15)2				

		Has operator Requested Rakital Elosing	DE INDE WAIVAI DET 44 CERT 122.20(DI[ID])	· · · · · · · · · · · · · · · · · · ·				
3		PERMIT COVERAGE Operator unpermitted for one month (# months unpermitted equals number of violations). Discharge without a permit.	Findings	Citation Reference** CWA 301	R C A*	No. of Deficien- cies	Dollar Amount \$500.00	Total
		SWPPP REVIEW						
4		SWPPP not prepared (If no SWPPP, leave elements 5 - 30 blank)		UCGP 7.1.1			\$5,000.00	
5		SWPPP prepared but prepared after construction start (# of months = # of violations)		UCGP 7.1.1			\$75,00	=
6		SWPPP does not identify all potential sources of pollution to include: porta-pottys, fuel tanks, staging areas, waste containers, chemical storage areas, concrete cure, paints, solvents, etc		UCGP 7.2.6,a			\$250.00	2
7		SWPPP does not identify all operators for the project site and the areas of the site over which each operator has control	€,	UCGP 7.1.1	-		\$500,00	=
-8		SWPPP does not have site description, as follows:	The following findings were not included in the site map;					
	A	Nature of activity in description	a. The equipment storage yard north of	UCGP 7.2.2			\$100.00	
		Intended sequence of major activities	100 S (photos 841-843);	UCGP 7.2.4	_		\$100.00	
		Total disturbed acreage	b. The property boundary or the extents	UCGP 7.2.2			\$100.00	
		General location map	of construction activities or where earth-	UCGP 7.2.5	+		\$100.00	
	Ë	Site map is not included in SWPPP.	disturbing activities will occur;	000F 1,2,5		ļļ	000.001	<u></u>

		areas of disturbance, locations of major controls, structural practices shown, stabilization practices, offsite materials, waste, borrow or equipment storage ageas, surface waters, discharge points, areas of final stabilization (count each omission under 8F es 1 violation)	 Approximate slopes before and after major grading activities; Locations where sediment, soil, or other construction materials will be stockpiled, Stockpiles were observed on the site (photos 833 and 839); and Topography of the site or drainage patterns. 	UCGP 7.2.5	Yes	5	\$50,00		-\$250
ļ	G	Location/description industrial activities, like concrete or asphalt batch plants		UCGP 7.2.5.a.vii			\$500.00	=	
-9	j	SWPPP does not:		399411998/185523581876	1800 P			1.1.1. Aug	server and
		Describe all pollution control measures (e.g. BMPs)		UCGP 7.2.9			\$750.00	=	
1	:		e gana e de la companya e	UCGP 7:2.4			\$250.00		
	8	Describe sequence for implementation							
						1			
		Detail operator(s) responsible for implementation		UCGP 7.2.1			\$250.00		
10		SWPPP does not describe interim stabilization practices.		UCGP 2:2:&. 7.2.9.c			\$2,50.00	=	
11		SWPPP does not describe permanent stabilization practices		UCGP 2:2 & 7.2:9			\$250:00	=	
12		SWPPP does not describe a schedule to implement stabilization practices	No final stabilization with estimated start dates and duration was discussed in the SWPPP; and		Yes	1	\$250.00		.\$250
13		Following dates are not recorded: major grading activities; construction temporarily or permanently ceased; stabilization measures initiated (count each omission under 13 as 1 violation)					\$250,00	=	
14		SWPPP does not have description of structural practices to divert flows from exposed soils, retain flows, or limit runoff from exposed areas		UCGP 2.1.3a-b & 7.2.9.a			\$500.00		
15		SWPPP does not have a description of measures. Ihat will be installed during the construction process to control pollutants in storm water discharges that will occur AFTER construction operations have been completed					\$500.00	Ŧ	
16		SWPPP does not describe measures to prevent discharge of solid materials to waters of the US, except as authorized by 404 permit					\$500:00		
17		SWPPP does not describe measures to minimize off site vehicle tracking and generation of dust		UCGP 2.1.2.c, 2.1.2.e, & 7.2.9.a iil			\$500,00		5051
18		w/updates re: controls used to reduce pollutants	discussed in the SWPPP. A concrete	UCGP 7.2.6.b. 7,2.10.b.& 2.3.3.c	Yes	1	\$250.00		\$250
19		SWPPP does not have description of pollutant sources from areas other than construction (asphalt or concrete plants) w/ updates re: controls to reduce pollutants from these materials		UCGP 1,3.3 & 7.2.6.a			\$500.00	=	
20		storm water discharges listed in subpart 1.3.B of the CGP		7.2,7	Yes	1	\$500.00	1	\$500
21		pollution prevention measures for non-storm water	Pollutution prevention measures for non- stormwater discharges were not addressed in the SWPPP.	UCGP 1.3.4, 7.2.7, & 7.2.9.a	Yes	1	\$500,00	*	\$50

22	Endangered Species Act documentation is not in			T		Г	\$500.00	=	
	SWPPP		Anna and the state of the state of the		200300400000000		No. Contraction of the second		L'Anno constante de la constant
23	Historic Properties (Reserved) Copy of permit and/or NOI not in SWPPP (count		UCGP 7.2.1 &			158	\$250.00		
	each omission under 24 as 1 violation)		7.2.16	ļ				_1	
25	SWPPP is not consistent with requirements specified in applicable sediment and erosion site						\$750.00	=	
	plans or site permits, or storm water management								
	plans or site permits approved by State, Tribal or								
·	local officials (é.g., MS4 requirements)								
26	SWPPP has not been updated to remain consistent		UCGP 7.4.1.a			Π	\$250.00	=	
	with changes applicable to protecting surface waters in State. Tribal or local erosion plans								
		·····							
27	Copies of inspection reports have not been retained as part of the SWPPP for 3 years from date permit	:	UCGP 4.1.7.c & 5.4.3				\$500.00	=	
	coverage terminates		u,n.u						
28	SWPPP has not been updated/modified to reflect	The site map did not reflect the site. For	UCGP 5.4.2.5 & 7.4.1	Yes	2	·	\$50.00	=	\$100
	change at site effecting discharge, or where inspections identify SWPPP/BMPs as ineffective,	example; the equipment storage yard north of 100 S was not depicted on the	7						
	updates to SWPPP regarding modifications to	site map (photos 841-843). Although							
	BMPs not made within 7 days of such inspection (count each omission under under 28 as 1 violation)	some stormwater controls were shown on the site map, they did not reflect the							
		control observed at the site during the							
		inspection. For example, there was no vehicle tracking control where shown on							
		the site map (photos 834, 835, 844, and							
		845).							
29	Copy of SWPPP not retained on site	· · · · · · · · · · · · · · · · · · ·	UCGP 7,1.1.8	_ ·			\$500.00	=	
~9 			7.3						
	A SWPPP not made available upon request		UCGP 7.3	<u>ж.</u>	<u>.</u>		\$500.00		
30	SWPPP not signed/certified		UCGP 7,2:15		<u> </u>		\$500,00		
		1	·····	Sub	total SWP	PP I I	Deficiencie	<u>s</u> .	\$1,850
	INSPECTIONS							-	
31	Inspections not performed and documented at least once every 14 days and within 24 hours after storm	Not all inspections occurred every 7 days, which was the inspection	UCGP 4.1.2, 4.1.3, 4.1.4,	Yės	2		\$250,00	=	\$500
	event greater than 0.5 inches or greater (pot		4.1.7, 7.2.11.b, &					1	
	required if, temp stabilization; runoff unlikely due to	indicated by the SWPPP. Between the	7.2.11.c						
1	winter conditions; construction during arid periods in arid areas) (Count each failure to inspect and	6/9/16 inspection and the 6/17/16 inspection, 8 days lapsed. Between the							
	document as one violation).	6/23/16 inspection and the 7/8/16							
		inspection, 15 days lapsed. It is							
		unknown what frequency the inspections occurred at between 4/9/16 and 5/13/16,							
		because the reports did not include an							
		inspection date.							
			siyaaan is	eşek,			8 - M. K	··	
						1			
	No inspections conducted and documented (if				FALSE		True or		
	True, then leave elements 32-39 blank)				FALSE		True or False		
	True, then leave elements 32-39 blank) Number of Inspections expected if performed every 7 days:				FALSE				
	True, then teave elements 32-39 blank) Number of Inspections expected if performed every 7 days: Number of Inspections expected if performed bi-				FALSE				
-	True, then leave elements 32-39 blank) Number of Inspections expected if performed every 7 days:	: · · ·			FALSE				
20	True, then leave elements 32-39 blank) Number of Inspections expected if performed every 7 days: Number of Inspections expected if performed bi- weekly: If known, number of days of rainfall of >0.5"	Inspections were not performed by	UCGP 4.1.1, 6, &	Yes					\$750
32	True, then leave elements 32-39 blank) Number of Inspections expected if performed every 7 days: Number of Inspections expected if performed bi- weekly:	Inspections were not performed by qualified, certified personnel. The	UCGP 4.1.1, 6, & 7.2.12	Yes			False		\$750
32	True, then leave elements 32-39 blank) Number of Inspections expected if performed every 7 days: Number of Inspections expected if performed bi- weekly: If known, number of days of rainfall of >0.5"	qualified, certified personnel. The SWPPP did not indicate that personnel		Yes			False		\$750
32	True, then leave elements 32-39 blank) Number of Inspections expected if performed every 7 days: Number of Inspections expected if performed bi- weekly: If known, number of days of rainfall of >0.5"	qualified, certified personnel. The SWPPP did not indicate that personnel were trained. Larry Woodruff stated that he had not been trained in stormwater,		Yes			False		\$750
32	True, then leave elements 32-39 blank) Number of Inspections expected if performed every 7 days: Number of Inspections expected if performed bi- weekly: If known, number of days of rainfall of >0.5"	qualified, certified personnel. The SWPPP did not indicate that personnel were trained. Larry Woodruff slated that		Yes			False		\$750

¢

33		All areas disturbed by construction activity or used for storage of materials and which exposed to precipitation not inspected		UCGP.4.1.5.a & 4.1.5.c				\$50,00	5	
34	1	All politicion control measures not inspected to ensure proper operation	Observations indicate the Hughes inspector did not check whether all erosion and sediment controls and pollution prevention controls were installed, appeared to be operational, and were working as intended to minimize pollutant discharges. Observations indicate the Hughes inspector did not determine if any controls needed to be replaced, repaired, or maintained. The inspection reports contained a section to list the stornwater controls that were installed. This was blank on the inspection reports. for 5/19/16, 5/26/16, and 6/2/16. During the EPA's inspection, trackout was observed with no vehicle tracking control, and dumpsters were not covered (photos 834-835; 641, 844-845; 850, 852, and 858). The concrete washout had concrete spilled around it; and there was concrete spilled on the ground around the concrete mixers (photos 848 and 857).	UCGP 4,1.5,b &	Yes	3		\$50.00	11	\$1:
35		Discharge locations are not observed and inspected		Part 4.1.5.e				\$50.00		
36	-	For discharge locations that are not accessible.						\$50.00	=	
37		nearby locations are not inspected Entrance/exit not inspected for off-site tracking		UCGP 4.1.5 & 4.1.5	-			\$50.00	=	
38		location of sediment/pollutant discharge, BMP(s) requiring maintenance, BMP(s) that have failed, BMP(s) that are needed, corrective action required including changes/updates to SWPPP and	No inspection date was included on the reports between 4/9/16 and 5/13/16. What was assumed to be the 5/26/16 inspection report included this date beside the review signature, but the inspection date was left blank. No corrective actions were taken according to the inspection reports beliween 3/24/16 and 7/8/16. Larry Woodruff stated he had noted that some corrective actions were needed, but none had been taken. He stated he planned to keep them on the corrective action log until they were corrected. A total of 15 inspections were incomplete.	UCGP 4.1.7, 4.1.6, & 5,4	Yes	15		\$50.00	11	- \$7:
39		Inspection reports not properly signed/certified. (count each failure to to sign/certify as 1 violation)	· · · · · · · · · · · · · · · · · · ·	UCGP 4.1.7,5				\$50,00	11	
4				Sut	tota	Inspectio	ns I	Deficienci	es	\$2,15
40		AVAILABILITY OF RECORDS Sign/notice not posted		UCGP 1.5	+	·		\$250.00	=	
	A	Does not contain copy of complete NOI						\$50.00	=	
	B	Location of SWPPP or contact person for scheduling viewing times where on-site location for SWPPP unavailable not noted on sign		UCGP 1.5				\$50.00		
			· · · · · · · · · · · · · · · · · · ·	·····	Subt	otai Reco	rds I	Deficienci	es	
			· · · · · · · · · · · · · · · · · · ·		<u> </u>					
41	_	BEST MANAGEMENT PRACTICES No velocity dissipation devices located at discharge	· · · · · · · · · · · · · · · · · · ·	UCGP 2.1.3.a &				\$500,00	=	
+1	ан . С	locations or outfall channels to ensure non-erosive flow to receiving water	• .	2.1,3.6.3						•
	·	Control measures are not properly:	The following stormwater controls		1.20 500	183838382	1604 bar	en anter en anter Cal	144 144	ustatetta a

			1000004	is c	1	т т			
	Selected, installed and maintained	required by the permit were not implemented at the site: a. The Little Logan River runs through the southern portion of the construction site. No buffer or equivalent erosich/sediment control was used (photo 853); b. No vehicle tracking control was used at any of the 5 vehicle exits on 100 S or 100 W, or the vehicle tracking control had filled with sediment (photos 834- 835, 844-845, 850, 852, and 858). The SWPPP discussed street sweeping, but this had not been done recently. Sediment was observed in the streets	UCGP 2.1.1.c, 2.1.1.d, 2.1.3.a, 2.1.3.b, 2.2, & 2.3.2	Yes	15		\$500,00		-\$7,500
E	Maintenance not performed prior to next anticipated storm event	(photos 834, 835, 836, 840, 844, 850, 852, 854, 858); c. Stockpiles were observed on the site without any controls (photos 833 and 839); and d. Although storm drain inlet protection was used on storm drains within the area of disturbance, no storm drain inlets had controls along 100 S, 100 W, or in the parking lot on the northwest corner of the site near a storage yard (photos 836-838, 840, and 855-856). This was observed at eight storm drains.	UCGP 2.1.1.d.ii & 2.1.1.iii				\$250.00) =	
	(count each failure to select, install, maintein each BMP as one violation)								
43	When sediment escapes the site, it is not removed at a frequency necessary to minimize off-site impacts	Corrective actions listed included trackout. Reports for 3/24/16 and 3/31/16 listed trackout in areas A and D, and dumpsters not covered. During the EPA's inspection, trackout was observed with no vehicle tracking control, and dumpsters were not covered (photos 634-835, 841, 844-845, 850, 852, and 858). One count was included for each inspection where trackout is known and one count was included based on the EPA's inspection observations.	UCGP 2.1,2.c.iv	Yes	3		\$500,00	.1	\$1,500
	Litter, construction debris, and construction chemicals exposed to storm water are not prevented from becoming a pollutant source (e.g. screening outfails, pickup daily, etc.)	The concrete washout had concrete spilled around it, and there was concrete spilled on the ground around the concrete mixers (photos 848 and 857). Materials listed in the permit, including oils and gasoline, were stored in areas without cover or similarly controlled to prevent discharge of pollutants. Oil was stored in an area without cover in the equipment storage yard north of 100 S (photo 843). Gasoline and engine oil was observed stored in an area without cover by the concrete mixers south of 100 S (photos 846 and 848). Trash and	UCGP 2.3.3	Yes	4		\$500.00	1	\$2,000
		debris were observed in the storage yard north of 100 S (photo 842). Dumpsters and port-o-lets were observed on the site. Trash was also observed around a storm drain on 100 S (photo 840).							
45	Stabilization measures are not initiated as soon as practible on portions of the site where construction activities have temporarily or permanently ceased within 14 days after such cessation	debris were observed in the storage yard north of 100 S (photo 842). Dumpsters and port-o-lets were observed on the site. Trash was also observed around a	UCGP 2.2				\$500.00		
45	practible on portions of the site where construction activities have temporarily or permanently ceased within 14 days after such cessation *Exceptions:	debris were observed in the storage yard north of 100 S (photo 842). Dumpsters and port-o-lets were observed on the site. Trash was also observed around a	UCGP 2.2				\$500.00		
45	practible on portions of the site where construction activities have temporarily or permanently ceased within 14 days after such cessation	debris were observed in the storage yard north of 100 S (photo 842). Dumpsters and port-o-lets were observed on the site. Trash was also observed around a							

46		Common Drainage of 10+ acres does not have a sedimentation basin for the 2 year, 24 hour storm, or 3600 cubic fl. storage per acre drained		,,,,,	UCGP 2.1,3.b.).1		\$1,000.00 =	
	Ä	Where sedimentation basin not attainable, smaller sediment basins, sediment traps, or erosion controls not implemented for downslope boundaries					\$1,000;00 =	
		Sediment not removed from sediment basin or traps when design capacity reduced by 50% or more			UCGP: 2.1,3.b.ii		.\$500.00 ≈	
47		Common Drainage less than 10 acres does not have sediment traps, silt fences; vegetative buffer strips, or equivalent sediment controls for all down slope boundaries (not required if sedimentation sediment basin meeting criteria in 46 above)		<u></u> ,	UCGP:2:1.1.b. 2.1.1.c, & 2.1.2		\$500.00 =	
		Sediment not removed from sediment trap when design capacity reduced by 50% or more			UCGP 2.1.1.d &		\$500.00 =	
I		Idesign capacity reduced by 50 % of more			14,4,4	Subtotal BMF	P Deficiencies	\$11,000
48		SMALL BUSINESS EVALUATION Is the Owner/Operator a Small Business?	Unknown	<u></u>	<u> </u>	T T T	<u> </u>	
48		A small business is defined by EPA's Small Business Compliance Policy as: "a person, corporation, partnership, or other entity that employs 100 or fewer individuals (across all facilities and operations owned by the small business)." The number of employees should be considered as full-time equivalents on an annual basis, including contract employees (see 40 CFR 372.3). A full time employee unit is 2000 hours worked per year.	UIKIOWI	:				
		Honos por your.	<u> </u>	· · · · ·	The second second second second second	Total Expedited	Settlement:	\$15,000
		* Requires Corrective Action				· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·

.

4

š.

and the second second

.