

2010 AUG -5 PM 2:04

FILED EPA REGION VIH MEARING CLERK

PO BOX 792 332 WEST RAILROAD AVENUE PRICE UTAH 84501-0792 435-637-3211 435-637-6628 facsimile

July 30, 2010

Ms. Tina Artemis, Regional Hearing Clerk (8RC) U.S. EPA, Region 8 1595 Wynkoop Street Denver, CO 80202-1129

Re: Docket no. CWA-08-2010-0020

Dear Ms. Artemis:

This correspondence will verify receipt of the administrative complaint dated July 26, 2010 and received July 28, 2010, in Price, Utah.

We have been working on the recommendations outline in Ms. Nakad's September 1, 2009 on site inspection. We have contacted the consulting firm used in our original spill prevention and control and countermeasure (SPCC) plan written in July of 2000 asking for their assistance in updating our plan to include Ms. Nakad's comments. Additionally, we have been working on the dirt berm and concrete retaining wall mentioned in Ms. Nakad's notes.

We began immediately after our inspection making the improvements outlined on the inspection report. Photos of our progress were sent to Ms. Nakad. She replied to the photos on September 30, 2009 (see copy of her remarks, exhibit 1). I responded to Ms. Nakad on October 1, 2009 (copy attached exhibit 2; I apologize for the poor quality).

I was somewhat taken back by the July 26, 2010 complaint letter. We do of course wish to contest the allegations and penalties outlined in the complaint. Your assistance in doing so would be appreciated.

I intend to forward the information from the engineering firm updating our SPCC plan. Please advise any additional information required.

Sincerely,

Ellís L. Pierce President Pierce Oil Company, Inc.

FXHIBIT 1

From: Date: 09/30/09 10:43:52 To: Cc: ; Subject: Re: Fw: 18 pictures for you

I had a look at the photos you sent. It is good that you compacted the dirt berm before you put the loose stones on top. However, I think it would serve you better to put the straw bales behind the dirt/stone berm rather than behind the concrete berm (unless there are cracks in the concrete berm - if so, the cracks must be repaired). You must maintain the dirt/stone berm to ensure that it does not wear or wash away as the previous berm did. I am also concerned as to whether the totes (if any have oil in them) on the west side have enough berm left along the south side. It was difficult to tell when I did the inspection due to the vegetation. Please check to ensure that a discharge from the totes would not flow down gradient to the storm drain in the street behind the facility. While you only have to provide containment sufficient for the largest tote, the containment must be able to prevent a discharge to navigable waters. The slope on the south side is quite steep towards the storm drain and a discharge may flow quickly to the drain especially during a rain event.

Should you open a road to the street behind the facility, you will need to install a traffic bump or trench to ensure that you have sufficient containment to prevent discharged oil from flowing off site into the storm drain in the street as the storm drains discharges to the Price River. Also did you install any berm on the east side of the warehouse where there are drums without containment near the fence?

I have not received corrections to the SPCC Plan. If that has been accomplished, please send the revised pages to the SPCC Plan.

Jane Nakad OPA Compliance Specialist and Enforcement Officer Technical Enforcement Program 303-312-6202

U.S. Environmental Protection Agency Mail Code: 8ENF-UFO 1595 Wynkoop Street Denver, CO 80202

The preceding message, including any attachments, contains information that may be confidential and may be exempt from disclosure under applicable law. It is intended to be conveyed only to the named recipient(s). If you recieved this message in error or if you are not the intended recipient, please notify the sender and delete the message from your system. Any use, dissemination, distribution, or reproduction of this message by unintended recipients is not authorized and may be unlawful.

EXHIBIT 2

Prom Date: 10/01/09 08:19 55 To: Co Subject: Rel Fw. 12 pintoles for you

As Nakad

Your suggestion to place the straw balks behind the dim beint makes sense. I will attend to it

The concrete retaining way does not have any crucks in it, the purpose of the straw is to filter any contaminates that may find there way into the contaminant.

Should release occur from a lote on the west side the dat berrin would direct any liquid into the containment provided by the concrete retaining well, not towards the storm drain on Price river drive.

It is my intention to open an entrance to the city streat. When that is done I will address a water way that will insure any potential for contamination will be addressed.

If was my intention to make the corrections to the SPCC plan after I have addressed all the tissues we discussed. I have constructed a borm behard the storage shed on the south nast side of the property. That project is nearly complete, , will send you dictures upon completion.

Thank you for your assistance 4 appreciate your help and patience.

Pierce Oil Co. Inc Pierce Oil Co. Inc Piol Box 792 Phoel Utab 8450 (431, 537 5211 X 12 Fiar 435 637 6628

- - - - - - - Web with the

Ptom Date: 19/30/09/10/43/52 To: Ce Subject for Swi 18 (subjection)

Interview power at the photoe your want. It is prove that you compare in the uninterm before you put the conservatives on top. However, the net in the servation of the top of the standard common the first state of momentum terminal the superior to messare are are drop on the interview of servation of servations of the state of the terminal terminal the superior to messare are are drop on the terminal terminal termination of the superior termination of the termination of servations.