


**Appendix J**  
**Site Photos – July/August 2009**



**View of Typical 35' - 45' Length Roof Trusses in Metal Beam Stockpile B on West Side of SIM Property (7/22/09)**



**View of Typical 12' - 25' Length Girts & Purlins in Metal Beam Stockpile A on West Side of SIM Property (7/22/09)**



**Support Zone on East Side of SIM Property (7/16/09)**



**Exclusion Zone on West Side of SIM Property; Background shows material handling logistics of typical 35' - 45' Length Roof Truss being relocated (7/16/09)**



**Typical Metal Beam Segregation & Sampling Staging Areas (7/16/09)**



**Metal Beams Inspected & Segregated from Stockpile C (7/16/09)**



**Typical 35' - 45' Length Roof Trusses (foreground) and 12' - 25' Length Girts & Purlins (background) Inspected & Segregated from Stockpile C (7/16/09)**




**Typical 10' - 12' Length Roof Truss Column Supports & Tails (Middle of photo) Inspected & Segregated from Stockpile C (7/22/09)**



**Typical 12' – 25' Length Girts & Purlins Inspected & Segregated from Stockpile C  
(7/16/09)**



**Metal Beam Decontamination Tent (7/22/09)**



**Inside Metal Beam Decontamination Tent (7/22/09)**



**Stockpile Area C – Metal Beam Inspection, Segregation (background) & Sampling (foreground) 12' – 25' Length Girts & Purlins (7/14/09)**



**Metal Beam Stockpile Area C – Inspection, Segregation & Soil Sampling Completed  
(8/24/09)**



**Metal Beam Stockpile Area B – Inspection, Segregation & Soil Sampling Completed  
(8/24/09)**



**Metal Beam Stockpile Area A – Inspection, Segregation & Soil Sampling Completed  
(8/24/09)**



**Metal Beam Stockpile Area B & A – Inspection, Segregation & Soil Sampling Completed  
(8/24/09)**



**Site ready for demobilization - photo of EZ entrance facing south; this photo also depicts typical inclement weather, high winds and above normal heavy rainfalls that caused long workday delays and several Site shutdowns (8/27/09)**



**Site ready for demobilization - photo of EZ, looking south (stockpile C area- right edge). Photo also depicts typical inclement weather, high winds and above normal heavy rainfalls that caused long workday delays and several Site shutdowns (8/27/09)**



**Site ready for demobilization - photo of EZ, looking south towards stockpile C area. Photo also depicts typical inclement weather, high winds and above normal heavy rainfalls that caused long workday delays and several Site shutdowns (8/27/09)**



**Site ready for demobilization - photo of EZ, looking west. Photo also depicts typical inclement weather, high winds and above normal heavy rainfalls that caused long workday delays and several Site shutdowns (8/27/09)**



**Site ready for demobilization - photo of EZ looking west at former decontamination tent area. (stockpile B area- right edge). Photo also depicts typical inclement weather, high winds and above normal heavy rainfalls that caused long workday delays and several Site shutdowns (8/27/09)**



**Site ready for demobilization - photo of EZ looking northwest at former stockpile B area (foreground) & A (background). Photo also depicts typical inclement weather, high winds and above normal heavy rainfalls that caused long workday delays and several Site shutdowns (8/27/09)**



**Site ready for demobilization - photo of EZ looking north. Photo also depicts typical inclement weather, high winds and above normal heavy rainfalls that caused long workday delays and several Site shutdowns (8/27/09)**



**Photo at EZ entrance showing site ready for demobilization; decontamination tent & storage containers demobilized. Soil and Debris rolloffs ready for transportation to Metro Waste Authority Landfill (8/27/09)**



**Photo from cul-de-sac showing site ready for demobilization; support zone trailers, storage containers & equipment demobilized. (Stockpile in left edge of photo from SIM activities on east side of property) (8/27/09)**