

## **5.0 PROGRESS SINCE THE LAST FIVE-YEAR REVIEW**

The issues listed below from the First Five-Year Review were addressed before the Second Five-Year Review was completed:

- Internal land use restrictions were filed for PSCs SS-42 and ST-18
- Radiological monitoring continued annually at PSC RW-02
- Annual groundwater monitoring was conducted at PSCs SS-42 and ST-18
- Based on the recommendation of ADEQ in the First Five-Year Review, routine groundwater sampling was conducted at three additional PSCs: SD-20, FT-07E, and RW-02. As requested by ADEQ, groundwater sampling was completed at SD-20 and FT-07E during the annual sampling event conducted before the preparation of this Second Five-Year Review. An attempt was made to collect samples from MW-124 at site RW-02, but the well was discovered to be collapsed; therefore, no sample could be retrieved.

*This page was intentionally left blank.*