

Sources
 Base map: 1938 Sanborn Fire Insurance Map
 Ditch: Composite of Figures 9 and 10 (LOL0086747 and LOL0086749) in USEPA Aerial Photo Analysis, June 1999 [Joint Expert Witness Ref. 189] and Williams Bros. Rainfall and Surface Runoff Survey, Sept 1974 [Joint Expert Witness Ref. 225]

Legend

▲ < 7	→ Drainage Features
▲ 7 - 16	▭ Cotton Gin Structures (1938)
▲ 16 - 40	▭ Arsenic Remedial Design
▲ 40 - 79.5	▭ ROD Limits
▲ > 79.5	




	Figure 2
	Arsenic Remedial Design Area and Potential Sources
91 Fulton Street Boonton, New Jersey 07005	January 15, 2016