




Exhibit 9

Complainant's Ex. 9

Photo Log - Stevenson Site WE 408 - 12/9/10		
MAP POINT	jpg #s	description/comment
A	195-199	beginning of fill at south west corner of site
B	200-207	fill adjacent to wetlands
C	208-211	edge of levee fill looking east
D	212-218	cypress, cattail, standing water
E	219-220	River between levee and small island
F	221-228	panorama panning right to left; 2nd fill area in the left side of 227-228
G	229	wet area on left; looking back toward I-10 bridge
G	230-236	looking from levee into wet area
H	237-242	S. edge of turnaround; note fill material
I	243-262	Truck turnaround area; note tracks & fill/debris
J	263-264	River Side looking upriver
J	265	Looking back at I-10 bridge towards Beaumont
K	266	Looking back south at turnaround area in mid distance
L	267-270	wet area near north end of site
L	271-272	River Side looking upriver; note crushed culvert pipe
M	273-275	remnant trees/island on the River side of levee
N	276	on the north edge of site looking at river
O	277-283;	Looking into wet area at the north end of site
O	284	Looking upriver on River side of levee at north end of site
O	285-288	Looking south into wet area at north end of site
btw J & I	289-293	Walking back from the north end, looking back at the edge of the turnaround area
I	294-297	fill area; note tracks
I	298-299	fill area without vegetation







Compliments Exo



Exhibit 10


Complainant's Ex. 10


Photo Log - Stevenson Site WE 408 - 12/9/10		
MAP POINT	jpg #s	description/comment
A	195-199	beginning of fill at south west corner of site
B	200-207	fill adjacent to wetlands
C	208-211	edge of levee fill looking east
D	212-218	cypress, cattail, standing water
E	219-220	River between levee and small island
F	221-228	panorama panning right to left; 2nd fill area in the left side of 227-228
G	229	wet area on left; looking back toward I-10 bridge
G	230-236	looking from levee into wet area
H	237-242	S. edge of turnaround; note fill material
I	243-262	Truck turnaround area; note tracks & fill/debris
J	263-264	River Side looking upriver
J	265	Looking back at I-10 bridge towards Beaumont
K	266	Looking back south at turnaround area in mid distance
L	267-270	wet area near north end of site
L	271-272	River Side looking upriver; note crushed culvert pipe
M	273-275	remnant trees/island on the River side of levee
N	276	on the north edge of site looking at river
O	277-283;	Looking into wet area at the north end of site
O	284	Looking upriver on River side of levee at north end of site
O	285-288	Looking south into wet area at north end of site
btw J & I	289-293	Walking back from the north end, looking back at the edge of the turnaround area
I	294-297	fill area; note tracks
I	298-299	fill area without vegetation



© 2013

2013







Compendium's Exam









Complaint's Ex. 10

Exhibit 11

Complainant's Ex. 11

Photo Log - Stevenson Site WE 408 - 12/9/10		
MAP POINT	jpg #s	description/comment
A	195-199	beginning of fill at south west corner of site
B	200-207	fill adjacent to wetlands
C	208-211	edge of levee fill looking east
D	212-218	cypress, cattail, standing water
E	219-220	River between levee and small island
F	221-228	panorama panning right to left; 2nd fill area in the left side of 227-228
G	229	wet area on left; looking back toward I-10 bridge
G	230-236	looking from levee into wet area
H	237-242	S. edge of turnaround; note fill material
I	243-262	Truck turnaround area; note tracks & fill/debris
J	263-264	River Side looking upriver
J	265	Looking back at I-10 bridge towards Beaumont
K	266	Looking back south at turnaround area in mid distance
L	267-270	wet area near north end of site
L	271-272	River Side looking upriver; note crushed culvert pipe
M	273-275	remnant trees/island on the River side of levee
N	276	on the north edge of site looking at river
O	277-283;	Looking into wet area at the north end of site
O	284	Looking upriver on River side of levee at north end of site
O	285-288	Looking south into wet area at north end of site
btw J & I	289-293	Walking back from the north end, looking back at the edge of the turnaround area
I	294-297	fill area; note tracks
I	298-299	fill area without vegetation





Exhibit 12


Complainant's Ex. 12


Photo Log - Stevenson Site WE 408 - 12/9/10		
MAP POINT	jpg #s	description/comment
A	195-199	beginning of fill at south west corner of site
B	200-207	fill adjacent to wetlands
C	208-211	edge of levee fill looking east
D	212-218	cypress, cattail, standing water
E	219-220	River between levee and small island
F	221-228	panorama panning right to left; 2nd fill area in the left side of 227-228
G	229	wet area on left; looking back toward I-10 bridge
G	230-236	looking from levee into wet area
H	237-242	S. edge of turnaround; note fill material
I	243-262	Truck turnaround area; note tracks & fill/debris
J	263-264	River Side looking upriver
J	265	Looking back at I-10 bridge towards Beaumont
K	266	Looking back south at turnaround area in mid distance
L	267-270	wet area near north end of site
L	271-272	River Side looking upriver; note crushed culvert pipe
M	273-275	remnant trees/island on the River side of levee
N	276	on the north edge of site looking at river
O	277-283	Looking into wet area at the north end of site
O	284	Looking upriver on River side of levee at north end of site
O	285-288	Looking south into wet area at north end of site
btw J & I	289-293	Walking back from the north end, looking back at the edge of the turnaround area
I	294-297	fill area; note tracks
I	298-299	fill area without vegetation














COMI

12/12

Complainant's Ex. 12




Cont. Ex. 12



Exhib. 13

Complainant's Ex. 13

Photo Log - Stevenson Site WE 408 - 12/9/10		
MAP POINT	jpg #s	description/comment
A	195-199	beginning of fill at south west corner of site
B	200-207	fill adjacent to wetlands
C	208-211	edge of levee fill looking east
D	212-218	cypress, cattail, standing water
E	219-220	River between levee and small island
F	221-228	panorama panning right to left; 2nd fill area in the left side of 227-228
G	229	wet area on left; looking back toward I-10 bridge
G	230-236	looking from levee into wet area
H	237-242	S. edge of turnaround; note fill material
I	243-262	Truck turnaround area; note tracks & fill/debris
J	263-264	River Side looking upriver
J	265	Looking back at I-10 bridge towards Beaumont
K	266	Looking back south at turnaround area in mid distance
L	267-270	wet area near north end of site
L	271-272	River Side looking upriver; note crushed culvert pipe
M	273-275	remnant trees/island on the River side of levee
N	276	on the north edge of site looking at river
O	277-283;	Looking into wet area at the north end of site
O	284	Looking upriver on River side of levee at north end of site
O	285-288	Looking south into wet area at north end of site
btw J & I	289-293	Walking back from the north end, looking back at the edge of the turnaround area
I	294-297	fill area; note tracks
I	298-299	fill area without vegetation





Copyright © 1988

Exhibit 14

Complainant's Ex. 14

Photo Log - Stevenson Site WE 408 - 12/9/10		
MAP POINT	Jpg #s	description/comment
A	195-199	beginning of fill at south west corner of site
B	200-207	fill adjacent to wetlands
C	208-211	edge of levee fill looking east
D	212-218	cypress, callall, standing water
E	219-220	River between levee and small island
F	221-228	panorama panning right to left; 2nd fill area in the left side of 227-228
G	229	wet area on left; looking back toward I-10 bridge
G	230-236	looking from levee into wet area
H	237-242	S. edge of turnaround; note fill material
I	243-262	Truck turnaround area; note tracks & fill/debris
J	263-264	River Side looking upriver
J	265	Looking back at I-10 bridge towards Beaumont
K	266	Looking back south at turnaround area in mid distance
L	267-270	wet area near north end of site
L	271-272	River Side looking upriver; note crushed culvert pipe
M	273-275	remnant trees/island on the River side of levee
N	276	on the north edge of site looking at river
O	277-283	Looking into wet area at the north end of site
O	284	Looking upriver on River side of levee at north end of site
O	285-288	Looking south into wet area at north end of site
btw J & I	289-293	Walking back from the north end, looking back at the edge of the turnaround area
I	294-297	fill area; note tracks
I	298-299	fill area without vegetation





Complainant Ex. 14






Exhibit 15

Complainant's Ex. 15

Photo Log - Stevenson Site WE 408 - 12/9/10		
MAP POINT	Jpg #s	description/comment
A	195-199	beginning of fill at south west corner of site
B	200-207	fill adjacent to wetlands
C	208-211	edge of levee fill looking east
D	212-218	cypress, cattail, standing water
E	219-220	River between levee and small island
F	221-228	panorama panning right to left; 2nd fill-area in the left side of 227-228
G	229	wet area on left; looking back toward I-10 bridge
G	230-236	looking from levee into wet area
H	237-242	S edge of turnaround; note fill material
I	243-262	Truck turnaround area; note tracks & fill/debris
J	263-264	River Side looking upriver
J	265	Looking back at I-10 bridge towards Beaumont
K	266	Looking back south at turnaround area in mid distance
L	267-270	wet area near north end of site
L	271-272	River Side looking upriver; note crushed culvert pipe
M	273-275	remnant trees/island on the River side of levee
N	276	on the north edge of site looking at river
O	277-283;	Looking into wet area at the north end of site
O	284	Looking upriver on River side of levee at north end of site
O	285-288	Looking south into wet area at north end of site
btw J & I	289-293	Walking back from the north end, looking back at the edge of the turnaround area
I	294-297	fill area; note tracks
I	298-299	fill area without vegetation



Complaints






Complian



1915

Cont.



© 2000 National Geographic Society





Exhibit 16

Complainant's Ex. 16

Photo Log - Stevenson Site WE 408 - 12/9/10		
MAP POINT	jpg #s	description/comment
A	195-199	beginning of fill at south west corner of site
B	200-207	fill adjacent to wetlands
C	208-211	edge of levee fill looking east
D	212-218	cypress, cattail, standing water
E	219-220	River between levee and small island
F	221-228	panorama panning right to left; 2nd fill area in the left side of 227-228
G	229	wet area on left; looking back toward I-10 bridge
G	230-236	looking from levee into wet area
H	237-242	S. edge of turnaround; note fill material
I	243-262	Truck turnaround area; note tracks & fill/debris
J	263-264	River Side looking upriver
J	265	Looking back at I-10 bridge towards Beaumont
K	266	Looking back south at turnaround area in mid distance
L	267-270	wet area near north end of site
L	271-272	River Side looking upriver; note crushed culvert pipe
M	273-275	remnant trees/island on the River side of levee
N	276	on the north edge of site looking at river
O	277-283;	Looking into wet area at the north end of site
O	284	Looking upriver on River side of levee at north end of site
O	285-288	Looking south into wet area at north end of site
btw J & I	289-293	Walking back from the north end, looking back at the edge of the turnaround area
I	294-297	fill area; note tracks
I	298-299	fill area without vegetation



Compton



Cont. Ex. 16

