



RECEIVED
OF
2008 APR 14 10 3

MILLER BREWING COMPANY

Certified Mail Return Receipt Requested 7007 2560 0001 5408 1279

April 8, 2008

RE: *Written Report Reportable Diesel Fuel Spill 2/11/2008 - Miller Brewing Company Fort Worth, Texas 76134*

Document Processing Center (7407M)
(Attn: Section 8(e) Coordinator)
Office of Pollution Prevention And Toxics
U.S. Environmental Protection Agency
1200 Pennsylvania Ave, NW
Washington, D.C. 20460

CONTAIN NO CBI

To Whom It May Concern:

Enclosed is the written report for the reportable diesel fuel spill on 2/11/2008 at Miller Brewing Company on 2/11/2008. The submission was not deliverable and returned to sender due to incorrect address. Reports were delivered to the Texas Commission on Environmental Quality and the Fort Worth Department of Environmental Management by reporting deadline. If you have any questions, please contact me at 817-551-3347 or via e-mail at gomez.mike@mbco.com.

Sincerely,

Mike Gomez
Brewery Environmental Coordinator

Enclosure (1)



RECEIVED
2008 APR 14 11:10:54

MR 311031



MILLER BREWING COMPANY

Certified Mail Return Receipt Requested # 7007 2560 0001 5408 0739

March 11, 2008

**Ms. Martha Britton
TCEQ DFW Region 4 Office
2301 Gravel Drive
Fort Worth, Texas 76118**

Re: Diesel Fuel Spill 2-11-2008 Miller Breweries West LP TCEQ Account # TA-0235-N


Ms. Britton,

Attached please find follow-up correspondence related to subject event:

- **Spill Response and Notification Form**
- **Incident Summary Report**
- **Facility site map will spill area highlighted**

Thank you for your consideration in this matter. If you have any questions or require additional information, please contact me at 817-551-3347 during normal business hours or via e-mail at gomez.mike@mbco.com

Sincerely,


**Mike Gomez
Brewery Environmental Coordinator**

(attachments)

**cc: National Emergency Response Center
Office of Toxic Substances
Document Processing Center
Environmental Protection Agency
401 M Street, S.W.
Washington, D.C. 20460
Attention: Section 8(e) Coordinator
Certified Mail Return Receipt Requested # 7007 2560 0001 5408 0746**

**Fort Worth Department of Environmental Management
5000 M.L. King Freeway
Fort Worth, Texas 76119
Attn: Mr. Clarence Reed
Certified Mail Return Receipt Requested # 7007 2560 0001 5408 0753**

FORM 10 - SPILL RESPONSE NOTIFICATION FORM

NAME AND PHONE NUMBER OF PERSON COMPLETING FORM	MIKE GOMEZ
Date & Time Form Completed/Updated	3-10-08 ~ 2:00pm
REPORTER INFORMATION	
Date and Time Initial Spill Report Received	(use 24 hour time)
REPORTER'S NAME (LAST, FIRST)	TORRES, MARTIN
REPORTER'S PHONE NUMBER	817-551-3489
Department	Technical Services
Position	Utilities Manager
Reporter's Location	Building # and Street: Bldg #22 7001 S. FREEWAY
	City: Fort Worth
	State and Zip Code: TEXAS 76134
Confidential	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
INCIDENT DESCRIPTION	
MATERIAL RELEASED	Oil/Fuel Type of Fuel <u>DIESEL #2</u> CAS# 68476-34-6 Hazmat/Unknown _____ Chemical Name & CHRIS Code _____
<input checked="" type="checkbox"/> YES NO	Is material a CERCLA Hazardous Substance? Yes No Is material an Extremely Hazardous Substance? Yes <input checked="" type="checkbox"/> NO
	Best Estimate of Quantity Released to Land <u>10 gal</u> (include units)
	Best Estimate of Quantity Released to Water <u>NONE</u> (include units)
	Is material still being released Yes <input checked="" type="checkbox"/> No _____ Current Spill Rate _____
TYPE OF INCIDENT (CIRCLE ALL THAT APPLY)	<input checked="" type="checkbox"/> Inside building or containment area <input type="checkbox"/> Navigable Water (storm drain) <input type="checkbox"/> Release to sanitary sewer <input type="checkbox"/> Fire <input type="checkbox"/> Explosion <input type="checkbox"/> Air Release <input checked="" type="checkbox"/> Soil
SOURCE AND CAUSE OF INCIDENT	Operator Error - DIESEL TANKS INSIDE BUILDING #12 OVERFILLED DURING REFUELING. DIESEL SPILLED TO ROOF AND CONTAINMENTS VIA TANK VENTS AND SOME TO GROUND VIA ROOF DRAIN SPOUTS.
DATE AND TIME OF INCIDENT	2-11-08 ~ 10:05AM

INCIDENT DESCRIPTION (CONT.)	
INCIDENT ADDRESS/LOCATION (Include state and zip code)	7001 S. FREEWAY Fort Worth, TX 76134 Miller Brewing Co (fire pump house bldg 12)
County	TARRANT
Nearest City & Distance from City (miles)	Fort Worth ~ 8 mi
Latitude (for marine spills)	___ Degrees ___ Minutes ___ Seconds N/A
Longitude (for marine spills)	___ Degrees ___ Minutes ___ Seconds N/A
Container Type & Capacity (include units)	Steel tanks with containment 275 gal / 300 gal
Facility Capacity (include units)	
WEATHER CONDITIONS	
Wind speed and direction; Temperature,	50°F 16-20 mph South
Precipitation Rate and Type;	NO precipitation
Wave/Current Information (marine spills)	N/A
RESPONSE ACTIONS	
Initial Actions Taken	<ol style="list-style-type: none"> 1. Locate spill reporter. 2. Establish initial command post location. 3. Assign recorder. 4. Rescue any injured individuals. 5. Secure spill area and determine need for evacuation. 6. Stop spill source, if not already accomplished. 7. Complete initial site and material hazard assessments. 8. Prepare site maps. 9. Establish hot/warm/cold/safe zones 10. Prevent spill from spreading.
Actions Taken to Stop Release	FUEL DELIVERY DRIVER STOPPED REFUELING - TURN TRUCK PUMP OFF
Actions Taken to Contain Release	FIREPUMP HOUSE TECHNICIAN AND DRIVER MOVED FUEL INLET CATCH PANS TO DRAIN SPOUTS - BUCKET USED TO RECOVER FUEL BACK INTO TRUCK TANK. PIGMAT USED ON ROOF AND CLAY ABSORBENT USED AT DRAIN SPOUT EXITS.
Actions Taken to Cleanup Release	EAGLE ENVIRONMENTAL SERVICES CONDUCTED CLEANUP. COLLECTED ALL PIGMAT AND REMOVED TOP LAYER OF ROOFING. REMOVED ~ 50 GALLONS OF DIESEL FROM OVERFILLED TANKS. REMOVED ~ 138 FT ³ OF SOIL ALL AFFECTED AREAS SPRAYED WITH MICRO BLAZE BEFORE AND AFTER CLEANUP

INCIDENT DESCRIPTION (CONT.)	
IMPACT/HEALTH THREATS	
NUMBER OF INJURIES	NONE
NUMBER OF DEATHS	NONE
EVACUATION(S) REQUIRED	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> NO
Description of Areas to be Evacuated and Areas Already Evacuated including Number Evacuated	N/A
Was There Any Property Damage	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Damage in Dollars (estimated)	~\$12,000 (Roof Repair)
Environmental Media Affected	Soil
DESCRIPTION OF ENVIRONMENTAL AND HEALTH THREATS INCLUDING AREAS THREATENED	~138 cu.ft of soil REMEDIATED
PRECAUTIONS TO MINIMIZE HEALTH THREATS TO LOCAL RESIDENTS INCLUDING MEDICAL ADVICE	N/A
Additional Information Any information about the incident not recorded elsewhere in the report	
AGENCY NOTIFICATIONS	
NRC 1-800-424-8802	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO NRC Call No. 862151 TIME: 8:47 AM 2/12/08
EPA	<input type="checkbox"/> YES <input type="checkbox"/> NO TIME:
INRCC-TCEQ	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO TIME: 8:55 AM 2/12/08
City of Fort Worth DEM	<input type="checkbox"/> <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO TIME: 9:21 AM 2/12/08
Other (List) State of Texas ERC	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO TIME: 8:55 AM 2/12/08
Other (List) Tarrant County LEPC	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO TIME: 9:05 AM 2/12/08
Other (List)	<input type="checkbox"/> YES <input type="checkbox"/> NO TIME:

Reportable Diesel Fuel Spill
February 11, 2008

Incident Report

At about 10:05 AM during unloading of diesel fuel # 2 to the fire pump house inside tanks, approximately thirty (30) gallons were spilled on the roof and into the tank containment systems via the tank vents. Duration of the event was about five minutes. Fuel ran down the roof drains to the ground below. About 10 gallons (of the thirty gallons) spilled to ground. Immediate action by the driver and fire pump house operator included moving the fuel inlet catch pans under the two drain spouts and using a bucket to recover fuel from the catch pans back into the truck tank. Once additional assistance (Buildings and Grounds personnel, M. Torres, R. Crabbe and M. Gomez) arrived at 10:12 AM, pig mat was spread on the roof to absorb the diesel and clay absorbent was piled on the ground around the building drain spouts. The Miller Emergency Response Team was not called out since the spill had been controlled and contained. The spill covered approximately 400 sq. ft. of roof area and about 138 sq. ft. of ground for both drain spouts.

Eagle Environmental Services was contacted at 10:47 AM and arrived at the brewery at 12:08 PM to conduct the spill clean up. They sprayed Microblaze on the affected roof area, collected the spent pig mat, removed top surface of roof and gravel, and drained the remaining fuel on the roof to the catch pans below. The inside of the drain spouts were sprayed with Microblaze and all materials were placed into plastic bags. The catch pans were also treated with Microblaze after the diesel fuel was collected from the pans. About 50 gals of diesel fuel was recovered from both of the overfilled tanks. Eagle also removed about 138 cubic feet of soil. The roof was given a second treatment of MicroBlaze and absorbent socks were placed at the roof drain openings. The dug out areas on the ground were also treated with MicroBlaze. All affected materials were collected into a plastic lined and covered dumpster. Eagle Environmental Services will provide the remediation of the soil and disposal of all materials.

There was not a threat to any body of water and the spill was contained on brewery property.

The incident was caused by operator error. Advanced Petroleum driver Tommy J. Jordan did not pay enough attention to the fuel tank site glasses and overfilled both diesel fuel tanks. Miller Brewing Co. utilities technician was inside the fire pump house instead of directly monitoring the unloading of diesel fuel. The technician was re-instructed on adhering to the procedure.

Weather Conditions: Partly cloudy, 50°F with 16 to 20 mph South wind

Regulatory Agencies Notification

Based on spill coverage (about 400 sq.ft. on the roof), the following agencies were notified in the order listed.

National Response Center 1-800-424-8802 Mr. Kevin Williams notified on 2/12/08 at approximately 8:47 AM. He assigned Incident # 862151.

State of Texas Emergency Response Center 1-800-832-8224 Ms. Cindy Moore notified on 2/12/08 at approximately 8:55 AM. She assigned Report # 20080506.

Tarrant County Local Emergency Planning Commission 817-884-1473 (phone not picking up) Contacted Mr. Keith Wells on his cell phone on 2/12/08 at approximately 9:05 AM I left a voice mail message with the information on the spill on Mr. Wells' office phone (817-392-6177) per his instructions.

TCEQ – DFW Region 4 Office 817-588-5800 Mr. Brent Chandler notified on 2/12/08 at approximately 9:14 AM and gave him the information on the spill.


City of Fort Worth Department of Environmental Management 817-871-5465 Mr. Clarence Reed notified on 2/12/08 at approximately 9:21 AM. I gave Mr. Reed the information on the spill.

Follow-up to Spill

The diesel fuel spill was discussed with supplier on 2/12/08 by Utilities Manager M. Torres. Below is the supplier information.

Advance Petroleum
2451 Great SW Parkway
Fort Worth, Texas
Driver: Tommy J. Jordan

2-11-08
 Spill Site
 Fire Pump house



- NOTES
1. SEE SHEET 201-1 FOR GENERAL NOTES.
 2. SEE SHEET 201-2 FOR GENERAL NOTES.
 3. SEE SHEET 201-3 FOR GENERAL NOTES.
 4. SEE SHEET 201-4 FOR GENERAL NOTES.
 5. SEE SHEET 201-5 FOR GENERAL NOTES.
 6. SEE SHEET 201-6 FOR GENERAL NOTES.
 7. SEE SHEET 201-7 FOR GENERAL NOTES.
 8. SEE SHEET 201-8 FOR GENERAL NOTES.
 9. SEE SHEET 201-9 FOR GENERAL NOTES.
 10. SEE SHEET 201-10 FOR GENERAL NOTES.
 11. SEE SHEET 201-11 FOR GENERAL NOTES.
 12. SEE SHEET 201-12 FOR GENERAL NOTES.
 13. SEE SHEET 201-13 FOR GENERAL NOTES.
 14. SEE SHEET 201-14 FOR GENERAL NOTES.
 15. SEE SHEET 201-15 FOR GENERAL NOTES.
 16. SEE SHEET 201-16 FOR GENERAL NOTES.
 17. SEE SHEET 201-17 FOR GENERAL NOTES.
 18. SEE SHEET 201-18 FOR GENERAL NOTES.
 19. SEE SHEET 201-19 FOR GENERAL NOTES.
 20. SEE SHEET 201-20 FOR GENERAL NOTES.