



CERTIFIED MAIL RETURN RECEIPT REQUESTED 7004 1350 0004 5969 0825

January 23, 2007

Texas Commission on Environmental Quality
DFW Regional Office
2309 Gravel Drive
Fort Worth, TX 76118

07 JAN 30 AM 6:03
RECEIVED
OPPT/CBIC

Attention: Mr. Tony Walker, Regional Director

Subject: Follow-up on Ammonia Release Reported December 22, 2006

Company: Miller Breweries West LP
7001 South Freeway
Fort Worth, TX 76134



Account #: TA-0235-N

Pursuant to 30 TAC § 327.3(e), the following release update notification is provided. Also please note that the Miller Fort Worth facility was not in routine operation between December 22, 2006 and January 1, 2007.

Facility Emergency Contacts:

Stan Curry 817-551-3398 (Voice)
817-822-4695 (Cell)

John Williams 817-551-3402 (Voice)
817-822-6488 (Cell)

Don Nikirk 817-551-3372 (Voice)
817-521-5064 (Cell)



CONTAINS NO CBI

Contains No CBI

Agencies Notified:

EPA National Response Center: 12/22/2006 @ 9:29 am CST, Case Number 821812,
Petty Office Thompson

State of Texas Emergency Response Center: 12/22/2006 @ 9:33 am CST, Case Number
20064283, Operator Beth

Tarrant County LEPC: 12/22/2006 @ 9:39 am CST, Operator Summer

Incident Summary:

On Thursday December 21, 2006 at approximately 8:50 am, an estimated quantity of approximately 480 lbs. to 1,076 lbs. of ammonia was released during servicing of refrigeration equipment in the basement. Please note that this amount differs from the original quantity reported on December 22, 2006. Due to the misalignment of an operating hand valve during equipment isolation a hydrostatic relief valve lifted to relieve system pressure. When incident investigation bench testing all the PSV's that were thought to be possibly related to incident one was found to be lifting at less than the set point of 150 psig which caused the release. Conditions at the time of release were recorded as follows:

Temperature: 40 °F
Relative Humidity: 66%
Wind Speed: 9 mph
Wind Direction: NW
Skies: Clear

Remedial Actions:

1. To immediately stop the release, the operator re-opened the valve that was mistakenly closed.
2. New relief valves were installed during the incident investigation.
3. The operating procedure for this equipment will be revised to include information and caution statements to prevent over-pressuring the vessel while servicing. All operators will have refresher training on the revised procedure.

Thank you for your consideration in this matter. If you have any questions concerning this correspondence or if I can be of further assistance, please feel free to contact me. I can be reached during normal business hours Monday through Friday at 817-551-3398 (voice), 817-551-3313 (FAX), 817-822-4695 (Cell) or be e-mail at curry.stan@mbco.com.

Sincerely,



Stan K. Curry
Environmental and Regulatory Compliance Coordinator

cc: National Emergency Response Center
Office of Toxic Substances
Document Processing Center
Environmental Protection Agency
401 M Street, S.W
Washington, DC 20460
ATTN: Section 8(e) Coordinator
Certified Mail RRR # 7004 1350 0004 5969 0832

City of Fort Worth Environmental Management
1000 Throckmorton Street
Fort Worth, TX 76102
ATTN: Mr. Greg Dawson
Certified Mail RRR # 7004 1350 0004 5969 0849