

Appendix G
Site Inspection Photos



Figure 1: Applied Materials Building 1
Facing Northeast



Figure 2: Adjacent Church Property
Facing East



Figure 3: Former Groundwater Extraction System
Facing Southeast



Figure 4: Former Location of Extraction System
Facing North



Figure 5: Former Extraction Trench
Facing South



Figure 6: Monitoring Well AM1-3 w/ Damaged
Lid



Figure 7: Monitoring Well AM1-3



Figure 8: Monitoring Well AM1-11



Figure 9: Monitoring Well AM1-7



Figure 10: Monitoring Well AM1-6



Figure 11: Former Extraction Well and Current
Monitoring Well AM1-5E