



Attachment E


Site Photographs




1. Project Sign leaning Against Northwest Side of Building




2. View of OU2 Treatment Facility in Foreground with the South Wall of the OU2 Treatment Facility in the Background. Also in Background is the RFI Facility




3. View of Individual Pipelines from the OUI SVE Wells




4. Damaged Piping at OUI Condensate Holding Tank




5. Treatment Facilities as well as Recycled Fibers Inc, in Background




6. Cars Parking on Vault Covers
Crown on Landfill Evident, Ice Rink in Background




7. Damaged Curbing Surrounding SVE Vault Well No. 4
OU2 Treatment Building and Site Fencing in Background




8. OU2 Treatment Building




9. Influent Equalization Tank, Motor Control Center in Background along with UV/OX Control Panel (PeroPure)




10. GAC Units in the OU2 Groundwater Treatment Plant



11. UV/Oxidation System (no Longer use in the OU2 Treatment Train)



12. Caustic and Acid Storage for UV/Oxidation System



13. Extraction Well Pneumatic Controls and Sump in Background