1Q 2008 QUARTERLY GW SAMPLING CS

COREY STRAUSS

"Rite in the Rain"®

ALL-WEATHER

JOURNAL

No. 391

3/12/08

0645 ARRIVE ON SITE UP AT LAB. WARMING UP YSI METERS.
0730 BEGIN CALIBRATION.
0900 HEALTH AND SAFETY MEETING.
1000 LEAVING LAB AREA. HEADING TO B/W-27D.
1030 BEGIN PUMPING OUT WATER IN PUMP & LINE
1040 BEGIN TAKING PARAMETERS
1130 45 COLLECT SAMPLE B/W-27D
1200 MOB OVER TO B/W-25
1220 SET UP EQUIP. STATIC 19.09' BGS
1245 BEGIN PUMPING
1330 SAMPLE COLLECTED AT B/W-25I
1350 MOB OVER TO B/W-9I
1405 BEGIN PUMPING
1400 SAMPLE COLLECTED B/W-9I
1500 MOB TO B/W-9D. STATIC 20.78' BGS
1515 START PUMPING
1620 COLLECT SAMPLES B/W-9D AND B/W-9D MS/MSD
1640 MOB OVER TO B/W-10
1700 ARRIVE AT B/W-10 STATIC 21.36' BGS
1800 SAMPLE COLLECTED AT B/W-10D.
1830 BACK TO LAB TO DO DRIFT CHECK
1900 OFF SITE

Corey J. Strauss

3/13/08

0630 ARRIVE AT LAB AREA
0700 BEGIN CALIBRATING YSI
0830 H+S MEETING
0900 HEAD TO MW-2002-2I STATIC.
1020 SAMPLE COLLECTED AT MW-2002-2I
1100 HEAD TO B/W-11D1. STATIC 38.53'
1220 COLLECT SAMPLE B/W-11D1 ~~GAS~~
COLLECT SAMPLE BW-5I
COLLECT SAMPLE B/W-3I
1730 DRIFT CHECK
1830 OFF SITE

3/14/08

0600 ARRIVE ON MINESITE.
0630 BEGIN YSI CALIBRATIONS.
0700 LOADING UP SUPPLIES IN TRUCK
0715 HEALTH + SAFETY MTG
0730 MOBING TO B/W-29 CLUSTER
0740 ARRIVE AT B/W-29 BEGIN SETTING UP
0910 COLLECT SAMPLES B/W-29I1-D1 + B/W-29I1-D2
1025 COLLECT SAMPLES B/W-29S
1125 COLLECT SAMPLES B/W-29I-2
1200 BACK UP TO LAB AREA ~~BE~~ TO DO A DRIFT CHECK ON YSI
1320 TRASH RUN TO DUMPSTER
1600 OFF SITE.

Cory J. Stearns

3/17/08

0600 ARRIVE AT LAB. BEGIN CALIBRATING YSI
0795 HEALTH + SAFETY MTG.
0730 OFF TO B/W-4 CLUSTER.
0800 BEGIN PUMPING ON B/W-4S.
0810. STOPPED PUMPING. NEED TO FIX GENERATOR.
0850 START PUMPING AGAIN.
0950 COLLECT SAMPLE B/W-4S
1110 COLLECT SAMPLE B/W-4D
1240 COLLECT SAMPLE B/W-4I
1250 HEAD UP TO LAB TO DROP SAMPLES OFF
1300 HEAD OVER TO B/W-6 TO GIVE MATT FUEL
1330 ARRIVE AT B/W-28 CLUSTER
1335 BEGIN PUMPING AT B/W-28I
1450 COLLECT SAMPLE B/W-28I
1600 COLLECT SAMPLE B/W-28D
1725 COLLECT SAMPLE B/W-28S
1740 BACK TO LAB TO DRIFT CHECK ON YSI.
1830 OFF SITE.

Cory J. Stearns

3/18/08

0600 ON SITE. START CALIBRATIONS
0730. MOBING TO B/W-23.
0740. DO NOT HAVE CORRECT FITTING. CALL TOM JUDY (QED). MOB OVER TO B/W-1 CLUSTER IN THE MEANTIME.
0800 ARRIVE AT B/W-1.
0950 COLLECT B/W-1S + MS/MSD
~~1100~~ 1120 COLLECT B/W-1I
1140 NEED TO RUN UP TO LAB TO GET PART FOR B/W-1D CAP & DROP SAMPLES OFF.
1230 BACK ON SAMPLE LOCATION
1350 COLLECT SAMPLE B/W-1D (GAS)
1410 BACK TO SITE TO GET ANOTHER GAS CYLINDER
~~1545~~ CO
1530 ARRIVE AT B/W-16D
1545 COLLECT SAMPLE B/W-16D (GAS)
1615 GO TO B/W-2
1640 UP TO LAB
1700 DRIFT CHECK
1800 OFF SITE.

3/19/08

0600 ARRIVE ON SITE. BEGIN CALIBRATIONS
0730 HEALTH AND SAFETY MTG
0745 HEAD UP TO B/W-23D.
0905 COLLECT SAMPLE B/W-23D (GAS)
0920 BACK ON MINE SITE TO GET ICE AND EXCHANGE GAS TANKS.
0940 MOB OVER TO B/W-29D
1000 ARRIVE AT B/W-29D
1120 COLLECT B/W-29D (GAS)
1145 HEAD UP TO LAB.
1215 HEAD TO PA-MW-2
1345 COLLECT SAMPLE PA-MW-2 (GAS)
1400 MOB OVER TO PA-MW-3
1515 COLLECT SAMPLE PA-MW-3 (GAS)
1545 MOB TO PA-MW-1
1715 COLLECT SAMPLE PA-MW-1 (GAS)
1730 DROP GAS CYLINDERS OFF
1740 UP TO LAB DRIFT CHECK METERS
1830 OFF SITE

3/20/08

0600 ARRIVE ON SITE
0730 H&S MTG
0800 ARRIVE AT MW-2
1000 COLLECT SAMPLE MW-2 (GAS)
1150 COLLECT SAMPLE UW-1 (GAS)
1355 COLLECT SAMPLE WW-1D+ WW-1D-2
1570 COLLECT SAMPLE MCB-2 (GAS)
1530 DRIFT CHECK