Modified from Woodward-Clyde, 1988



See Figure 4.1-1 for location of Cross-Section and description of lithologic units

Source:
Modified from Woodring, W.P., and Bramlette, M.N., 1950, Geology and Paleontology of the Santa Maria District, California: U.S. Geological Survey Prof. Paper 222.

Note: All faults are schematic and are not to scale.

Explanation

Qal – Alluvium	Tcg – Graciosa Member	Tsts – Todos Santos Claystone Member	Tps – Point Sal Formation
Qt – Terrace Deposits	Tcc – Cebada Member	Tmu – Monterey Shale Upper Member	Tl – Undifferentiated Lospe Formation
Qo – Orcutt Sand	Tf – Foxen Mudstone	Tmm – Monterey Shale Middle Member	
Tpr – Paso Robles Formation	Ts – Sisquoc Formation	Tml – Monterey Shale Lower Member	

2000 0 2000 4000

Figure 4-11

Regional Geologic Cross-Section

Final Remedial Investigation Report
Casmalia Resources Superfund Site

January 2011

T:\CASMALIA\GIS\deliverables\RI_Final_11\Section4\Fig4-11_RegionalGeologicXSect.mxd