

r
Se.
To:
Subject:

Toffel, Melissa
Friday, December 15, 2017 10:36 AM
'luckymart200@gmail.com'
Required list of documentation

Hi Lakhmir – here is what we are requesting that you send in by the end of this month:

1. The most recent testing of the Line Leak Detectors and Line Tightness Testing for each of the tanks;
2. The most recent test of the cathodic protection system;
3. Tank release detection results, which is the test currently performed by the Veeder-Root, for the months of November and December 2017 **for each tank**;
4. Verification of Overfill being installed on each tank. You may already have ballfloats installed, but need a contractor to verify that they are still intact and functioning. If you need to have overfill installed, we need to see that it gets installed immediately; and,
5. A probe needs to be installed on Tank #5, or, another valid method of release detection needs to be utilized on Tank #5 (for example - SIR) and we need documentation to show release detection being performed on this tank.

Please give me a call at the number below with any questions. Thank you,

Melissa Toffel
U.S. EPA Region III
Land & Chemicals Division
RCRA Underground Storage Tank Branch
1650 Arch Street (Mail Code 3LC31)
Philadelphia, PA 19103
P: 215-814-2060
F: 215-814-3163

