

U.S. ENVIRONMENTAL PROTECTION AGENCY

Risk Management Program Inspection Findings and Alleged Violations Summary Region 10

REASON FOR INSPECTION: This inspection is for the purpose of determining compliance with Section 112(r)(7) accidental release prevention requirements of the Clean Air Act, as amended 1990. The scope of this inspection may include, but is not limited to: reviewing and obtaining copies of documents and records; interviews and taking of statements; reviewing of chemical storage, handling, processing, and use; taking samples and photographs; and any other inspection activities necessary to determine compliance with the Act

and any other inspection activities necessary to determine compliance with the Act.				
FACILITY NAME: Bellingham Cold Storage Co Orchard Facility	☑ PRIVATE # EMPLOYEES: 55	☐ GOVERNMENTAL		
FACILITY LOCATION: 600 Orchard Dr., Bellingham, WA 98225	INSPECTION START DATE: N/A	INSPECTION START	TIME:	
MAILING ADDRESS: P.O. Box 895, Bellingham, WA 98227	INSPECTION END DATE: N/A	INSPECTION END TO	IME:	
RESPONSIBLE OFFICIAL, TITLE, PHONE NUMBER: Douglas Thomas, President 360-733-1640	EPA FACILITY ID# 100000141973			
FACILITY REPRESENTATIVE(S), TITLE(S), PHONE NUMBER(S):		INSPECTOR NAME(S), TITLE(S), PHONE NUMBER(S) Javier Morales, RMP Coordinator, 206-553-1255		
	INSPECTOR SIGNATURE	DATE		
INSPECTION FINDINGS				
IS FACILITY SUBJECT TO RMP REGULATION (40 CFR 68)?		⊠ YES	□ №	
DID FACILITY SUBMIT AN RMP AS PROVIDED IN 68.150 TO 68.185?		⊠ YES	□NO	
DATE RMP FILED WITH EPA: 6/24/1999	PA: 6/24/1999 DATE OF LATEST RMP UPDATE: 12/14/2018			
1) PROCESS/NAICS CODE: 49312	PROGRAM LEVEL:	1 2	⊠ 3	
REGULATED SUBSTANCE: Anhydrous Ammonia	MAX. QUANTITY IN	N PROCESS (lbs.): 30,3	378	
DESCRIPTION OF ALLEGED VIOLATIONS				
CAA Section 112(r) and its implementing regulations in 40 C.F.R. Part 68 require an owner or operator of a stationary source that has more than a threshold quantity of a regulated substance (listed in § 68.130) in a process, to develop a Risk Management Plan (RMP) and Risk Management Program.				
The owner or operator must review and update the RMP as specified in 40 C.F.R. § 68.190(b) as required by § 68.190(a). Bellingham Cold Storage Company failed to submit an updated RMP to EPA at least once every five years as required by § 68.190(a) and (b)(1). The first submission of the RMP that EPA has on file is dated 6/24/1999. The latest RMP submission that EPA has on file is dated 12/14/2018. The five-year update was due 12/14/2023.				
DID FACILITY CORRECTLY ASSIGN PROGRAM LEVELS TO PROCESSES?		⊠ YES □ NO		
☐ PROGRAM LEVEL 1 ☐ PROGR	AM LEVEL 2 🔀 PROGRAM LEVEL 3			