

ATTACHMENT 3

Captured Images from Video IMG_1299 and IMG_1300 taken on May 9, 2022, Kiryas Joel Poultry Wastewater Pretreatment Plant equalization tank overflow and entry into storm inlets/catch basins that flow into a Tributary of the Ramapo River.

1. From IMG_1299 Untreated wastewater from equalization ("EQ") tank overflowing from top of EQ tank and person hosing down area.



2. From IMG_1300 Untreated process wastewater from EQ tank overflowing.



3. From Video IMG_1300 – May 9, 2022, Untreated process wastewater from EQ tank overflowing flowing towards storm drain/catch basin.



4. From Video IMG_1300 – May 9, 2022, Untreated process wastewater from EQ tank overflowing flowing towards storm drain/catch basin.



5. From Video IMG_1300 – May 9, 2022, Untreated process wastewater from EQ tank overflowing and wastewater flowing into and being hosed into catch basin



Wastewater entering Storm Inlet/Catch Basin that flows to a tributary of Ramapo River.

6. From Video IMG_1300 – May 9, 2022, Untreated process wastewater from EQ tank overflowing and flowing into storm drain/catch basin



Wastewater entering Storm Inlet/Catch Basin that flows to a tributary of Ramapo River.

7. From Video IMG_1300 – May 9, 2022, Untreated process wastewater from EQ tank overflowing and flowing into storm drain/catch basin



Wastewater entering Storm Inlet/Catch Basin that flows to a tributary of Ramapo River.