


UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 10

1200 Sixth Avenue, Suite 900 Seattle, Washington 98101-3140



EXPEDITED SETTLEMENT AGREEMENT

DOCKET NO:

CAA-10-2017-0075

This ESA is issued to:

Wilbur-Ellis Company

599 C Street

Walla Walla, Washington 99362

This Expedited Settlement Agreement (ESA) is being entered into by the Complainant, U.S. Environmental Protection Agency Region 10 (EPA), and by Respondent pursuant to Section 113(a)(3) and (d) of the Clean Air Act, 42 U.S.C. § 7413(a)(3) and (d), and by 40 C.F.R. § 22.13(b). On December 9, 2016, EPA obtained the concurrence of the U.S. Department of Justice, pursuant to Section 113(d)(1) of the Act, 42 U.S.C. § 7413(d)(1), to pursue this administrative enforcement action.

ALLEGED VIOLATIONS

EPA found that Respondent had violated regulations implementing Section 112(r) of the Act at 40 C.F.R. Part 68 by failing to comply with the regulations as noted on the enclosed Risk Management Plan Inspection Findings and Alleged Violations Summary, which is hereby incorporated by reference.

SETTLEMENT

In consideration of Respondent's size of business, its full compliance history, its good-faith effort to comply, and other factors as justice may require, and upon consideration of the entire record, the parties enter into the ESA in order to settle the violations described in the enclosed Summary for the total penalty amount of \$15,000.

This settlement is subject to the following terms and conditions:

Respondent, by signing below, waives any objections that it may have regarding jurisdiction, neither admits nor denies the specific factual allegations contained herein and in the Summary, and consents to the assessment of the penalty as stated above.

Respondent waives its rights to a hearing afforded by Section 113(d)(2)(A) of the Act, 42 U.S.C. § 7413(d)(2)(A), and to appeal this ESA. Each party to this action shall bear its own costs and fees, if any.

Respondent also certifies, subject to civil and criminal penalties for making a false submission to the United States Government, that Respondent has corrected the violations listed in the enclosed Summaries and has sent a cashier's check or certified check (payable to the "Treasurer, United States of America") in the amount of \$15,000 in payment of the full penalty amount to the following address:

U.S. Environmental Protection Agency Fines and Penalties Cincinnati Finance Center P.O. Box 979077 St. Louis, Missouri 63197-9000

The docket number of the ESA <u>must be included on the check</u>. (The docket number is located at the <u>top</u> <u>of this ESA</u>.)

This original ESA and a copy of the check must be sent by certified mail to:

Javier Morales, EPA, Region 10, RMP Coordinator Office of Compliance and Enforcement U.S. Environmental Protection Agency 1200 Sixth Avenue, Suite 900, Mail Stop: OCE-101 Seattle, Washington 98101

Upon Respondent's submission of the signed original ESA, EPA will take no further civil action against Respondent for the alleged violations of the Act referenced in the Summary. EPA does not waive its right to any other enforcement action for any other violations of the Clean Air Act or any other statute.

If the signed original ESA with an attached copy of the check is not returned to the EPA at the above address by Respondent within 45 days of the date of Respondent's receipt of it (90 days if an extension is granted), the proposed ESA is withdrawn, without prejudice to EPA's ability to file an enforcement action for the violations identified herein and in the Summary.

This ESA is binding on the parties signing below.

EOD DECDOMINENT.

This ESA is effective upon filing with the Regional Hearing Clerk.

TOR REST ON DELIG.	. 11
Signature:	Date: 4/4/2017
Name (print): LEORA GOBLE	
Title (print): FIKS CENTRAL SERVICES LEAD, WILBUR	-ELLIS COMPANY, LLC
Title (print): FIKS CENTRAL SERVICES LEAD, WILBUR Cost to correct violation(s) 5,000	
FOR COMPLAINANT: Janes Pr	Date: 4-7-2017
Edward J. Kowalski	
Director	
Office of Compliance and Enforcement	
I hereby ratify the ESA and incorporate it herein by reference	e. It is so ORDERED. 4 10 17
M. Socorro Rodriguez	A THE PURCE SEE
Regional Judicial Officer	

CAA-10-2017-0075 Wilbur-Ellis Co.



U.S. ENVIRONMENTAL PROTECTION AGENCY

Risk Management Program Inspection Findings and Alleged Violations Summary Region 10

REASON FOR INSPECTION: This inspection is for the purpose of determining compliance with Section 112(r)(7) accidental release prevention requirements of the Clean Air Act, as amended 1990. The scope of this inspection may include, but is not limited to: reviewing and obtaining copies of documents and records; interviews and taking of statements; reviewing of chemical storage, handling, processing, and use; taking samples and photographs; and any other inspection activities necessary to determine compliance with the Act

and any other inspection activities necessary to determine compliance with the Act.			
FACILITY NAME Wilbur Ellis Walla Walla	PRIVATE GOVERNMENTAL/MUNICIPAL # EMPLOYEES 18 POPULATION SERVED:		
FACILITY LOCATION 599 C Street, Walla Walla, WA 99362	INSPECTION START DATE AND TIME: August 5, 2016, 8:30 am		
MAILING ADDRESS 599 C Street, Walla Walla, WA 99362	INSPECTION END DATE AND TIME: August 5, 2016, 12:15 pm		
RESPONSIBLE OFFICIAL, TITLE, PHONE NUMBER Richard Meeks, Branch Manager, (509) 730-3105	EPA FACILITY ID# 1000 0009 6004		
James Nacke, EHSS Wilbur Ellis Representative (509) 730-3105	INSPECTOR NAME(S), TITLE(S), PHONE NUMBER(S) Terry Garcia, US EPA SEE Grantee RMP Inspector, 206-553-1761 Bob Hales, US EPA SEE Grantee RMP Inspector, 206-553-4090 Peter Phillips, US EPA SEE Grantee RMP Inspector, 206-553-1757 Javier Morales, US EPA RMP Coordinator, 206-553-1255 INSPECTOR SIGNATURE		
	1/28/17		
INSPECTION FINDINGS			
IS FACILITY SUBJECT TO RMP REGULATION (40 CFR 68)?	⊠ YES □ NO		
DID FACILITY SUBMIT AN RMP AS PROVIDED IN 68.150 TO 68.185? DATE RMP FILED WITH EPA: 6/21/1999			
PROCESS/NAICS CODE: 1000056225/ 42491 REGULATED SUBSTANCE: Anhydrous Ammonia	PROGRAM LEVEL: 1☐ 2 ☑ 3 ☐ MAX. QUANTITY IN PROCESS 168,000 (lbs)		
PROCESS/NAICS CODE: 1000063238/42491 REGULATED SUBSTANCE: Ammonia (conc. 20% or greater)	PROGRAM LEVEL: 1 2 2 3 1 MAX. QUANTITY IN PROCESS: 146,000 (lbs)		

DESCRIPTION OF ALLEGED VIOLATIONS

CAA Section 112(r) and its implementing regulations in 40 C.F.R. § Part 68 require an owner or operator of a stationary source that has more than a threshold quantity of a regulated substance (listed in § 68.130) in a process, to develop a Risk Management Plan (RMP) and Risk Management Program.

Four EPA representatives and an EPA contractor inspected the Wilbur-Ellis Company facility on August 5, 2016. Based upon this inspection the Wilbur-Ellis Company facility is in violation of the following risk management program elements listed below. Specifically, at the time of inspection, the Wilbur-Ellis Company facility:

- 1. <u>Safety Information</u>: Wilbur-Ellis failed to ensure that the anhydrous ammonia storage process is designed in compliance with recognized and generally accepted good and engineering practices as required by 40 C.F.R. § 68.48 (b). The pressure relief system for each anhydrous ammonia storage vessel has two dual pressure relief valves (PRV) with a two-way manifold and one PRV with two-way manifold and a capped port. The pressure relief system design does not provide adequate relief capacity when isolating a single PRV for replacement. Reference CGA-2.1-2014, 6th Ed., Requirements for the Storage and Handling of Anhydrous Ammonia, Section 5.8, Pressure relief devices.
- 2. Operating Procedures: Wilbur-Ellis' written operating procedures failed to provide clear instructions or steps for safely conducting activities associated with each covered process consistent with the safety information for the process as required by 40 C.F.R. § 68.52(a). Wilbur-Ellis Company Procedures Aqueous Ammonia Production, Issue Date April 10, 2014, pg. H-5, does not address the emergency shutdown button (E-Stop) for the ammonia converter pump located at the main office in the Emergency Shutdown Procedures for the operator. Wilbur-Ellis Company Procedure Anhydrous Ammonia Delivery and Loading, Issue Date April 10, 2014, pg. H-1 to H-3, does not address an emergency shutoff button (E-Stop) for the ammonia load-out pump is located between the pressure vessels.
- 3. Operating Procedures: Wilbur-Ellis failed to include consequences of deviations and steps required to correct or avoid deviations as required by 40 C.F.R. § 68.52(b). Wilbur-Ellis Company Procedure Anhydrous Ammonia Delivery and Loading, Procedure Aqueous Ammonia Production, and Procedure Aqueous Ammonia Delivery and Loading, Issue Date April 10, 2014, pgs. H-1 to H-8, does not include consequences of deviations and steps required to correct or avoid deviations for the operator.
- 4. Operating Procedures: Wilbur-Ellis failed to provide equipment inspections as required by 40 C.F.R. § 68.52(c). Wilbur-Ellis was unable to provide documentation on equipment inspections of the two stage cooling tower aqua ammonia converter system.

(Cont'd	n Page	2)
---------	--------	----

Certificate of Service

The undersigned certifies that the original of the attached EXPEDITED SETTLEMENT AGREEMENT AND FINAL ORDER, In the Matter of: Wilbur-Ellis Company, LLC, Docket No.: CAA-10-2017-0075, was filed with the Regional Hearing Clerk and served on the addressees in the following manner on the date specified below:

The undersigned certifies that a true and correct copy of the document was delivered to:

Javier Morales, RMP Coordinator 1200 Sixth Avenue, OCE-101 Suite 900 Seattle, Washington 98101

Further, the undersigned certifies that a true and correct copy of the aforementioned document was placed in the United States mail certified/return receipt to:

Leora Goble EHSS Central Services Lead Wilbur-Ellis Company, LLC 16300 Christensen Road, Suite 135 Tukwila, Washington 98188

DATED this // day of April, 2017 Time Jung

Regional Hearing Clerk

EPA Region 10