

**CLEAN AIR ACT STATIONARY SOURCE INSPECTION FINDINGS, ALLEGED VIOLATIONS, AND PROPOSED PENALTY FORM**

<b>Table 1 - Inspection Information</b>	
<b>Inspection/ Report Review Date(s):</b> July 17-20, 2023	<b>Docket Number:</b> C A A - 1 0 - 2 5 - 0 0 0 5
<b>Respondent Address:</b> 3585 SW 198th Avenue and 2501 NE Century Boulevard	<b>Facility Name(s):</b> Intel Aloha Campus and Intel Ronler Campus
<b>City:</b> Aloha and Hillsboro	<b>Inspector(s) Name(s):</b> Cynthia Schafer
<b>State:</b> OR <b>Zip Code:</b> 97007 and 97124	<b>EPA Delegated Official:</b> Edward Kowalksi
<b>Respondent Name:</b> Intel Corporation	<b>EPA Attorney Contact(s):</b> Shirin Gallagher, 206-553-4194

<b>Table 2 - Violations</b>
<p><b><u>Background</u></b> On July 17 through 20, 2023, authorized Environmental Protection Agency inspectors obtained evidence that Intel Corporation (Respondent) violated the Clean Air Act National Emission Standards for Hazardous Air Pollutants for Stationary Reciprocating Internal Combustion Engines (RICE) at 40 C.F.R. Part 63 Subpart ZZZZ. Pursuant to 40 C.F.R. § 63.6640 and Table 2d to Subpart ZZZZ, the owner or operator of emergency stationary RICE must change the oil and filter and inspect and replace as necessary all hoses and belts every 500 hours of operation or annually, whichever comes first; and must inspect and replace as necessary the air cleaner every 1,000 hours of operation or annually, whichever comes first. Pursuant to 40 C.F.R. § 63.6625(i), an owner or operator complying with those work practice requirements must, among other things, keep records of the parameters that are analyzed as part of the program, the results of the analysis, and the oil changes for the engine.</p> <p><b><u>Violation</u></b> EPA has determined that Respondent failed to maintain records for the RICE engines listed below between 2021 and 2022, located at Intel’s Aloha and Ronler Campuses, in violation of 40 C.F.R. § 63.6625(i).</p> <ul style="list-style-type: none"> <li>• RA1-ELEC-CPS-GEN01</li> <li>• RA1-ELEC-CPS-GEN02</li> <li>• RA1-ELEC-CPS-GEN03</li> <li>• RA1-ELEC-CPS-GEN04</li> <li>• D1C-CPS-GEN01</li> <li>• D1C-CPS-GEN02</li> </ul>

- D1C-CPS-GEN03
- RB1-EPS-GEN01
- RP1-EPS-GEN01
- EPS-GEN04
- RS4-ELEC-EG-4-1
- RS6-ELEC-EG-6-1
- F15-EG01
- PH #3
- MAX-EGEN

<b>Violation Description</b>	<b>Regulatory Citation or Permit Condition</b>	<b>Time Period</b>	<b>Document [or Report]</b>
Failure to Maintain Records	40 CFR 63.6625(i)	2021 - 2022	NEICVP1520E01

**Table 3 - Penalty and Required Corrective Action**

Penalty	\$ 39,187.00
Required Corrective Action	In addition to paying the monetary penalty, Respondent must certify that Respondent is in compliance with 40 C.F.R. § 63.6625(i).