



TRI Explorer

[Recent Additions](#) | [Contact Us](#)
 You are here: [EPA Home](#) | [TRI](#) | [TRI Explorer\(ver 4.7\)](#) | [Reports](#)

Search: All EPA This Area

[Bookmark](#)

2007 State Fact Sheet

[See Note](#)


[Go To New Report](#)

Alaska

Data source: Release Year 2007 PDR data set frozen on September 22, 2008 and released to the public January 8, 2009

Reported Disposal or Other Releases and Other Waste Management Activities (in pounds)

	Total
On-site Disposal to Class I Underground Injection Wells, RCRA Subtitle C Landfills, and other Landfills	
Class I Wells	0
RCRA Subtitle C Landfills	0
Other Landfills	193,613
SubTotal	193,613
Other On-site Disposal or Other Releases	
Fugitive Air Emissions	449,305
Point Source Air Emissions	940,147
Surface Water Discharges	63,962
Class II-V Wells	21,278,305
Land Treatment	0
RCRA Subtitle C Surface Impoundment	0
Other Surface Impoundments	253,198,145
Other Land Disposal	308,323,841
SubTotal	584,253,705
Total On-site Disposal or Other Releases	584,447,318
Off-site Disposal to Class I Underground Injection Wells, RCRA Subtitle C Landfills, and other Landfills	
Underground Injection to Class I Wells	0
RCRA Subtitle C Landfills	22,260
Other Landfills	728
SubTotal	22,988
Other Off-site Disposal or Other Releases	
Storage Only	0
Solidification/Stabilization (metals only)	3
Wastewater Treatment (metals only)	0
Transfers to POTWs (metals only)	0
Underground Injection to Class II-V Wells	0
RCRA Subtitle C Surface Impoundment	0
Other Surface Impoundments	0
Land Treatment	228,304
Other Land Disposal	0
Other Off-site Management	3,465
Transfers to Waste Broker for Disposal	12,673
Unknown	2,002
SubTotal	246,447
Total Off-site Disposal or Other Releases	269,434
Total On- and Off-site Disposal or Other Releases	584,716,753
Transfers Off-site for Further Waste Management (in pounds)	417,249
Recycling	33,129
Energy Recovery	107,286
Treatment	4,865



The map colors counties according to the total on-site disposal or other releases reported by TRI facilities in the county.	State/TRI Data
	Population 683,478
	Square Miles 663,267
	Total Facilities 34
	Total Forms 203
	Form As 31

On- and Off-site Waste Management (in pounds)	Total
Recycled On-site	34,456,723
Recycled Off-site	33,129
Energy Recovery On-site	72,420
Energy Recovery Off-site	93,186
Treated On-site	2,088,655
Treated Off-site	3,304
Total On-site Disposal to Class I Underground Injection Wells, RCRA Subtitle C Landfills, and Other Landfills	192,893
Total other On-site Disposal or Other Releases	584,221,448
Total Off-site Disposal to Class I Underground Injection Wells, RCRA Subtitle C Landfills, and Other Landfills	23,473
Total other Off-site Disposal or Other Releases	242,016
Total Production-related Waste Managed	621,427,246
Non-production-Related Waste Managed	21,369

POTWs	274
Metals and Metal Compounds	0
Non-metal TRI Chemicals	274
Other Off-site Transfers	0
Other Transfers Off-site for Disposal or	
Other Releases	271,695

For More Information . . .

State Contact

[TRI State Contacts](#)

EPA Regional Contact

[TRI Regional Contacts](#)

Note:

On-site Disposal or Other Releases include Underground Injection to Class I Wells (Section 5.4.1), RCRA Subtitle C Landfills (5.5.1A), Other Landfills (5.5.1B), Fugitive or Non-point Air Emissions (5.1), Stack or Point Air Emissions (5.2), Surface Water Discharges (5.3), Class II-V Wells (5.4.2), Land Treatment/Application Farming (5.5.2), Surface Impoundments (5.5.3) and Other Land Disposal (5.5.4). Off-site Disposal or Other Releases include from Section 6.2 Underground Injection (M71), RCRA Subtitle C Landfills (M65), Other Landfills (M64, M72), Storage Only (M10), Solidification/Stabilization - Metals and Metal Compounds only (M41 or M40), Wastewater Treatment (excluding POTWs) - Metals and Metal Compounds only (M62 or M61), Surface Impoundments (M63), Land Treatment (M73), Other Land Disposal (M79), Other Off-site Management (M90), Transfers to Waste Broker - Disposal (M94, M91), and Unknown (M99) and, from Section 6.1 Transfers to POTWs (metals and metal compounds only).

Off-site disposal or other releases show only net off-site disposal or other releases, that is, off-site disposal or other releases transferred to other TRI facilities reporting such transfers as on-site disposal or other releases are not included to avoid double counting.

Transfers to Recycling are Section 6.2, sum of Solvents/Organics Recovery (M20), Metals Recovery (M24), Other Reuse or Recovery (M26), Acid Regeneration (M28) and Transfer to Waste Broker - Recycling (M93)). Transfers to Energy Recovery are Section 6.2, sum of Energy Recovery (M56) and Transfer to Waste Broker - Energy Recovery (M92)). Transfers to Treatment are Section 6.2, sum of Solidification/Stabilization (M40, except for metals and metal compounds), Incineration/Thermal Treatment (M50), Incineration/Insignificant Fuel Value (M54), Wastewater Treatment (excluding POTWs) (M61, except for metals and metal compounds), Other Waste Treatment (M69) and Transfer to Waste Broker - Waste Treatment (M95)). Transfers to POTWs (non-metals) are Section 6.1 (except metals and metal compounds). Transfers to POTWs (metals and metal compounds) are Section 6.1 (metals and metal compounds only). Other off-site transfers are Section 6.2 sum of amounts with no code or invalid code. Other transfers off-site to disposal or other releases do not include transfers to POTWS of metals and metal compounds and are Section 6.2, sum of Underground Injection (M71), RCRA Subtitle C Landfills (M65), Other Landfills (M64), Storage Only (M10), Solidification/Stabilization - Metals and Metal Compounds only (M41), Solidification/Stabilization (M40 metals and metal compounds only), Wastewater Treatment (excluding POTWs) - Metals and Metal Compounds only (M62), Wastewater Treatment (excluding POTWs) (M61 metals and metal compounds only), Surface Impoundments (M63), Land Treatment (M73), Other Land Disposal (M79), Other Off-site Management (M90), Transfers to Waste Broker - Disposal (M94 or M91), and Unknown (M99).

A choropleth map is a map which colors regions or areas according to the value of data defined for that area. The choropleth maps presented here color states, or counties, according to aggregations of TRI data reported by facilities in that area. Coloring an area with one color is not meant to imply that the TRI amounts are uniformly distributed throughout that area; instead it should be interpreted as a color representing, for example, the total amounts reported by facilities in that area. Choropleth maps are one of the most commonly used means of displaying areal data.

Population for states and Puerto Rico from <http://www.census.gov/popest/states/NST-ann-est.html>

[EXIT Disclaimer](#)

For Island areas from <http://www.census.gov/population/www/cen2000/islandareas.html> [EXIT Disclaimer](#)

Square miles from http://www.census.gov/population/censusdata/90den_stco.txt [EXIT Disclaimer](#)

Total Facilities is the number of facilities located within the jurisdiction that submitted at least one TRI Form for 2007. Total Forms is the number of TRI Forms submitted from facilities located within the jurisdiction for 2007. Form As is the number of TRI Form As submitted by facilities located within the jurisdiction for 2007.

On- and Off-site Waste Management from Section 8, Column B (Recycled On-site (8.4), Recycled Off-site (8.5), Energy Recovery (8.2), Energy Recovery (8.3), Treated On-site (8.6), Treated Off-site (8.7) and Quantity Disposed of or Otherwise Released On- and Off-site (8.1)). Non-production-related waste managed from Section 8.8.

TOP OF SCREEN 

[EPA Home](#) | [Privacy and Security Notice](#) | [Contact Us](#)

Last updated on Tuesday, December 9th, 2008.

http://palomino.rtpnc.epa.gov/cgi-bin/broker?view=STCO&trilib=TRIQ0&state=02&SFS=YES&year=2007&_service=oiaa&_program=xp_tri.sasmacr.tristart.macro

[Print As-Is](#)

This document will now print as it appears on screen when you use the File » Print command.

Use View » Refresh to return to original state.

This request took 4.40 seconds of real time (v9.1 build 1461).