



South Coast Air Quality Management District

21865 Copley Drive, Diamond Bar, CA 91765-4178
(909) 396-2000 • www.aqmd.gov

June 2nd, 2015

Mr. Robert Nguyen
Environmental Manager
Tesoro Refining & Marketing Company, LLC.
2101 East Pacific Coast Highway
Wilmington, CA 90744

Subject: Transmittal of Title V Permit Renewal

Facility ID	Facility Name	Address
800436	Tesoro Refining and Marketing Company, LLC, Los Angeles Refinery, Wilmington Operations	2101 East Pacific Coast Highway, Wilmington, CA 90744

Dear Mr. Nguyen:

Enclosed is the final Title V permit renewal issued by the South Coast Air Quality Management District (SCAQMD) for the facility listed above. Effective May 13, 2015, this Title V permit will supersede the current revision of the Title V Facility Permit issued to your facility by the SCAQMD.

The draft copy of this permit was submitted to the U.S. EPA Region IX (EPA) for a 45-day review period (March 19, 2015 to April 27, 2015) and made available for a public comment period (March 19, 2015 to May 12, 2015). The SCAQMD received no comments on the draft permit from the EPA or the public.

The SCAQMD has incorporated the following administrative changes to your Title V permit since the issuance of the most current revision of your RECLAIM facility permit:

Facility Permit Changes

- Rule 219-exempt equipment (Heat exchange systems) was added to the permit as E1730 in Process 21 and tagged with Conditions H23.43 to reflect the applicability of 40 CFR 63 Subpart CC.
- The rule tagging for permit conditions and devices have been updated to reflect the current applicable version of Rules (see Attachment for detailed list).
- The table of Facility Rules in Section K has been updated to reflect the changes in effective dates and federal enforceability of applicable rules (see Attachment for detailed list).
- Equipment subject to CAM (D96) was tagged with condition H23.44 to reflect applicability of 40CFR64, and Section I was updated to include the approved CAM plan.

Section B: Administrative Revision

Section B of your facility permit is updated as explained below:

On May 2, 2008, the South Coast Air Quality Management District (SCAQMD) issued your facility a Clean Fuels Plan (A/N 474582) pursuant to Rule 2002(c)(12). Under the approved Plan, the facility's annual allocations were increased by 19,843 pounds of NOx for Compliance Years 2000 and forward, which is equal to the calculated emission increases expected from the modifications required solely to comply with the state or federal reformulated gasoline requirements at this refinery.

As a result of the amendment to Rule 2002 in January 2005 to further reduce RECLAIM NOx Allocations, the NOx historical baseline Clean Fuel Adjustments for Compliance Year 2007 and subsequent years were reduced by the appropriate adjustment factors as stated in Rule 2002(f)(1)(A). For Compliance Year 2014, Tesoro's NOx RTCs issued pursuant to Rule 2002(c)(12) were reduced from 19,843 pounds to 15,378 pounds.

Based on the data you provided in your facility's Compliance Year 2014 APEP report, SCAQMD determined, using the equations in your approved Clean Fuels Plan, the total actual NOx emission increase eligible for Clean Fuel Adjustment to be 11,696 pounds. Pursuant to Rule 2002(c)(12) and the approved plan, your facility's Compliance Year 2014 NOx Allocation is hereby decreased by 3,682 pounds (11,696 lbs. - 15,378 lbs.).


In accordance to the conditions of your approved Plan, your Allocations for Compliance Year 2014, after these adjustments, will be used to determine compliance with Rule 2004(d) - Prohibition of Emissions in Excess of Annual Allocation.

Additionally, our review of your APEP report also found errors in the entries for "Allocation Adjustments Previously Issued" and "Adjustments to be Made" in Section VIII. The value for "Allocation Adjustments Previously Issued" should be 19,843 but was entered as 15,914 pounds. For "Adjustments to be Made", the value should be a decrease of 8,147 pounds but the entered value was an increase of 4,218 pounds. Please take note of these discrepancies and take appropriate steps to ensure that the APEP report is properly completed in the future.

Finally, the enclosed Revision #15 of your Facility Permit Section B is issued to reflect these Clean Fuels allocation adjustments prior to determining compliance with your Allocations.

Please review the attached permit carefully. Questions concerning changes to Section B should be directed to Mr. Bob Sanford at (909) 396-2660 or bsanford@aqmd.gov, while all other questions concerning the subject permit should be directed to Ms. Sawsan Andrawis at (909) 396-2607 or sandrawis@aqmd.gov.

Sincerely,


Danny Luong, R.E.
Senior Manager
RECLAIM Admin., Refinery Permitting,
Retail Gasoline Dispensing

Enclosure: Title V Permit Renewal

cc: Gerardo C. Rios, USEPA, Region IX
Edwin Pupka, Compliance, SCAQMD

ATTACHMENT: RULE DATES UPDATED IN THE FACILITY PERMIT

The following rules (revision date) were updated in Section K of the facility permit:

Updated: 219 (5-3-2013), 301 (6-6-2014), 304 (6-6-2014), 3003 (11-5-2010), 3005 (11-5-2010)

Removed: 219 (7-11-2003), 301 (5-2-2008), 304 (7-9-2004), 3003 (3-16-2001), 3005 (3-16-2001)

The rules that follow were updated in Section K of the facility permit as well as for specific devices (emission limits) and/or conditions as listed below:

Rule 461 updated to add 4-6-2012 (SIP approved) revision and to remove 6-3-2005 (SIP approved) revision for the following condition:

- S13.8

Rule 463 updated to add 11-4-2011 (SIP approved) revision and to remove 5-6-2005 (SIP approved) revision for the following conditions:

- S13.6, S13.7, S13.9, C6.2, C6.3, E440.1, E440.2, H23.25, H23.31, H23.33, K67.2, K67.8, K67.9, K67.11, K67.12, K67.15, K67.16

Rule 1110.2 updated to add 9-7-2012 (non-SIP approved) revision and 2-1-2008 (SIP approved) revision for the following device and conditions:

- D12.13, C1.45, C1.55, K67.13

Rule 1113 updated to add 6-3-2011 (SIP approved), 9-6-2013 (non-SIP approved) revision and remove 11-8-1996 (SIP approved) revision for the following device and condition:

- E1493, K67.4

Rule 1122 updated to add 5-1-2009 (non-SIP approved) revision for the following device and condition:

- E1492, H23.14

Rule 1146 updated to add 11-1-2013 (SIP approved) revision and to remove 11-17-2000 (SIP approved) revision for the following devices and condition:

- D92, D215, D216, D249, D250, D328.2

Rule 1149 updated to remove 7-14-1995 (SIP approved) revision for the following conditions:

- S13.6, S13.7, S13.9, H23.25, H23.33

Rule 1158 updated to add 7-11-2008 (SIP approved) revision to remove 6-11-1999 (SIP approved) revision for the following conditions:

- S7.1, S7.2, S13.3, A63.6

Rule 1168 updated to remove 10-3-2003 (SIP approved) revision and to add 1-7-2005 (SIP approved) for the following device:

- E1491

Rule 1171 updated to add 5-1-2009 (non-SIP approved) revision and to remove 11-7-2003 (SIP approved) revision for the following devices:

- E1491, E1492, E1493, E1499

Rule 1173 updated to add 2-6-2009 (SIP approved) revision and to remove 5-3-1994 (SIP approved) and 6-1-2007 (non-SIP approved) revisions for the following conditions:

- H23.5, H23.16, H23.39

Rule 1470 updated to add 5-4-2012 (non-SIP approved) revision and to remove 6-1-2007 (non-SIP approved) revision for the following conditions:

- C1.43, C1.45, C1.55, C1.56

Rule 2004 updated to remove 5-11-2001 (SIP approved) revision and to add 4-6-2007 (SIP approved) for the following condition:

- F25.1

Rule 2005 updated to add 6-3-2011 (SIP approved) revision and to remove 5-6-2005 (SIP approved) revision for the following devices:

- D32, D770, D777, D1122

40CFR60 Subpart A, 40CFR61 Subpart A, 40CFR63 Subpart A updated to add 4-4-2014 revision for the following condition:

- F52.3

40CFR60 Subpart Db updated to add 2-27-2014 revision and to remove 1-28-2009 revision for the following device and condition:

- D1122, H23.29

40CFR60 Subpart J updated to 9-12-2012 revision and to remove 6-24-2008 revision for the following device and conditions:

- D96, A63.7, B61.1, B61.4, B61.9, D82.2, D90.7, D90.8, D90.16, D90.17, H23.3, H23.18, H23.29, H23.32

40CFR60 Subpart Ja updated to 9-12-2012 revision and to remove 6-24-2008 revision for the following devices and conditions:
H23.42

40CFR63 Subpart CC updated to add 6-20-2013 revision and to remove 6-23-2003 revision for the following conditions:

- D90.4, D90.5

40CFR63 Subpart CC, #1 updated to add 6-20-2013 revision and to remove 6-23-2003 revision for the following devices:

- D227, D450, D949

40CFR63 Subpart CC, #2 updated to add 6-20-2013 revision and to remove 6-23-2003 revision for the following devices:

- D58, D86, D95, D167, D346, D498, D549, D582, D583, D568, D586, D587, D588, D603, D605, D609, D612, D629, D632, D635, D657, D1555, D688, D689, D693, D696, D697, D998, D700, D998, D1001, D1002, D1022, D1023

40CFR63 Subpart CC, #3A updated to add 6-20-2013 revision and to remove 6-23-2003 revision for the following devices:

- D593, D599, D613, D614, D617, D618, D621, D630, D647, D648, D649, D650, D651, D652, D653, D654, D655, D656, D658, D659, D660, D1078

40CFR63 Subpart CC, #4 updated to add 6-20-2013 revision and to remove 6-23-2003 revision for the following device:

- D458, D459, D460, D461, D463, D464, D465, D466, D469, D471, D473, D472, D1304

40CFR63 Subpart CC, #5A updated to add 6-20-2013 revision and to remove 6-23-2003, or 10-28-2009 revisions for the following devices:

- D1354, D1355, D1357, D1359, D1361, D1367, D1365, D1366, D1381, D1392, D1419, D1443, D1444, D1446, D1447, D1448, , D1451, D1384, D1454, D1455, D1456, D1458, D1557, D1608, D1683

40CFR68- Accidental Release Prevention updated to add 4-9-2004 revision and to remove 5-24-1996 revisions for the following condition:

- F24.1