

Date: 3/28/2011

**ERRATA****1) Table 1, Perchlorate Soil Data (pages 13 and 14):**

Perchlorate concentrations for eight samples were erroneously reported as non-detect (ND). Corrected values for samples RIA-01 through RIA-04 are shown below:

Area	Site ID	Site Type	Sample Date	Sample Depth (ft bgs)	Concentration (µg/kg)	RL (µg/kg)	Investigating Party
45	RIA-01	SB-DP	6/9/2004	6	450	40	Goodrich / Geosyntec
				12	440	40	
	RIA-02	SB-DP	6/9/2004	6	310	40	Goodrich / Geosyntec
				12	280	40	
	RIA-03	SB-DP	6/9/2004	6	37 J	40	Goodrich / Geosyntec
				12	36 J	40	
	RIA-04	SB-DP	6/9/2004	6	180	40	Goodrich / Geosyntec
				12	630	40	

Source: Draft Remedial Investigation Report - 160-Acre Parcel, Geosyntec Consultants, March 2005.

**2) Table 3, Perchlorate and TCE Groundwater Data (page 1):**

The date on the fourth line for PW-2 was erroneously reported as 10/27/2004. The correct date is 12/27/2004.