

CONTENTS

	Page
SUMMARY	vi
1. INTRODUCTION	1
1.1 Project Personnel	1
2. EXTRACTION AND MONITORING WELL DESTRUCTIONS	2
3. GROUND WATER FLOW	3
4. GROUND WATER ANALYSES	4
4.1 Analytic Results	4
4.1.1 1,1,1-TCA	4
4.1.2 1,1-DCA	5
4.1.3 1,1-DCE	5
4.1.4 Other VOCs	6
4.2 QA/QC Review	6
5. PUMPING MODIFICATION PROGRAM	7
5.1 Background	7
5.2 Analytic Results	7
6. EXTRACTION SYSTEM AND MONITORING WELL STATUS	9
7. OTHER REPORTING REQUIREMENTS	10
7.1 Monitoring and Reporting in Accordance with Site Discharge Permits	10
7.2 Projected Use of Applied Materials Building 1	10
7.3 Hydrogeologic Setting	10
7.4 Natural Attenuation Evaluation	11

8. PROPOSED REMEDIAL ACTIONS FOR 2005-2006	12
9. CONCLUSIONS	13
10. REFERENCES	14

FIGURES

- Figure 1. Well Locations - Applied Materials Building 1 and Vicinity
- Figure 2. Potentiometric Surface of the A Water-Bearing Zone–July 8, 2004
- Figure 3. Potentiometric Surface of the A Water-Bearing Zone–January 11, 2005
- Figure 4. Ground Water Elevation vs. Time, Representative A-Zone Monitoring Wells
- Figure 5. 1,1,1-TCA in the A Water-Bearing Zone– January 12 and 13, 2005
- Figure 6. 1,1-DCA in the A Water-Bearing Zone– January 12 and 13, 2005
- Figure 7. 1,1-DCE in the A Water-Bearing Zone– January 12 and 13, 2005
- Figure 8. 1,1,1-TCA, 1,1-DCA, and 1,1-DCE vs. Time, January 1997 through January 2005
Wells AM1-11, AM1-5E, AM1-6, and AM1-7
- Figure 9. Geologic Section A-A'

TABLES

- Table 1. 2005 and Proposed 2006 Self-Monitoring Program and Reporting Schedule
- Table 2. Ground Water Elevations, January 14, 2004 to January 13, 2005
- Table 3. Signature VOCs in Ground Water at Selected Wells, Pumping Modification Program
- Table 4. Well Details and Depths

APPENDICES

- Appendix A. Analytic Results for Volatile Organic Compounds in Ground Water, November 1983 through January 2005
- Appendix B. QA/QC Summary Tables and Chain-of-Custody Records, January 2005