

8.0 ISSUES

Table 8.1 summarizes the issues identified at the sites under consideration in this Five-Year Review during the data evaluation and assessment process. Identified issues are evaluated as to whether they affect the current protectiveness of the remedy, or may affect the protectiveness in the future.

**Table 8.1
Issues Summary
Luke AFB, Arizona**

Issue	Affects Protectiveness	
	Currently	Future
MW-123 at PSC FT-07E has collapsed.	No*	No*
MW-124 at PSC RW-02 has collapsed.	No	No
Sample zone was obstructed at MW-114 at PSC ST-18.	No*	No*
The screen of MW-118 at PSC FT-07 is submerged.	No*	No*
The screen of MW-114 at PSC ST-18 is submerged.	No*	No*
The screen of MW-113 at PSC SD-20 is submerged.	No*	No*
The screen of MW-121 at PSC SS-42 is submerged.	No*	No*
The screen of MW-125R at PSC SS-42 is submerged.	No*	No*
Metals groundwater data for MW-119 at PSC SS-42 is incomplete.	No	No
Institutional Control Plan does not discuss PSC DP-23.	No	No
Institutional Control Plan should not include PSC SS-42.	No	No
Base General Plan does not list or illustrate PSC DP-23	No	No
Base General Plan does not list or illustrate PSC ST-18	No	No

Notes:

* See the explanation provided in Section 7.1.2. Also, the Base is pursuing funds to replace the wells with submerged screens and the replacement wells will be sampled shortly after they are installed

MW monitoring well

PSC potential source of contamination

This page was intentionally left blank.