Figure 2-1 Regional Drawdown Correction Example
Water Level Elevations in MW-12 Wells



fig2-1



URS

2003 Pumping Tests Technical Memorandum for Extraction Wells EW-108 and EW-112
Newmark Groundwater Contamination Superfund Site
San Bernardino, California

Figure 2-2. Well Responses to Pumping

Z:\Emagis\Newmark\OPS\2003 pumptestsltech memo\fig2-2.wor 03/31/04 kep