

LEGEND

- PEMACO SITE BOUNDARY FENCE
- B-6 — MONITORING WELL, PERCHED ZONE (<35 FEET BGS.)
- HP-5 — HYDROPUNCH LOCATION (IN-SITU GROUNDWATER SAMPLE COLLECTED FROM 25'-30' BGS., FEBRUARY 2001)
- MW-2 — MONITORING WELL, EXPOSITION AQUIFER
- CPT-13 — CONE PENETRATION TESTING LOCATION (IN-SITU GROUNDWATER SAMPLE COLLECTED FROM 75'-80' BGS., FEB. 2001)
- —118— GROUNDWATER ELEVATION CONTOUR LINE
- 116.50 — GROUNDWATER ELEVATION IN FEET ABOVE MEAN SEA LEVEL

NOTES:

1. ALL PERCHED ZONE WELLS GAUGED 4/1/2002.
2. GROUNDWATER ELEVATION FOR B-17 IS NOT USED FOR CONTOURING DUE TO STRATIGRAPHIC CONDITIONS IN THAT LOCATION. SEE CROSS SECTION A-A'.

0 40 80

APPROXIMATE SCALE IN FEET

DATE:	FILE NAME:	APPROVED BY:
5/5/2002	PEM-P-GGM-2Q-02.DWG	

GROUNDWATER GRADIENT MAP
PERCHED ZONE, APRIL 2002

PEMACO SUPERFUND SITE
5050 EAST SLAUSON AVENUE
MAYWOOD, CALIFORNIA

TN & A — T N & Associates, Inc. Engineering and Science

FIGURE 7B