

Seismic Line Location Map



EXPLANATION

Upper/Lower HSU Contact as Interpreted From Borehole and CPT Data

* Depth BGS Shown to Account for Topographic Variation Between Seismic Line and Well Location

FIG L-16.DWG 40.0
20101213.1133

NO.	DATE	REVISIONS	BY	CHK

DRAWN:	Ntm	PROJECT NO:	4088097619
ENGINEER:		SCALE:	Check Graphic
CHECKED:	NAM	APPROVED:	WJF
DATE:	1/2011	DATE:	1/2011

Final Remedial Investigation Report

Casmalia Resources Superfund Site
Casmalia, California

Seismic Refraction Results
Production Survey Line SL-8

FIGURE **L-16**
SHEET: OF
REVISION NUMBER: 0
DATE: January 2011