



EXPLANATION

Upper/Lower HSU Contact as Interpreted From Borehole and CPT Data

Plotted: 12-14-2010 10:11 AM By: pcbouldreau
Path: P:\4098\042051_Casmalia\RI Report Draft 2007\Appendix L\CAD\RWS_work_November2007\ Fig L-37_P2SL-12_30ltr.dwg

NO.	DATE	REVISIONS	BY	CHK

DRAWN: Ntm	PROJECT NO: 4088097619		
ENGINEER:	SCALE: Check Graphic		
CHECKED: NAM	APPROVED: WJF		
DATE: 1/2011	DATE: 1/2011		

Final Remedial Investigation Report
Casmalia Resources Superfund Site
Casmalia, California

Phase II Seismic Refraction Results
Line P2SL-12

FIGURE **L-37**
SHEET: OF
REVISION NUMBER: 0
DATE: January 2011