

All Values in mg/kg

Explanation

0 240 480
Scale in Feet

Soil Sample Locations
- Sediment (Type 8a/8b)

Other Site Features
- Casmalia Site Boundary
- Stormwater Ponds Area Boundary
- Piezometer
- Monitoring Well
- Liquids Extraction Well
- Historical Soil Samples
- Perimeter Source Control Trench (Brierly & Lyman, 1989)
- Perimeter Control Trench (Brierly & Lyman, 1989)
- Fence
- Road Remnants
- Historical Natural Drainage (Based on 1956 Photo, 1974 Topographic Maps, and Figures 21-2 and 21-3 Woodward-Clyde, 1988)
- Historical Features
- Stormwater Pond
- Treated Liquid Impoundment
- Trench

Source: Topographic base map provided by Pacific Engineering, Inc. from aerial survey dated March 4, 2004

Figure B-19a

Summary Analytical Results
Inorganics Detected Above Screening Levels
Stormwater Ponds

Final Remedial Investigation Report
Casmalia Resources Superfund Site
January 2011

T:\CASMALIA\GIS\deliverables\RI_Final_11\AppendixB\stormwater.apr