


Seismic Line Location Map




EXPLANATION

Upper/Lower HSU Contact as Interpreted From Borehole and CPT Data

* Depth BGS Shown to Account for Topographic Variation Between Seismic Line and Well Location

FIG L-21.DWG 40.0
20101213:1309

| NO. | DATE | REVISIONS | BY | CHK |
|---|---|---|---|---|

| | | | |
|---|---|---|---|
| DRAWN: Ntm | PROJECT NO: 4088097619 | | |
| ENGINEER: | SCALE: Check Graphic | | |
| CHECKED: NAM | APPROVED: WJF | | |
| DATE: 1/2011 | DATE: 1/2011 | | |

**Final Remedial Investigation Report**

Casmalia Resources Superfund Site
Casmalia, California

**Seismic Refraction Results**
**Production Survey Line SL-13**

FIGURE **L-21**
SHEET: OF
REVISION NUMBER: 0
DATE: January 2011