

Legend

- Groundwater Well
- Road

Notes:

[1] ARU-1 = Location ID
[2] J = Estimated value
[3] µg/L = micrograms per liter
[4] mg/L = milligrams per liter
[5] pCi/L = picocuries per liter
[6] Concentrations shown for each location are exceedances of either the EPA Maximum Contaminant Levels (MCLs), the EPA Region IX Preliminary Remediation Goals (PRGs) or both.
[7] Dissolved metals exceedances are not included
[8] Aerial Source: ESRI I3 Imagery Prime World 2D dataset, April 26, 1992; October 12, 1992; June 17, 2005

Lab Parameter	MCL	PRG	Units
1,2-Dibromoethane	0.05	0.0056	µg/L
Aluminum	50	36,000	µg/L
Antimony	6	15	µg/L
Arsenic	10	0.045	µg/L
bis(2-Ethylhexyl) phthalate	6	4.8	µg/L
Bromodichloromethane	--	0.18	µg/L
Cadmium	5	18	µg/L
Chloride	250	--	mg/L

Lab Parameter	MCL	PRG	Units
Chlorodibromomethane	--	0.13	µg/L
Chloroform	--	0.17	µg/L
Fluoride	4,000	2.2	mg/L
Gross Alpha Activity	15	--	pCi/L
Iron	300	11,000	µg/L
Manganese	50	880	µg/L
Molybdenum	--	180	µg/L

Lab Parameter	MCL	PRG	Units
Radium 226 Activity	--	0.000823	pCi/L
Selenium	50	180	µg/L
Sulfate	250	--	mg/L
Tetrachloroethene	5	0.1	µg/L
Total Dissolved Solids	500	--	mg/L
Trichloroethene	5	0.028	µg/L
Vanadium	--	36	µg/L

N
W E
S

0 1,500 3,000 6,000 Feet

DRAFT

FIGURE 4-49
SUMMARY OF GROUNDWATER SAMPLE EXCEEDANCES, AUGUST-SEPTEMBER 2006
ASARCO, LLC Hayden Plant Site
Hayden, Arizona

The data on this figure are derived from tables 4-16, 4-17, 4-18, 4-20, 4-21, 4-22, 4-23, 4-25, 4-26, and 4-27.

CH2MHILL

\\MADISON\GROUPS\EMS\GIS_LIBRARY\ASARCO\MAPFILES\03_FINAL\FIG4-49_GW_EXCEEDANCE_AUGUST-SEPTEMBER2006.MXD TJW 7/24/2008