19th Avenue Landfill Superfund Site 2010 Five Year Review

Appendix J - Photographs of Current Site Condition



19th Ave. Landfill Cell A-1 Flare Station Documents, 3-25-10.

19th Ave. Landfill Cell A-1 Cap Showing Erosion and Straw Waddles, 3-25-10, looking East.



Cell A Erosion - 19th Ave Landfill.

19th Ave. Landfill Cell A Storm Drain Inlet in East Perimeter Drainage Showing Debris on Grate, 3-9-2010, looking East.

19th Ave. Landfill Cell A Landfill Gas Extraction Blowers, 3-9-2010, looking Northeast.



19th Ave Cell A Landfill GasCondensate Collection System Vault (note the condition of Vault), 2-9-2010.

19th Ave. Landfill Cell A
Gas System Condensate Collection Vault Showing Recent Excavation and Leaking Pneumatic Lines.



Area with evidence of ponding NW corner of Cell A Cap.

#9
Groundwater Monitoring Well - 19th Avenue Landfill

#10
Cracks in Cap of Cell A - 19th Ave Landfill

#11
Salt River Flow - 19th Ave Landfill.


#12
19th Ave. Landfill Cell A
and Salt River from Cell A-1,3-25-10,looking North.

19th Ave. Landfill Cell A Perimeter Landfill Gas Probe at Northwest Corner,3-9-2010.

19th Ave. Cell A Landfill Gas Blower, 3-9-2010,looking Northeast.

19th Ave. Landfill Cell A Signage at Main Entrance Northwest Corner,3-9-2010.

19th Ave. Landfill Cell A South - Central Gate and Signage ,3-9-2010,looking N of Rio Salado Parkway.

#17
19th Ave. Landfill Cell A Southwest Retention Basin
3-9-2010,looking South.


#18
CITY OF PHOENIX PROPERTY
NO TRESPASSING
19th Ave Landfill Cell A-1 Flare Station Gate
and Signage, 3-25-10,looking Northeast.

#19
Erosion By Roadway - 19th Ave Landfill.

#20
A-1 Flare Station with
Cell A Levees & Industrial background.

#21
Rip Area SE Corner of Cell A.

#22
Ramp on Cell A-1 Levee showing
Debris left by River Flows.


#23
19th Ave. Bridge &
Cell A Levee from Riparian Area River.