





EXPLANATION

Upper/Lower HSU Contact as Interpreted From Borehole and CPT Data

* Contact depth adjusted to account for topography

Plotted: 12-21-2010 4:59 PM By: pcboudreau
Path: P:\4098\042051_Casmalia\RI Report Draft 2007\Appendix L\CAD\RWS_work_November2007\ Fig L-04.dwg

| NO. | DATE | REVISIONS | BY | CHK |
|---|---|---|---|---|
| | | | | |

| | | | |
|---|---|---|---|
| DRAWN: | NTM | PROJECT NO: | 4088097619 |
| ENGINEER: | | SCALE: | Check Graphic |
| CHECKED: | NAM | APPROVED: | WJF |
| DATE: | 1/2011 | DATE: | 1/2011 |

**Final Remedial Investigation Report**

Casmalia Resources Superfund Site
Casmalia, California

**Seismic Refraction Results**
**Pilot Study Line PS-1**

FIGURE **L-4**
SHEET: OF
REVISION NUMBER: 0
DATE: January 2011