

LEGEND

- Burial Trench
- Landfill Boundaries
- Facility and Zone 1 Boundary
- Perimeter Source Control Trench (PSCT)
- Plume Capture Collection Trench (PCT)
- Clay Barrier
- Creek
- Pond Outline
- Topographic Contours (contour interval is 10 feet)
- 20 — Saturated Thickness Contour March 2001 (feet)
- 10 — Saturated Thickness 10 feet Model Layer 1 Unsaturated
- 0 — Saturated Thickness Zero feet Model Layers 1-3 Unsaturated
- 422.0' Pond Stage Elevation
- MW-15C Upper HSU Monitoring Well
- GW-P(E) Upper HSU Piezometer
- RP-85D Lower HSUPiezometer with Vibrating Wire Transducer
- RAP-3A Upper HSU Extraction Point
- POND18 Upper HSU Surface Water Sample
- RP-60C Lower HSU Monitoring Well
- C1-1C Lower HSU Piezometer
- MET Meteorological Station
- ⊠ Water Level May Not Be in Equilibrium
- △ Deeper Lower HSU Well or Piezometer; water level not used in contouring
- ◇ Water Level Not Used in Contouring
- NM Not Measured
- ND No Data

NOTES:

Topo map revised 1998, 2000 and 2003.

Zone 1 boundary (green) is approximate and includes the area within the facility boundary.

4088097619/15000.DWG 1.0
20111011153:13:53

NO.	DATE	REVISIONS	BY	CHK

DRAWN: PCB	PROJECT NO:	4088097619	
ENGINEER:	SCALE:	1"= 400'	
CHECKED: NAM	APPROVED:	WJF	
DATE: 1/2011	DATE:	1/2011	

Final Remedial Investigation Report

Casmalia Resources Superfund Site
Casmalia, California

Saturated Thickness of Upper HSU (Model Layers 1-3) March 2001

FIGURE: **F-6**
SHEET: **1** OF **1**
REVISION NUMBER: 0
DATE: January 2011