

City of Middleton

DRAFT 09/18/00

SAMPLE DISCHARGE MONITORING REPORT (DMR)1

Reporting and Tracking Trades on DMRs and in PCS

I. DMRs:

1A	Parameter	Effluent	<i>[actual measured P discharge]</i>
1B	Limit		Reporting Only
2A	Parameter	Credits	5.0
2B	Limit		Reporting Only
3A	Parameter	Debits	0
3B	Limit		Reporting Only
4A	Parameter	Ratio	.75
4B	Limit		Reporting Only
5A	Parameter	Adjusted Discharge	6.67 $xx - [(5.0 - 0)/.75] = xx + 6.67$
5B	Limit		[Unadjusted base permit limit]

Items in italics are what the permittee reports on the form. Everything else is preprinted on the form. The bottom row (5A/5B) is what PCS will use for the compliance determination. Rows 2 and 3 would be in "Parma Pounds", and rows 1 and 5 would be in real pounds measured at the outfall.

City of Boise

SAMPLE DISCHARGE MONITORING REPORT (DMR)

Reporting and Tracking Trades on DMRs and in PCS

I. DMRs:

1A	Parameter	Effluent	<i>[actual measured P discharge]</i>
1B	Limit		Reporting Only
2A	Parameter	Credits	0
2B	Limit		Reporting Only
3A	Parameter	Debits	5.0
3B	Limit		Reporting Only
4A	Parameter	Ratio	.56
4B	Limit		Reporting Only
5A	Parameter	Adjusted Discharge	8.9 $yy - [(0 - 5.0)/.56] = yy - 8.9$
5B	Limit		[Unadjusted base permit limit]

Items in italics are what the permittee reports on the form. Everything else is preprinted on the form. The bottom row (5A/5B) is what PCS will use for the compliance determination. Rows 2 and 3 would be in "Parma Pounds", and rows 1 and 5 would be in real pounds measured at the outfall.

¹ The real DMRs will include detailed instructions on how to complete the form