



South Coast Air Quality Management District

21865 Copley Drive, Diamond Bar, CA 91765-4178
(909) 396-2000 • www.aqmd.gov

June 12, 2013

Ms. Yijin Wang
Air Quality Manager
Kinder Morgan Energy Partners, L.P.
1100 Town and Country Road
Orange, California 92868

Dear Ms. Wang:

RE: Facility ID # 800129
SFPP, L.P. (Colton South Terminal)
2359 Riverside Ave.
Bloomington, CA

Enclosed are the revised Title Page, Table of Contents, and Section D of your Title V/RECLAIM Facility Permit. The revised sections reflect the changes as follows:

Section D – Permits to Operate (Revised)

<i>Device No.</i>	<i>New Appl. No.</i>	<i>Previous Appl. No.</i>	<i>Description/Modification</i>
D25	458547	444960	STORAGE TANK, INTERNAL FLOATING ROOF, NO. C-23 <ul style="list-style-type: none">• Add rim mounted secondary seal• Increase vapor pressure and throughput• Remove recirculation line and connect line• Correct nominal capacity
D26	458551	444961	STORAGE TANK, INTERNAL FLOATING ROOF, NO. C-25 <ul style="list-style-type: none">• Add secondary seal• Increase vapor pressure and throughput
D28	458552	444963	STORAGE TANK, INTERNAL FLOATING ROOF, NO. C-27 <ul style="list-style-type: none">• Add rim mounted secondary seal• Increase vapor pressure and throughput

D34	458553	444976	STORAGE TANK, INTERNAL FLOATING ROOF, NO. C-33 <ul style="list-style-type: none"> • Add rim mounted secondary seal • Increase vapor pressure and throughput
D35	458554	444965	STORAGE TANK, INTERNAL FLOATING ROOF, NO. C-34 <ul style="list-style-type: none"> • Correct from wiper to rim mounted secondary seal • Increase vapor pressure and throughput • Remove conditions that reference drain dry tanks (this was imposed on previous permit in error since this is not a drain dry tank)
D37	458557	444973	STORAGE TANK, INTERNAL FLOATING ROOF, NO. C-36 <ul style="list-style-type: none"> • Add secondary seal • Increase vapor pressure and throughput

This revision is covered under A/N 509021 and is a "minor permit revision" to the Title V/RECLAIM permit previously dated April 1, 2013. No comments were received during the EPA comment period which began about April 4, 2013.

Additionally, the following permit was inadvertently omitted from the April 1, 2013 TV/RECLAIM Facility Permit. A/N 481543 (G2496) was issued a Permit to Operate/Construct in the April 23, 2009 (Revision 1). After construction completion, SFPP Colton informed SCAQMD that the actual sump installed is smaller than originally planned (from 10000 gallon to 4000 gallon). This description correction is administrative, since there is no change in emissions, and is updated in this revision.

<i>Device No.</i>	<i>Application No.</i>	<i>Description</i>
D317	481543	STORAGE TANK, NO. C-47, UNDERGROUND

Please review the attached sections carefully. Insert the enclosed sections into your Title V/RECLAIM Facility Permit and discard the earlier versions.

Ms. Yijin Wang
Kinder Morgan Liquid Terminals, LLC.
SFPP Colton Terminal 800129

- 2 -

June 12, 2013

The operation of your facility is bound by the conditions and/or requirements stated in the facility Permit to Operate. If you determine that there are administrative errors, or if you have any questions concerning changes to your permit, please contact Ms. Linda Dejbakhsh, Air Quality Engineer, at (909) 396-2614 within 30 days of the receipt of your permit.

Sincerely,



Andrew Y. Lee, P.E.
Senior Engineering Manager
Energy/Public Services/Waste
Mgmt./Terminals- Permitting
Engineering and Compliance

AYL:CDT:LLD
Enclosures

cc: Gerardo Rios, EPA Region IX
Compliance
Central File
TV Application File (A/N 509021)
A/N 458547 (cover letter)