

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

JUL 3 1 2007

REPLY TO THE ATTENTION OF:

SC-6J

CERTIFIED MAIL RETURN RECEIPT REQUESTED

Patrick Hedger Plant Manager Prairie Farms Dairy, Inc. 400 West Highway 50 O'Fallon, IL 62269

RE: Complaint and Expedited Settlement Agreement

ESA Docket No: RMP-06-ESA-010 Docket No. **CAA-05-2007-0015**

Dear Mr. Hedger:

Enclosed please find a copy of the fully executed Expedited RMP Settlement Agreement (ESA). The ESA is binding on U.S. EPA and Respondent. U.S. EPA will take no further action against Respondent for the violations cited in the ESA. The ESA requires no further action on your part.

Please feel free to contact Monika Chrzaszcz at (312) 886-0181 if you have any questions regarding the enclosed document or if you have any other question about the program. Thank you for your assistance in resolving this matter.

Sincerely yours,

Mark J. Horwitz, Chie Chemical Emergency

Preparedness & Prevention Section

Enclosure(s)



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

REPLY TO THE ATTENTION OF:

EXPEDITED SETTLEMENT AGREEMENT (ESA)

DOCKET NO: RMP-06-ESA-010

This ESA is issued to: Prairie Farms Dairy, Inc.
At: 400 West Highway 50, O'Fallon, Illinois 62269
for violating Section 112(r)(7) of the Clean Air Act.

CAA-05-2007-0015

This Expedited Settlement Agreement (ESA) is being entered into by the United States Environmental Protection Agency (EPA), Region 5, by its duly delegated official, the Director, Division, and by Respondent pursuant to Section 113(a)(3) and (d) of the Clean Air Act, 42 U.S.C. § 7413(a)(3) and (d), and by 40 C.F.R. § 22.13(b). On November 30, 2006, EPA obtained the concurrence of the U.S. Department of Justice, pursuant to Section 113(d)(1) of the Act, 42 U.S.C. §7413(d)(1), to pursue this administrative enforcement action.

ALLEGED VIOLATIONS

On July 15, 2005, an authorized representative of the EPA conducted a compliance inspection of the subject facility (Respondent) to determine compliance with the Risk Management Plan (RMP) regulations promulgated at 40 C.F.R. Part 68 under Section 112(r) of the Act. EPA found that the Respondent had violated regulations implementing Section112(r) of the Act by failing to comply with the regulations as noted on the attached RISK MANAGEMENT PLAN INSPECTION FINDINGS, ALLEGED VIOLATIONS AND PROPOSED PENALTY SHEET (FORM), which is hereby incorporated by reference.

SETTLEMENT

In consideration of Respondent's size of business, its full compliance history, its good faith effort to comply, and other factors as justice may require, and upon consideration of the entire record the parties enter into the ESA in order to settle the violations, described in the attached FORM for the total penalty amount of \$1,845.00.

This settlement is subject to the following terms and conditions:

The Respondent by signing below waives any objections that it may have regarding jurisdiction, neither admits nor denies the specific factual allegations contained in herein and in the FORM, and consents to the assessment of the penalty as stated above. Respondent waives its rights to a hearing afforded by Section 113(d)(2)(A) of the Act, 42 U.S.C §7413(d)(2)(A), and to appeal this ESA. Each party to this action shall bear its own costs and fees, if any. Respondent also certifies, subject to civil and criminal penalties for making a false submission to the United States Government, that the Respondent has corrected the violations listed in the attached FORM and has sent a cashier's check or certified check (payable to the "Treasurer, United States of America") in the amount of \$1,845.00 in payment of the full penalty amount to the following address:

U.S. EPA Region 5 P.O. Box 371531 Pittsburgh, PA 15251-7531 The DOCKET NUMBER OF THIS ESA must be included on the check. (The DOCKET NUMBER is located at the top left corner of this ESA.)

This original ESA and a copy of the check must be sent by certified mail to:

Monika Chrzaszcz
Chemical Emergency
Preparedness and Prevention Section (SC-6J)
U.S. Environmental Protection Agency
77 West Jackson Boulevard
Chicago, Illinois 60604-3590

Upon Respondent's submission of the signed original ESA, EPA will take no further civil action against Respondent for the alleged violations of the Act referenced in the FORM. EPA does not waive any other enforcement action for any other violations of the Clean Air Act or any other statute.

If the signed original ESA with an attached copy of the check is not returned to the EPA Region 5 office at the above address in correct form by the Respondent within 45 days of the date of Respondent's receipt of it (90 days if an extension is granted), the proposed ESA is withdrawn, without prejudice to EPA's ability to file an enforcement action for the violations identified herein and in the FORM.

This ESA is binding on the parties signing below.

This ESA is effective upon filing with the Regional Hearing Clerk.

FOR RESPONDENT:	- 0 nM
Signature: / which Hodges	Date: <u>5-9-</u> 07
Name (print): PATRICK HOLER	
Title (print): PLANT MANAGER	
Prairie Farms Dairy, Inc.	
FOR COMPLAINANT: Mar Melc	Date: 7/10/17
Richard C. Karl, Director Superfund Division	/
I hereby ratify the ESA and incorporate it herein by reference. It	is so ORDERED. Date: 7/24/07
Mary A. Gade, Regional Administrator	



U.S. ENVIRONMENTAL PROTECTION AGENCY

RISK MANAGEMENT PROGRAM INSPECTION FINDINGS, ALLEGED VIOLATIONS AND PROPOSED PENALTY SUMMARY

CAA-05-2007-0015

REASON FOR INSPECTION: This inspection is for the purpose of determining compliance with the accidental release prevention requirements of Section 112(r)(7) of the Clean Air Act (Act), 42 U.S.C. § 7412(r)(7), and the regulations set forth at 40 C.F.R. Part 68. The scope of this inspection may include, but is not limited to: reviewing and obtaining copies of documents and records; interviews and taking of statements; reviewing chemical storage, handling, processing, and use; taking samples and photographs; and any other inspection activities necessary to determine compliance with the Act.

FACILITY NAME		X PRIVATE		☐ GOVERNMENTAL/MUNICIPAL
Prairie Farms Dairy, Inc.		32 EMPLOYEES		POPULATION SERVED
FACILITY ADDRESS 400 West Highway 50 O'Fallon, IL 62269				
RESPONSIBLE OFFICIAL, TITLE, PHONE NUMBER Monika Chrzaszcz, Environmental Engineer, (312) 886-0181		EPA FACILITY ID# 100000031878		
FACILITY REPRESENTATIVE(S), TITLE(S), PHONE NUMBER(S) Patrick Hedger, Plant Manager, (618) 632-3632 Dave Maneke, Safety Coordinator, (217) 854-2547		INSPECTOR NAME(S), TITLE Monika Chrzaszcz, Environme		
FACILITY REPRESENTATIVE, SIGNATURE DATE		INSPECTOR SIGNATURE	Mo	ml Clapsy DATE 24/06
	INSPECTIO	N FINDINGS		////
IS FACILITY SUBJECT TO RMP REGULATION (40 CFR 68)?		>	X YES	□ NO
DID FACILITY SUBMIT AN RMP AS PROVIDED IN 68.150 TO 68.185?			x YES	□NO
DATE RMP FILED WITH EPA: 06/8/1999	DATE	OF LATEST RMP UPDATE:	08/21/20	04
PROCESS/NAICS CODE:31152 Ice Cream and Frozen Dessert Manufacturing		PROGRAM LEVEL	: 1 🗆 2	□ 3×
REGULATED SUBSTANCE:anhydrous ammonia	MAX. C	QUANTITY IN PROCESS: 11,000	(lbs)	
2) PROCESS/NAICS CODE:	PROG	RAM LEVEL: 1 🗘 2 🖸 3 🖸		
REGULATED SUBSTANCE:	MAX. (DUANTITY IN PROCESS:		(lbs)
3) PROCESS/NAICS CODE:	_ PROGR	RAM LEVEL: 1 2 2 3 0		
REGULATED SUBSTANCE:	MAX. 0	DUANTITY IN PROCESS:		(lbs)
4) PROCESS/NAICS CODE:	PROG	RAM LEVEL: 1 🗘 2 🗘 3 🗘		
REGULATED SUBSTANCE:	MAX. (DUANTITY IN PROCESS:		(lbs)
5) PROCESS/NAICS CODE:	PROG	RAM LEVEL: 1 🗓 2 🗓 3 🗓		
REGULATED SUBSTANCE:	MAX. (DUANTITY IN PROCESS:		(lbs)
DID FACILITY CORRECTLY ASSIGN PROGRAM LEVELS TO PROCESSES?			J YES	□NO
ATTACHED CHECKLIST(S): D PROGRAM LEVEL 1 PROCESS CHECKLIST D PROGRAM LEVEL 2 PROCES	ce curcy	V DDOODANI SVEI	a ppoor	CO CHECKLIST
☐ PROGRAM LEVEL 1 PROCESS CHECKLIST ☐ PROGRAM LEVEL 2 PROCES	33 UNEUKL	IST X PROGRAM LEVEL	3 FNOCE	SS CHECKES!
OTHER ATTACHMENTS:				
INSPECTION SYMBOL KEY: Y - YES, N - NO, N/A - NOT APPLICABLE, S - SATIS	SFACTORY,	M - MARGINAL, U - UNSATISFA	ACTORY	

racinty Name. Frame Fams Daily, Inc. O Famon, IL				
Date RMP submitted: Initial: 6/8/1999, Updte: 6/21/2004	Date process(e	es) came	online:	<u>1967</u>
All comments and suggestions are in bold and italicized.	407			
Section A-Management [68.15]				
Management system developed and implemented as provided in 40 CFR 68.15? Comments:		S ⊠M	ם ט נ	⊃ N/A
Has the owner or operator:				
Developed a management system to oversee the implementation of the risk management program elements? [68.15(a)]	gement	⊠Y	□N	□ N/A
 Assigned a qualified person or position that has the overall responsibility for the devimplementation, and integration of the risk management program elements? [68.15] Pat Hedger has overall responsibility for the development, implementation, and in the risk management program elements at the O'Fallon facility. 	5(b)]	⊠Y	□N	□ N/A
 Documented other persons responsible for implementing individual requirements of management program and defined the lines of authority through an organization of document? [68.15(c)] Documentation was not available of other persons responsible for implementing requirements of the risk management program. Corporate employees as well as a individuals within the facility that are responsible for each individual requirement noted. 	hart or similar individual other	ΠY	⊠N	□ N/A
Section B: Hazard Assessment [68.20-68.42]				
Hazard assessment conducted and documented as provided in 40 CFR 68.20-68.42? Comments:		∃S □M	υu	□ N/A
Hazard Assessment: Offsite consequence analysis parameters [68.22]				
 Used the following endpoints for offsite consequence analysis for a worst-case scenario: [68.22(a)(1)] a. For toxics: the endpoints provided in Appendix A of 40 CFR Part 68? [68.22(a)(1)] b. For flammables: an explosion resulting in an overpressure of 1 psi? [68.22(a)(2)(i)])]	⊠Y	□N	□ N/A
☐ c. For flammables: a fire resulting in a radiant heat/exposure of 5 kw/m² for 4 [68.22(a)(2)(ii)]	0 seconds?			
or d. For flammables: a concentration resulting in a lower flammability limit, as p NFPA documents or other generally recognized sources? [68.22(a)(2)(iii)]	provided in			
 2. Used the following endpoints for offsite consequence analysis for an alternative relegions [68.22(a)] ☑ a. For toxics: the endpoints provided in Appendix A of 40 CFR Part 68? [68.22(a)] ☑ b. For flammables: an explosion resulting in an overpressure of 1 psi? [68.22(a)] ☑ c. For flammables: a fire resulting in a radiant heat/exposure of 5 kw/m2 for 40 [68.22(a)(2)(ii)] ☑ d. For flammables: a concentration resulting in a lower flammability limit, as presulting in a lower flammability limit flammability limit	2(a)(1)] a)(2)(i)]) seconds?	ΣY	□N	□ N/A
3. Used appropriate wind speeds and stability classes for the release analysis? [68.22(b)]		⊠Y	□N	□ N/A
4. Used appropriate ambient temperature and humidity values for the release analysis	s? [68.22(c)]	⊠Y	ΠN	□ N/A
5. Used appropriate values for the height of the release for the release analysis? [68.2]	22(d)]	⊠Y	ΠN	□ N/A

Program Level 3 Process Checklist

Facility Name: Prairie Farms Dairy, Inc. O'Fallon, IL Used appropriate surface roughness values for the release analysis? [68.22(e)] $\boxtimes Y$ \Box N □ N/A Do tables and models, used for dispersion analysis of toxic substances, appropriately account for □ N/A $\boxtimes Y$ dense or neutrally buoyant gases? [68.22(f)] Were liquids, other than gases liquefied by refrigeration only, considered to be released at the □Y □N ⊠ N/A highest daily maximum temperature, based on data for the previous three years appropriate for a stationary source, or at process temperature, whichever is higher? [68.22(g)] Hazard Assessment: Worst-case release scenario analysis [68.25] 9. Analyzed and reported in the RMP one worst-case release scenario estimated to create the ⊠Y □N □ N/A greatest distance to an endpoint resulting from an accidental release of a regulated toxic substance from covered processes under worst-case conditions? [68.25(a)(2)(i)] The worst-case release scenario analyzed a gas release from a 2,500 lbs cylinder over 10 minutes, resulting in a 90 lbs/min. release rate. 10. Analyzed and reported in the RMP one worst-case release scenario estimated to create the □Y □N ⊠ N/A greatest distance to an endpoint resulting from an accidental release of a regulated flammable substance from covered processes under worst-case conditions? [68.25(a)(2)(ii)] 11. Analyzed and reported in the RMP additional worst-case release scenarios for a hazard class if □Y □N 図 N/A the a worst-case release from another covered process at the stationary source potentially affects public receptors different from those potentially affected by the worst-case release scenario developed under 68.25(a)(2)(i) or 68.25(a)(2)(ii)? [68.25(a)(2)(iii)] 12. Has the owner or operator determined the worst-case release quantity to be the greater of the ⊠Y □N □ N/A following: [68.25(b)] a. If released from a vessel, the greatest amount held in a single vessel, taking into account administrative controls that limit the maximum quantity? [68.25(b)(1)] b. If released from a pipe, the greatest amount held in the pipe, taking into account administrative controls that limit the maximum quantity? [68.25(b)(2)] 13a. Has the owner or operator for toxic substances that are normally gases at ambient temperature and handled as a gas or liquid under pressure: 13.a.(1) Assumed the whole quantity in the vessel or pipe would be released as a gas over 10 ⊠Y □N □ N/A minutes? [68.25(c)(1)] 13.a.(2) Assumed the release rate to be the total quantity divided by 10, if there are no passive ⊠Y □N □ N/A mitigation systems in place? [68.25(c)(1)] 13.b. Has the owner or operator for toxic gases handled as refrigerated liquids at ambient pressure: 13.b.(1) Assumed the substance would be released as a gas in 10 minutes, if not contained by □Y □N ⊠ N/A passive mitigation systems or if the contained pool would have a depth of 1 cm or less? [68.25(c)(2)(i)] 13.b.(2) [Optional for owner / operator] Assumed the quantity in the vessel or pipe would be □Y □N ⊠ N/A spilled instantaneously to form a liquid pool, if the released substance would be contained by passive mitigation systems in a pool with a depth greater than 1 cm? [68.25(c)(2)(ii)] 13.b.(3) Calculated the volatilization rate at the boiling point of the substance and at the conditions □Y □N ⊠ N/A specified in 68.25(d)? [68.25(c)(2)(ii)] 13.c. Has the owner or operator for toxic substances that are normally liquids at ambient temperature: 13.c.(1) Assumed the quantity in the vessel or pipe would be spilled instantaneously to form a

Facility Name: Prairie Farms Dairy, Inc. O'Fallon, IL			
liquid pool? [68.25(d)(1)]	□Y	ΠN	⊠ N/A
13.c.(2) Determined the surface area of the pool by assuming that the liquid spreads to 1 cm deep, if there is no passive mitigation system in place that would serve to contain the spill and limit the surface area, or if passive mitigation is in place, the surface area of the contained liquid shall be used to calculate the volatilization rate? [68.25(d)(1)(i)]	ΠY	□N	⊠ N/A
13.c.(3) Taken into account the actual surface characteristics, if the release would occur onto a surface that is not paved or smooth? [68.25(d)(1)(ii)]	ΩY	ΠN	⊠N/A
13.c.(4) Determined the volatilization rate by accounting for the highest daily maximum temperature in the past three years, the temperature of the substance in the vessel, and the concentration of the substance if the liquid spilled is a mixture or solution? [68.25(d)(2)]	ΠY	□N	⊠ N/A
13.c.(5) Determined the rate of release to air from the volatilization rate of the liquid pool? [68.25(d)(3)]	ΞY	ΠN	⊠ N/A
13.c.(6) Determined the rate of release to air by using the methodology in the RMP Offsite Consequence Analysis Guidance, any other publicly available techniques that account for the modeling conditions and are recognized by industry as applicable as part of current practices, or proprietary models that account for the modeling conditions may be used provided the owner or operator allows the implementing agency access to the model and describes model features and differences from publicly available models to local emergency planners upon request? [68.25(d)(3)]	ΩY	□N	⊠ N/A
13.d. Has the owner or operator for flammables:			
13.d.(1) Assumed the quantity in a vessel(s) of flammable gas held as a gas or liquid under pressure or refrigerated gas released to an undiked area vaporizes resulting in a vapor cloud explosion? [68.25(e)]	ΠY	□N	⊠ N/A
13.d.(2) For refrigerated gas released to a contained area or liquids released below their atmospheric boiling point, assumed the quantity volatilized in 10 minutes results in a vapor cloud? [68.25(f)]	ΩY	□N	⊠ N/A
13.d.(3) Assumed a yield factor of 10% of the available energy is released in the explosion for determining the distance to the explosion endpoint, if the model used is based on TNT-equivalent methods? [68.25(e)]	ΠY	□N	⊠ N/A
14. Used the parameters defined in 68.22 to determine distance to the endpoints? [68.25(g)]	⊠Y	□N	□ N/A
15. Determined the rate of release to air by using the methodology in the RMP Offsite Consequence Analysis Guidance, any other publicly available techniques that account for the modeling conditions and are recognized by industry as applicable as part of current practices, or proprietary models that account for the modeling conditions may be used provided the owner or operator allows the implementing agency access to the model and describes model features and differences from publicly available models to local emergency planners upon request? [68.25(g)] a. What modeling technique did the owner or operator use? [68.25(g)] Guidance for Ammonia Ref. Ref. Tables or Equations were used.	⊠Y	□N	□ N/A
16. Ensured that the passive mitigation system, if considered, is capable of withstanding the release event triggering the scenario and will still function as intended? [68.25(h)]	⊠Y	ΠN	□ N/A
17. Considered also the following factors in selecting the worst-case release scenarios: [68.25(i)] a. Smaller quantities handled at higher process temperature or pressure? [68.25(i)(1)] b. Proximity to the boundary of the stationary source? [68.25(i)(2)]	ΠY	ΠN	⊠ N/A
Hazard Assessment: Alternative release scenario analysis [68.28]			
18. Identified and analyzed at least one alternative release scenario for each regulated toxic substance			

acility Name: <u>Praine Farms Dairy, Inc. O Fallon, IL</u>			
held in a covered process(es) and at least one alternative release scenario to represent all flammable substances held in covered processes? [68.28(a)] The alternative release scenario analyzed the release of 6,000 lbs, over 60 minutes, resulting in a	⊠Y	ΠN	□ N/A
100 lbs/min. release. The release was assumed to come from a $\frac{1}{4}$ in. hole in the high pressure liquid piping line.			
19. Selected a scenario: [68.28(b)] ☑ a. That is more likely to occur than the worst-case release scenario under 68.25? [68.28(b)(1)(i)]	⊠Y	ΠN	□ N/A
b. That will reach an endpoint off-site, unless no such scenario exists? [68.28(b)(1)(ii)]			
20. Considered release scenarios which included, but are not limited to, the following: [68.28(b)(2)] □ a. Transfer hose releases due to splits or sudden hose uncoupling? [68.28(b)(2)(i)] □ b. Process piping releases from failures at flanges, joints, welds, valves and valve seals, and drains or bleeds? [68.28(b)(2)(ii)] □ c. Process vessel or pump releases due to cracks, seal failure, or drain, bleed, or plug failure?	⊠Y	□N	□ N/A
[68.28(b)(2)(iii)] □ d. Vessel overfilling and spill, or overpressurization and venting through relief valves or rupture disks? [68.28(b)(2)(iv)]			
☐ e. Shipping container mishandling and breakage or puncturing leading to a spill? [68.28(b)(2)(v)]			
21. Used the parameters defined in 68.22 to determine distance to the endpoints? [68.28(c)]	⊠Y	□N	□ N/A
22. Determined the rate of release to air by using the methodology in the RMP Offsite Consequence Analysis Guidance, any other publicly available techniques that account for the modeling conditions and are recognized by industry as applicable as part of current practices, or proprietary models that account for the modeling conditions may be used provided the owner or operator allows the implementing agency access to the model and describes model features and differences from publicly available models to local emergency planners upon request? [68.28(c)]	⊠Y	□N	□ N/A
23. Ensured that the passive and active mitigation systems, if considered, are capable of withstanding the release event triggering the scenario and will be functional? [68.28(d)]	⊠Y	□N	□ N/A
 24. Considered the following factors in selecting the alternative release scenarios: [68.28(e)] a. The five-year accident history provided in 68.42? [68.28(e)(1)] b. Failure scenarios identified under 68.67? [68.28(e)(2)] 	ΠY	□N	⊠ N/A
Hazard Assessment: Defining off-site impacts-Population [68.30]			
25. Estimated population that would be included in the distance to the endpoint in the RMP based on a circle with the point of release at the center? [68.30(a)]	⊠Y	□N	□ N/A
26. Identified the presence of institutions, parks and recreational areas, major commercial, office, and industrial buildings in the RMP? [68.30(b)]	⊠Y	ΠN	□ N/A
27. Used most recent Census data, or other updated information to estimate the population? [68.30(c)]	⊠Y	□N	□ N/A
28. Estimated the population to two significant digits? [68.30(d)]	⊠Y	□N	□ N/A
Hazard Assessment: Defining off-site impacts-Environment [68.33]			
29. Identified environmental receptors that would be included in the distance to the endpoint based on a circle with the point of release at the center? [68.33(a)] Environmental receptors are not included within the distance to endpoint based on a circle with the point of release at the center.	ΟY	ПN	⊠ N/A
30. Relied on information provided on local U.S.G.S. maps, or on any data source containing U.S.G.S. data to identify environmental receptors? [Source may have used LandView to obtain information] [68.33(b)]	⊠Y	□N	□ N/A
Hazard Assessment: Review and update [68.36]			

acility Name: <u>Prairie Farms Dairy, Inc. O'Fallon, IL</u>			
31. Reviewed and updated the off-site consequence analyses at least once every five years? [68.36(a)]	⊠Y	ΠN	□ N/A
32. Completed a revised analysis and submit a revised RMP within six months of a change in processes, quantities stored or handled, or any other aspect that might reasonably be expected on increase or decrease the distance to the endpoint by a factor of two or more? [68.36(b)]	ΠY	□N	⊠ N/A
Hazard Assessment: Documentation [68.39] Has the owner/operator maintained the following records:			
33. For worst-case scenarios: a description of the vessel or pipeline and substance selected, assumptions and parameters used, the rationale for selection, and anticipated effect of the administrative controls and passive mitigation on the release quantity and rate? [68.39(a)]	⊠Y	ΠN	□ N/A
34. For alternative release scenarios: a description of the scenarios identified, assumptions and parameters used, the rationale for the selection of specific scenarios, and anticipated effect of the administrative controls and mitigation on the release quantity and rate? [68.39(b)]	⊠Y	ΩN	□ N/A
35. Documentation of estimated quantity released, release rate, and duration of release? [68.39(c)]	⊠Y	ΩN	□ N/A
36. Methodology used to determine distance to endpoints? [68.39(d)]	⊠Y	ΩN	□ N/A
37. Data used to estimate population and environmental receptors potentially affected? [68.39(e)]	⊠Y	ΩN	□ N/A
Hazard Assessment: Five-year accident history [68.42]			
38. Has the owner or operator included all accidental releases from covered processes that resulted in deaths, injuries, or significant property damage on site, or known offsite deaths, injuries, evacuations, sheltering in place, property damage, or environmental damage? [68.42(a)] The owner or operator stated that there have been no accidents in the past five years at this facility.	ΠY	□N	⊠ N/A
39. Has the owner or operator reported the following information for each accidental release: [68.42(b)] a. Date, time, and approximate duration of the release? [68.42(b)(1)] b. Chemical(s) released? [68.42(b)(2)] c. Estimated quantity released in pounds and percentage weight in a mixture (toxics)? [68.42(b)(3)] d. NAICS code for the process? [68.42(b)(4)] e. The type of release event and its source? [68.42(b)(5)] f. Weather conditions (if known)? [68.42(b)(6)] g. On-site impacts? [68.42(b)(7)] h Known offsite impacts? [68.42(b)(8)] i. Initiating event and contributing factors (if known)? [68.42(b)(9)] j. Whether offsite responders were notified (if known)? [68.42(b)(10)] k. Operational or process changes that resulted from investigation of the release? [68.42(b)(11)]	ΩY	⊡N ·	⊠ N/A
Section C: Prevention Program	-		
Implemented the Program 3 prevention requirements as provided in 40 CFR 68.65 - 68.87? Comments:	; ⊠M	U U	□ N/A
Prevention Program- Process Safety information [68.65]			
1. Has the owner or operator compiled written process safety information, which includes information pertaining to the hazards of the regulated substances used or produced by the process, information pertaining to the technology of the process, and information pertaining to the equipment in the process, before conducting any process hazard analysis required by the rule? [68.65(a)] Agri-Chemicals 1985 ed. of MSDS were reviewed. Does the process safety information contain the following for hazards of the substances: [68.65(b)] a. Toxicity information? [68.65(b)(1)]	⊠Y	□N	□ N/A

a	cility Name: Prairie Farms Dairy, Inc. O'Fallon, IL			
	□ b. Permissible exposure limits? [68.65(b)(2)]			
	☑ C. Physical data? [68.65(b)(3)]			
	☑ d. Reactivity data? [68.65(b)(4)]			
	■ e. Corrosivity data? [68.65(b)(5)]			
	✓ f. Thermal and chemical stability data? [68.65(b)(6)]			
L	g. Hazardous effects of inadvertent mixing of materials that could foreseeably occur? [68.65(b)(7)]			
	2. Has the owner documented information pertaining to technology of the process?		⊠N	□ N/A
	✓ A block flow diagram or simplified process flow diagram? [68.65(c)(1)(i)]	-	1	— 14//
	Latest updated in 2003.			
	\square Process chemistry? [68.65(c)(1)(ii)]-NA			
	✓ Maximum intended inventory? [68.65(c)(1)(iii)]			
	Safe upper and lower limits for such items as temperatures, pressures, flows, or compositions?			
	[68.65(c)(1)(iv)]			
	Upper and lower limits are specified in operating procedures.			
	\Box An evaluation of the consequences of deviation? [68.65(c)(1)(iv)]			
	☐ Does the process safety information contain the following for the equipment in the process: [68.65(d)(1)]			
	✓ Materials of construction? 68.65(d)(1)(i)]			
	☑ Piping and instrumentation diagrams [68.65(d)(1)(ii)]			
	☑ Electrical classification? [68.65(d)(1)(iii)]			
	☐ Relief system design and design basis? [68.65(d)(1)(iv)]			
	The owner or operator does have some documentation on the relief system, but not the relief systems design			
	basis.			
	☐ Ventilation system design? [68.65(d)(1)(v)]			
1	The owner or operator does not have documentation on the ventilation system design.			
	☑ Design codes and standards employed? [68.65(d)(1)(vi)]			
1	☐ Material and energy balances for processes built after June 21, 1999? [68.65(d)(1)(vii)]-NA			
	☐ Safety systems? [68.65(d)(1)(viii)]			
	The owner or operator does not have documentation on the safety systems at the facility.			
	3. Has the owner or operator documented that equipment complies with recognized and generally accepted good	ΠY	⊠N	□ N/A
	engineering practices? [68.65(d)(2)]			
	The owner or operator did not document the relief system design basis, the ventilation system design, and safety			
	systems at the facility.			
İ	A II the assessment determined and degenerated that existing againment designed and constructed in	ENV		
	4. Has the owner or operator determined and documented that existing equipment, designed and constructed in	⊠Y	ΠN	□ N/A
	accordance with codes, standards, or practices that are no longer in general use, is designed, maintained, inspected, tested, and operating in a safe manner? [68.65(d)(3)]			
I	inspected, tested, and operating in a safe manner: [06.05(u)(5)]			
F	Prevention Program- Process Hazard Analysis [68.67]			
,	5. Has the owner or operator performed an initial process hazard analysis (PHA), and has this analysis identified,	⊠Y	ΠN	□ N/A
	evaluated, and controlled the hazards involved in the process? [68.67(a)]		U IV	U 14/A
	An initial PHA was conducted on Dec. 4 th and 5 th of 1996. Another PHA was conducted in 2001.			
	The management of the second o			
,				
,	6. Has the owner or operator determined and documented the priority order for conducting PHAs, and was it	⊠Y	ΠN	□ N/A
,	6. Has the owner or operator determined and documented the priority order for conducting PHAs, and was it based on an appropriate rationale? [68.67(a)]	⊠Y	ПN	□ N/A
6	based on an appropriate rationale? [68.67(a)]			
6	based on an appropriate rationale? [68.67(a)] 7. Has the owner used one or more of the following technologies to conduct process PHA: [68.67(b)]	⊠Y ⊠Y	□N	□ N/A
6	based on an appropriate rationale? [68.67(a)] 7. Has the owner used one or more of the following technologies to conduct process PHA: [68.67(b)] What-if? [68.67(b)(1)]			
6	based on an appropriate rationale? [68.67(a)] 7. Has the owner used one or more of the following technologies to conduct process PHA: [68.67(b)] What-if? [68.67(b)(1)] Checklist? [68.67(b)(2)]			
6	based on an appropriate rationale? [68.67(a)] 7. Has the owner used one or more of the following technologies to conduct process PHA: [68.67(b)] What-if? [68.67(b)(1)] Checklist? [68.67(b)(2)] What-if/Checklist? [68.67(b)(3)]			
6	based on an appropriate rationale? [68.67(a)] 7. Has the owner used one or more of the following technologies to conduct process PHA: [68.67(b)] What-if? [68.67(b)(1)] Checklist? [68.67(b)(2)] What-if/Checklist? [68.67(b)(3)] Hazard and Operability Study (HAZOP) [68.67(b)(4)]			
6	based on an appropriate rationale? [68.67(a)] 7. Has the owner used one or more of the following technologies to conduct process PHA: [68.67(b)] What-if? [68.67(b)(1)] Checklist? [68.67(b)(2)] What-if/Checklist? [68.67(b)(3)] Hazard and Operability Study (HAZOP) [68.67(b)(4)] Failure Mode and Effects Analysis (FMEA) [68.67(b)(5)]			
6	based on an appropriate rationale? [68.67(a)] 7. Has the owner used one or more of the following technologies to conduct process PHA: [68.67(b)] What-if? [68.67(b)(1)] Checklist? [68.67(b)(2)] What-if/Checklist? [68.67(b)(3)] Hazard and Operability Study (HAZOP) [68.67(b)(4)]			

Facility Name: Prairie Farms Dairy, Inc. O'Fallon, IL			
8. Did the PHA address:	⊠Y	ΩN	□ N/A
☑ The hazards of the process? [68.67(c)(1)]			
☑ Identification of any incident which had a likely potential for catastrophic consequences? [68.67(c)(2)]			
Engineering and administrative controls applicable to hazards and interrelationships?[68.67(c)(3)]	1		
□ Consequences of failure of engineering and administrative controls? [68.67(c)(4)]			
✓ Stationary source siting? [68.67(c)(5)]			
☐ Human factors? [68.67(c)(6)]			
☑ An evaluation of a range of the possible safety and health effects of failure of controls? [68.67(c)(7)]			
9. Was the PHA performed by a team with expertise in engineering and process operations and did the team	⊠Y	ΩN	□ N/A
include appropriate personnel? [68.67(d)]			
The PHA team consisted of maintenance employees, supervisors, chief engineers, and the			
safety coordinator.			
10. Has the owner or operator established a system to promptly address the team's findings and recommendations	: D Y	⊠N	□ N/A
assured that the recommendations are resolved in a timely manner and documented; documented what actions		٠	
are to be taken; completed actions as soon as possible; developed a written schedule of when these actions are			
to be completed; and communicated the actions to operating, maintenance, and other employees whose work	´		
assignments are in the process and who may be affected by the recommendations? [68.67(e)]			
The owner or operator did not establish a system to promptly address the team's findings and			
recommendation for both PHA's that have been conducted At the time of the inspection, the			
inspector requested that the facility send in the PHA recommendation tracking form. The	1		
tracking form was received and reviewed. The facility does track recommendations, but needs			
to fully explain what has been done for each activity and how things were resolved and whether			
or not they have been actually resolved. If nothing can be done or currently can't be completed,	, [
that too needs to be identified.			
11. Has the PHA been updated and revalidated by a team every five years after the completion of the initial PHA	⊠Y	ΠN	□ N/A
to assure that the PHA is consistent with the current process? [68.67(f)]			— 11///
The next PHA should be conducted in 2006. I recommend that the facility also include in their	1		
PHA revalidation what they used to revalidated /guide them in the PHA and how they came up			
with their recommendations and suggestions, be specific in methods used.			
12. Has the owner or operator retained PHAs and updates or revalidations for each process covered, as well as the	e 🖂 Y	ΠN	□ N/A
resolution of recommendations for the life of the process? [68.67(g)]			
Prevention Program- Operating procedures [68.69]			
13. Has the owner or operator developed and implemented written operating procedures that provides instructions	s IXIV	□N	□ N/A
or steps for conducting activities associated with each covered process consistent with the safety information?	T .		— 17/7
[68.69(a)]			
14. Do the procedures address the following: [68.69(a)]	ΠY	⊠N	□ N/A
Steps for each operating phase: [68.69(a)(1)]	<u> </u>	۱۷۱ک	U IV/A
☑ Initial Startup? [68.69(a)(1)(i)]☑ Normal operations? [68.69(a)(1)(ii)]			
☐ Temporary operations? [68.69((a)(1)(iii)]-NA because the system never runs under temporary			
operations.	1		
 Significant specific conditions and the specific conditions are conditions and the specific conditions. Image: Condition of the cond			
assignment of shutdown responsibility to qualified operators to ensure that emergency shutdown is executed in	n		
a safe and timely manner? [68.69(a)(1)(iv)]			
\boxtimes Emergency operations? [68.69(a)(1)(v)]			
□ Normal shutdown? [68.68(a)(1)(vi)]			
Plate hardener and pump out procedures were reviewed. The pump out procedures need to be in the same			
specified format as other procedures and as the company has specified in their procedures. The owner or			
operator should make sure that shutdown procedures are available for all pieced of equipment.			
☐ Startup following a turnaround, or after emergency shutdown? [68.69(a)(1)(vii)]			

Facility Name: Prairie Farms Dairy, Inc. O'Fallon, IL			
The owner or operator stated that these procedures are the same as initial startup procedures, but this needs to			
be identified in the startup procedures.			
\square Operating limits: $[68.68(a)(2)]$			
 \infty Consequences of deviations [68.69(a)(2)(i)] \infty Steps required to correct or avoid deviation?[68.69(a)(2)(ii) 			
Safety and health considerations: [68.69(a)(3)]			
 Safety and hearth considerations. 100.07(a)(3)1 ☑ Properties of, and physical hazards presented by, the chemicals used in the process[68.69(a)(3)(i)] 			
Precautions necessary to prevent exposure, including engineering controls, administrative controls, and			
personal protective equipment? [68.69(a)(3)(ii)]			
□ Control measures to be taken if physical contact or airborne exposure occurs? [68.69(a)(3)(iii)]			
☑ Quality control for raw materials and control of hazardous chemical inventory levels? [68.69(a)(3)(iv)]			
☑ Any special or unique hazards? [68.69(a)(3)(v)]			
☐ Safety systems and their functions? [68.69(a)(4)]			
The owner or operator did not have any procedures regarding safety systems.			
15. Are operating procedures readily accessible to employees who are involved in a process? [68.69(b)]	⊠Y	□N	□ N/A
16. Has the owner or operator certified annually that the operating procedures are current and accurate and that	⊠Y	ΠN	□ N/A
procedures have been reviewed as often as necessary?[68.69(c)]			
17. Has the owner or operator developed and implemented safe work practices to provide for the control of	⊠Y	ΠN	□ N/A
hazards during specific operations, such as lockout/tagout? [68.69(d)]	١٠		
Lockout/tagout procedures are followed.			
Prevention Program - Training [68.71]			
18. Has each employee involved in operating a process, and each employee before being involved in operating a	$\boxtimes Y$	\Box N	□ N/A
newly assigned process, been initially trained in an overview of the process and in the operating			
procedures?[68.71(a)(1)]			
Initial training includes PHA I & II training, a mentoring program, MSDS training, hazard training, and exposure training. Those trained are given a group test. The owner or operator also stated			
that there is somewhat of a mentoring program for new employees.			
19. Did initial training include emphasis on safety and health hazards, emergency operations including shutdown,	⊠Y	ΠN	□ N/A
and safe work practices applicable to the employee's job tasks? [68.71(a)(1)]	اها	— 11	□ 1V/A
20. In lieu of initial training for those employees already involved in operating a process on June 21, 1999, an	ΠY	\Box N	⊠ N/A
owner or operator may certify in writing that the employee has the required knowledge, skills, and abilities to			
safely carry out the duties and responsibilities as specified in the operating procedures [68.71(a)(2)]			
21. Has refresher training been provided at least every three years, or more often if necessary, to each employee	⊠Y	\square N	□ N/A
involved in operating a process to assure that the employee understands and adheres to the current operating			
procedures of the process? [68.71(b)]			
The owner or operator stated that the facility offers training through HQ. The training covers			
IIAR material, PSM, PHA's, operating procedures, hot work, MSDS, and exposure to ammonia.			
The owner or operator must make sure that all employees who are required to attend training, do so and sign in to each training and this documentation be kept on file at the facility.			
22. Has owner or operator ascertained and documented in record that each employee involved in operating a	ΠY	$\boxtimes N$	□ N/A
process has received and understood the training required?] All training documents that reflect any of the training taken by employees involved in operating			
the ammonia system should be kept on file. Training documents were missing or incomplete at			
the time of the inspection.			
23. Does the prepared record contain the identity of the employee, the date of the training, and the means used to	ΠY		⊠ N/A
	<u> </u>		ا ۱۷/ <i>۲</i> ۱
verify that the employee understood the training? [68.71(c)]			

Program Level 3 Process Checklist

Facility Name: Prairie Farms Dairy, Inc. O'Fallon, IL

24. Has the owner or operator established and implemented written procedures to maintain the ongoing integrity of the process equipment listed in 68.73(a)? [68.73(b)] The owner or operator established a system to maintain the on-going integrity of the process equipment. Included in the procedures are a listing of general equipment. Recently the facility started documenting all tests and inspections on process equipment. Most PM work is conducted on weekends when there are less people at the facility. The owner or operator should also include their inspection sheet in their written procedures for this is the standard sheet used at the facility and should be specified as so in the written procedures.	⊠Y	ΠN	□ N/A
25. Has the owner or operator trained each employee involved in maintaining the on-going integrity of process equipment? [68.73(c)]	⊠Y	□N	□ N/A
26. Performed inspections and tests on process equipment? [68.73(d)(1)]	⊠Y	ΠN	□ N/A
27. Followed recognized and generally accepted good engineering practices for inspections and testing procedures? [68.73(d)(2)]	⊠Y	□N	□ N/A
28. Ensured the frequency of inspections and tests of process equipment is consistent with applicable manufacturers' recommendations, good engineering practices, and prior operating experience? [68.73(d)(3)]	⊠Y	□N	□ N/A
29. Documented each inspection and test that had been performed on process equipment, which identifies the date of the inspection or test, the name of the person who performed the inspection or test, the serial number or other identifier of the equipment on which the inspection or test was performed, a description of the inspection or test performed, and the results of the inspection or test? [68.73(d)(4)] The owner or operator should make sure that all process equipment tests, inspections, etc. are documented and kept on file. This includes yearly compressor work, relief valve change out, valve testing and change out, pipe thickness testing and any other work conducted on process equipment.	ΠY	⊠N	□ N/A
30. Corrected deficiencies in equipment that were outside acceptable limits defined by the process safety information before further use or in a safe and timely manner when necessary means were taken to assure safe operation? [68.73(e)]	⊠Y	□N	□ N/A
31. Assured that equipment as it was fabricated is suitable for the process application for which it will be used in the construction of new plants and equipment? [68.73(f)(1)]	⊠Y	□N	□ N/A
32. Performed appropriate checks and inspections to assure that equipment was installed properly and consistent with design specifications and the manufacturer's instructions? [68.73(f)(2)]	⊠Y	ΠN	□ N/A
33. Assured that maintenance materials, spare parts and equipment were suitable for the process application for which they would be used? [68.73(f)(3)]	⊠Y	ΠN	□ N/A
Prevention Program - Management Of Change [68.75]			
34. Has the owner or operator established and implemented written procedures to manage changes to process chemicals, technology, equipment, and procedures, and changes to stationary sources that affect a covered process? [68.75(a)] Management of change procedures were followed in 2001.	⊠Y	ΠN	□ N/A
35. Do procedures assure that the following considerations are addressed prior to any change: [68.75(b)] □ The technical basis for the proposed change? [68.75(b)(1)] □ Impact of change on safety and health? [68.75(b)(2) The owner or operator should not only make sure that procedures address this issue, but that each time MOC procedures are used, that specifically this issue is addressed in regards to the impact on that particular issue. □ Modifications to operating procedures? [68.75(b)(3)] □ Necessary time period for the change? [68.75(b)(4)]	ΣY	ΠN	□ N/A

₹a	cility Name: Prairie Farms Dairy, Inc. O'Fallon, IL			
	■ Authorization requirements for the proposed change? [68.75(b)(5)]			
	36. Were employees, involved in operating a process and maintenance, and contract employees, whose job tasks would be affected by a change in the process, informed of, and trained in, the change prior to start-up of the process or affected parts of the process? [68.75(c)]	⊠Y	□N	□ N/A
	37. If a change resulted in a change in the process safety information, was such information updated accordingly? [68.75(d)] A PHA should of been conducted in 2001.	ΩY	⊠N	□ N/A
;	38. If a change resulted in a change in the operating procedures or practices, had such procedures or practices been updated accordingly? [68.75(e)]	ΠY	□N	⊠ N/A
ı	Prevention Program - Pre-startup Safety Review [68.77]			
	39. Did the pre-startup safety review confirm that prior to the introduction of a regulated substance to a process: [68.77(b)] **A pre-startup safety review was never conducted. □ Construction and equipment was in accordance with design specifications? [68.77(b)(1)] □ Safety, operating, maintenance, and emergency procedures were in place and were adequate? [68.77(b)(2)] □ For new stationary sources, a process hazard analysis had been performed and recommendations had been resolved or implemented before startup? [68.77(b)(3)] □ Modified stationary sources meet the requirements contained in management of change? [68.77(b)(3)] □ Training of each employee involved in operating a process had been completed? [68.77(b)(4)]	□Y	⊠N	□ N/A
	Prevention Program - Compliance audits [68.79]			
	1. Has the owner or operator certified that the stationary source has evaluated compliance with the provisions of the prevention program at least every three years to verify that the developed procedures and practices are adequate and being followed? [68.79(a)] An Initial compliance audit was conducted in August of 2002, the next scheduled audit was in August 2005, after the July 15, 2005 inspection.	⊠Y	□N	□ N/A
	2. Has the audit been conducted by at least one person knowledgeable in the process? [68.79(b)]	⊠Y	ΠN	□ N/A
	3. Are the audit findings documented in a report? [68.79(c)]	⊠Y	ΠN	□ N/A
	4. Has the owner or operator promptly determined and documented an appropriate response to each of the findings of the audit and documented that deficiencies had been corrected? [68.79(d)] The owner or operator did not document that deficiencies had been corrected.	ΠY	⊠N	□ N/A
;	5. Has the owner or operator retained the two most recent compliance reports? [68.79(e)]	ΠY	ПN	⊠ N/A
	Prevention Program - Incident investigation [68.81]			
	 Has the owner or operator investigated each incident which resulted in, or could reasonably have resulted in a catastrophic release of a regulated substance? [68.81(a)] On March 13, 2003, the owner or operator stated that there was an incident at the facility. And Incident Investigation summary report dated 3/13/03 was reviewed. The incident caused a leak inside the engine room. The incident could of been prevented by installing a 250, not 150 SRV. The owner or operator should make sure that the procedures in place for incidents are followed whenever an incident occurs at the facility. 	⊠Y	□N	□ N/A
	2. Were all incident investigations initiated not later than 48 hours following the incident? [68.81(b)]	⊠Y	ΠN	□ N/A
	3. Was an accident investigation team established and did it consist of at least one person knowledgeable in the process involved, including a contract employee if the incident involved work of a contractor, and other persons with appropriate knowledge and experience to thoroughly investigate and analyze the incident? [68.81(c)]	⊠Y	□N	□ N/A

cility	Name: Prairie Farms Dairy, Inc. O'Fallon, IL			
4.	Was a report prepared at the conclusion of every investigation?[68.81(d)]	⊠Y	ΠN	□ N/A
5.	Does every report include: [68.81(d)] Date of incident? [68.81(d)(1)] Date investigation began? [68.81(d)(2)] A description of the incident? [68.81(d)(3)] The factors that contributed to the incident? [68.81(d)(4)] Any recommendations resulting from the investigation? [68.81(d)(5)]	⊠Y	□N	¹ N/A
6.	Has the owner or operator established a system to address and resolve the report findings and recommendations, and are the resolutions and corrective actions documented? [68.81(e)]	⊠Y	□N	□ N/A
7.	Was the report reviewed with all affected personnel whose job tasks are relevant to the incident findings including contract employees where applicable? [68.81(f)]	⊠Y	□N	□ N/A
8.	Has the owner or operator retained the incident investigation reports for five years? [68.81(g)]	⊠Y	□N	□ N/A
Se	ction D - Employee Participation [68.83]			
1.	Has the owner or operator developed a written plan of action regarding the implementation of the employee participation required by this section?[68.83(a)]	⊠Y	□N	□ N/A
2.	Has the owner or operator consulted with employees and their representatives on the conduct and development of process hazards analyses and on the development of the other elements of process safety management in chemical accident prevention provisions? [68.83(b)]	⊠Y	□N	□ N/A
3.	Has the owner or operator provided to employees and their representatives access to process hazards analyses and to all other information required to be developed under the chemical accident prevention rule? [68.83(c)]	⊠Y	□N	□ N/A
Se	ction E - Hot Work Permit [68.85]			
	Has the owner or operator issued a hot work permit for each hot work operation conducted on or near a covered process? [68.85(a)] e owner or operator should make sure hot work permit procedures are up to date and are ing followed whenever a hot work permit is issued.	⊠Y	□N	□ N/A
2.	Does the permit document that the fire prevention and protection requirements in 29CFR 1910.252(a) have been implemented prior to beginning the hot work operations? [68.85(b)]	⊠Y	ΠN	□ N/A
3.	Does the permit indicate the date(s) authorized for hot work and the object(s) upon which hot work is to be performed? [68.85(b]	⊠Y	□N	□ N/A
4.	Are the permits being kept on file until completion of the hot work operations? [68.85(b)]	⊠Y	□N	□ N/A
Se	ction F - Contractors [68.87]			
an ha	Has the owner or operator obtained and evaluated information regarding the contract owner or operator's safety performance and programs when selecting a contractor? [68.87(b)(1)] e owner or operator should maintain proper documentation from all contractors involved with y process equipment. Each contractor, according to company specific procedures, should ve on record an orientation checklists, safety declaration, performance evaluation, safety, and e-qualification checklists.	ΠY	⊠N	□ N/A
2.	Informed contract owner or operator of the known potential fire, explosion, or toxic release hazards related to the contractor's work and the process? [68.87(b)(2)]	⊠Y	ΠN	□ N/A
3.	Explained to the contract owner or operator the applicable provisions of the emergency response or the emergency action program? [68.87(b)(3)]	⊠Y	ΠN	□ N/A

acility Name: Prairie Farms Dairy, Inc. O'Fallon, IL								
4. Developed and implemented safe work practices consistent with §68.69(d), to control the entrance, presence, and exit of the contract owner or operator and contract employees in the covered process areas? [68.87(b)(4)]		ΠN	□ N/A					
Section G - Emergency Response [68.90 - 68.95]								
Developed and implemented an emergency response program as provided in 40 CFR 68.90-68.95? S N/A Comments: O'Fallon fire department has been specified as the first responder for this facility. They are a volunteer fire department though and are not all trained in responding to ammonia releases. The company may want to consider having a training both for employees and for the fire department to educated them on how to respond to ammonia releases. Although the company is not considered a first responder, the party that is, should have adequate training and knowledge.								
1. Is the facility designated as a "first responder" in case of an accidental release of regulated substances"	ΠY	⊠N	□ N/A					
1.a. If the facility is not a first responder:								
1.a.(1) For stationary sources with any regulated substances held in a process above threshold quantities, is the source included in the community emergency response plan developed under 42 U.S.C. 11003? [68.90(b)(1)] According to the owner or operator, the source is included in the community emergency response plan.	⊠Y	□N	□ N/A					
1.a.(2) For stationary sources with only regulated flammable substances held in a process above threshold quantities, has the owner or operator coordinated response actions with the local fire department? [68.90(b)(2)]	ΠY	ΠN	⊠ N/A					
1.a.(3) Are appropriate mechanisms in place to notify emergency responders when there is need for a response? [68.90(b)(3)]	⊠Y	ΠN	□ N/A					
 2. An emergency response plan which is maintained at the stationary source and contains the following? [68.95(a)(1)] a. Procedures for informing the public and local emergency response agencies about accidental releases? [68.95(a)(1)(i)] b. Documentation of proper first-aid and emergency medical treatment necessary to treat accidental human exposures? [68.95(a)(1)(ii)] c. Procedures and measures for emergency response after an accidental release of a regulated substance? [68.95(a)(1)(iii)] 	ΟY	□N.	⊠ N/A					
3. Procedures for the use of emergency response equipment and for its inspection, testing, and maintenance? [68.95(a)(2)]	ΩY	□N	⊠ N/A					
4. Training for all employees in relevant procedures? [68.95(a)(3)]	⊠Y	ΠN	□ N/A					
 Procedures to review and update, as appropriate, the emergency response plan to reflect changes at the stationary source and ensure that employees are informed of changes? [68.95(a)(4)] 	⊠Y	ΠN	□ N/A					
6. Did the owner or operator use a written plan that complies with other Federal contingency plan regulations or is consistent with the approach in the National Response Team's Integrated Contingency Plan Guidance ("One Plan")? If so, does the plan include the elements provided in paragraph (a) of 68.95, and also complies with paragraph (c) of 68.95? [68.95(b)]	ΠY	□N	⊠ N/A					
 Has the emergency response plan been coordinated with the community emergency response plan developed under EPCRA? [68.95(c)] According to the owner or operator, the emergency response plan has been coordinated with the community emergency response plan developed under EPCRA. 	⊠Y	ΠN	□ N/A					
Section H - Risk Management Plan [68.190 - 68.195]								
1. Has the owner or operator reviewed and updated the RMP and submitted it to EPA [68.190(a)]? Reason for	⊠Y	ΠN	□ N/A					

Facili	ity Na	ame: Prairie Farms Dairy, Inc. O'Fallon, IL			
	upo	late.			
[X	Five-year update. [68.190(b)(1)]			
1	3	Within three years of a newly regulated substance listing: [68.190(b)(2)]			
	_	At the time a new regulated substance is first present in an already regulated process above threshold quantities. [68.190(b)(3)]			
(_	At the time a regulated substance is first present in a new process above threshold quantities. [68.190(b)(4)]			
(_	Within six months of a change requiring revised PHA or hazard review. [68.190(b)(5)]			
(_	Within six months of a change requiring a revised OCA as provided in 68.36. [68.190(b)(6)]			
(_	Within six months of a change that alters the Program level that applies to any covered process. [68.190(b)(7)]			
reporting submit th		the owner or operator experienced an accidental release that met the five-year accident history porting criteria (as described at 68.42) subsequent to April 9, 2004, did the owner or operator bmit the information required at 68.168, 68.170(j) and 68.175(l) within six months of the release or the time the RMP was updated as required at 68.190, whichever was earlier. [68.195(a)]	ΠY	□N	⊠ N/A
3.		he emergency contact information required at 68.160(b)(6) has changed since June 21, 2004, did e owner or operator submit corrected information within thirty days of the change? [68.195(b)]	ΠY	□N	⊠ N/A