



RE: Floor drain seal
 customdesignsnwoodinc to: Jim Eppers

2009 DEC -7 PM 2:59
 04/08/2009 04:36 PM

History: This message has been forwarded.

FILED
 EPA REGION VIII
 HEARING CLERK

I am trying to down load the pictures but like I said I am not that pro computer. I will send the pictures my mail per your instructions. The items filled were not wells they were simple 10" round floor drains. The closure was accomplished the first week in October 2008. I am not delaying anything. I will put the pictures in the mail by Friday. For three simple little floor drains I don't see the requirement for a penalty.

-----Original Message-----

From: Eppers.Jim@epamail.epa.gov [mailto:Eppers.Jim@epamail.epa.gov]
 Sent: Wednesday, April 08, 2009 4:26 PM
 To: customdesignsnwoodinc
 Subject: Re: Floor drain seal

Royce,

Please get the required information to me immediately.

I need clear photos that show us that the Class V well is permanently closed and the date on which you closed it. If you can't send me the photos by email, mail them to me at the address below.

Delaying your submittal of this information will make it difficult if not impossible for the agency to waive a civil penalty in this case.

Jim Eppers
 Senior Attorney
 Legal Enforcement Program
 USEPA Region 8
 1595 Wynkoop Street (ENF-L)
 Denver, CO 80202-1129
 303-312-6893
 FAX: 303-312-6953
 e:mail eppers.jim@epa.gov

Notice: This message may contain privileged or other confidential information. If you are not the intended recipient, or believe that you have received this communication in error, please delete the copy you received and do not print, copy, retransmit, disseminate or otherwise use the information.

"customdesignsnw
 oodinc"
 <petewillson@qwe
 stoffice.net>

Jim Eppers/R8/USEPA/US@EPA

To

04/02/2009 01:09
PM

cc

Subject

Floor drain seal

Jim,

I did try to email you a description of the work done to seal the three small floor drains and since that time my computer crashed and I lost everything.

We filled the drains with concrete as far down as we could. The trap that is at the bottom of the drain is as far as we could go which is more than adequate to prevent any seepage from occurring. I will take some additional pictures and try to send to you as an attachment which will show the concrete to the floor level in the effected bays. Please keep in mind I am not the most pro computer person in the world. As far as receipts go I just bought some concrete at the local hardware store and never thought about keeping a receipt for \$10.00 so I have no documented evidence except for the pictures that show the drains filled to the floor level. This should be more than enough to settle this small issue.

Royce Willson
JPW holdings, LLC
Manager