



Memo

Date: 11/26/2007

To: Scott Gold

From: Jim Sorgatz

RE: Water Loss RV Park / Line Main Break

Scott,

A sever water leak was found yesterday, November 25th, 2007 at the end of row E on a 2" water main in the RV Park.

This 2" line discharges roughly 85 gallons per minute and by the meter readings and estimations from previous use for time frames I am estimate that we lost approximately 25,600 gallons.

This breakage occurred at the end of the main where it connects to the row mains. If you recall we had a break on a row main a few months ago. This line breakage appeared to be the result of ground settling and coupler separation.

This breakage also deteriorated a large portion of the RV Park road area.

I am sure that this would have been noticed sooner however the RV Park is almost empty due to the time of year and we are approaching our off season. The reason I caught this was the excessive gallon age use that appeared on the meters on the AM of November 25th.

These line are going to be shut down in 2 weeks for winter closure of rows D-F but I am going to recommend to the chief of maintenance that we perform twice daily drive through inspections in the park until the lines are shut down when the park business volume drops, say Starting September 15th -Dec 10 annually.

Jim Sorgatz

Licensed Operator

Mormon Lake Properties LLC Water System.



Memo

Date: 08/26/2007

To: Scott Gold, GM

From: Jim Sorgatz

RE: Water Line Break RV Park

Scott,

This notice is to inform you that a water line break was found on August 23rd on a 1 ½ inch row main water line.

By estimation the break occurred at 1:00 – 1:50 AM and was found at 5:40 AM. This line discharges roughly 70 gallons per minute and by this estimate and the meter readings from the previous day reading period I estimate that we lost approximately 16,800 gallons.

The break occurred at a 90 (elbow) cause which appeared to be chemical weakening from PVC glue that was used to bond joint or bad glue joint form the start.

To rectify the problem the line was excavated and the 90 was replaced and glued appropriately.

Jim Sorgatz

Licensed Operator

Mormon Lake Properties LLC Water System.