

ACTION: Final

DATE: 08/19/2003 1:48 PM

3745-18-04

Measurement methods and procedures.

①

(J) Any owner or operator of any sulfur dioxide source subject to, and not specifically exempted from, paragraphs (B)(4), (B)(5), (B)(6), (B)(7), (B)(8), (B)(11), (B)(13) and (B)(14) of rule 3745-18-49 of the Administrative Code, "Lubrizol Corporation" processes "L", "M", "N", "O", "W" and "AC" (OEPA source numbers P011, P012, P013, P014, P022 and P030), shall demonstrate compliance with the combined hourly emission limits by performing emission tests in accordance with Method 6 or Method 6C in 40 CFR Part 60, Appendix "A", and by employing the continuous emission rate monitoring system. The combined allowable sulfur dioxide emission limit for these processes for any hour shall be the sum of the individual allowable sulfur dioxide emissions limits for those processes that are in operation during any part of that hour. The combined allowable sulfur dioxide emission limit for these processes for any rolling three hour period shall be the average of the three, one hour allowable limits comprising the three hour period.

[Comment: For dates of non-regulatory government publications, publications of recognized organizations and associations, federal rules, and federal statutory provisions referenced in this rule, see rule 3745-18-01(C) of the Administrative Code titled "Incorporation by Reference."]

3745-18-04

Effective: 09/01/2003

R.C. 119.032 review dates: 12/31/2005

CERTIFIED ELECTRONICALLY

Certification

08/19/2003

Date

Promulgated Under: 119.03
Statutory Authority: 3704.03
Rule Amplifies: 3704.02
Prior Effective Dates: 12/28/79, 11/1/84, 5/11/87,
6/15/89, 10/31/91, 3/21/00