

DRAFT

Rule 463 Inspection and Maintenance Plan Approval

Facility ID : 800198 - Company Name : Ultramar/Valero Marine Terminal

LEGAL OWNER OR OPERATOR Ultramar/Valero Marine Terminal
FACILITY LOCATION 961 La Paloma Avenue, Wilmington, CA 90744
MAILING ADDRESS Same

ADMINISTRATIVE REQUIREMENTS

This facility shall be subject to the terms and conditions of this plan unless this plan is suspended, revoked, modified, reissued or denied. Failure to maintain a valid plan is a violation of Rule 463.

It is the responsibility of the facility to comply with other District Rules and Regulations and with all laws, ordinances and regulations of other government agencies which are applicable to the operation of the equipment.

This plan does not authorize the emission of air contaminants in excess of those allowed by Division 26 of the Health and Safety Code of the State of California or the Rules and Regulations of the AQMD. This plan cannot be considered as permission to violate existing laws, ordinances, regulation, or statutes of the other governmental agencies.

RULE 463 EQUIPMENT

Floating Roof Tanks as listed in submitted plan.

CONDITIONS

1. The operator shall conduct the operation of the storage equipment in compliance with all data and specifications submitted with the plan application under which this approval is granted.
2. Floating roof tank seals shall be properly installed and continuously maintained in good operating condition.

**Valero Marine Terminal
FID #800198**

Table 1.1 - Inventory of Floating Roof Tank Subject to SCAQMD Rule 463

Tank ID #	Maximum Capacity (barrels)	Product *	Shell Type	Roof Configuration	Date of Construction	Dimensions		Seal Manufacturer	Seal Type, Primary	Seal Type, Secondary	Proposed Inspection Schedule **
						tank dia (ft)	tank ht (ft)				
99-TK-42501	45,114	Alkylate	welded	IFR	1977	80	50	HMT	mech shoe	wiper	Mar-Apr, Sep-Oct
99-TK-42502	45,114	Iso-Oct	welded	IFR	1977	80	50	HMT	mech shoe	wiper	Mar-Apr, Sep-Oct
99-TK-67001	71,901	Raffinate	welded	DEFER	1959	100	51	HMT	mech shoe	wiper	May-Jun, Nov-Dec
99-TK-67002	71,901	Raffinate	welded	DEFER	1959	100	51	HMT	mech shoe	wiper	Mar-Apr, Sep-Oct
99-TK-67003	67,671	Raffinate	welded	DEFER	1959	100	48	HMT	mech shoe	wiper	Mar-Apr, Sep-Oct
99-TK-67004	67,671	Reformat	welded	DEFER	1959	100	48	HMT	mech shoe	wiper	Mar-Apr, Sep-Oct
99-TK-120001	126,574	RGO	welded	IFR	1977	134	50	HMT	mech shoe	wiper	Mar-Apr, Sep-Oct
99-TK-120002	126,574	LCO	welded	IFR	1974	134	50	HMT	mech shoe	wiper	May-Jun, Nov-Dec
99-TK-120003	126,574	Naphtha	welded	IFR	1977	134	50	HMT	mech shoe	wiper	Mar-Apr, Sep-Oct
99-TK-120004	126,574	RGO	welded	IFR	1977	134	50	HMT	mech shoe	wiper	May-Jun, Nov-Dec

Floating Roof Configuration: IFR - Internal Floating Roof
DEFER - Domed External Floating Roof

* Represents typical product. Product may change as needed within permitted allowances.

** Actual inspection schedule may vary depending on operational needs and availability of inspectors within the inspection requirements as outlined in Rule 463(e)(3).

**Valero Marine Terminal
FID #800198**

Table 1.2 - Inventory of Storage Tanks Not Subject to All Sections of SCAQMD Rule 463

ID #	Maximum Capacity (barrels)	Product *	Shell Type	Roof Configuration	Date of Construction	Dimensions		Seal Manufacturer	Seal Type, Primary	Seal Type, Secondary	Proposed Inspection Schedule **
						tank dia (ft)	tank ht (ft)				
99-TK-7301	7,491	Slop Oil	welded	IFR	1940	36	41	HMT	mech shoe	wiper	Mar-Apr, Sep-Oct
99-TK-7302	7,491	Slop Oil	welded	IFR	1940	36	41	HMT	mech shoe	wiper	Mar-Apr, Sep-Oct
99-TK-11001	11,531	Decant	welded	IFR	1940	48	35.5	Tarsco	mech shoe	wiper	Mar-Apr, Sep-Oct
99-TK-21001	20,809	Decant	welded	IFR	1940	60	41	Tarsco	mech shoe	wiper	Mar-Apr, Sep-Oct
99-TK-30001	33,159	Decant	welded	FIXED	1951	70	48	na	na	na	na
99-TK-30002	33,159	Decant	welded	FIXED	1951	70	48	na	na	na	na
99-TK-40001	39,500	RGO	welded	FIXED	1940	78	70	na	na	na	na

Floating Roof Configuration: IFR - Internal Floating Roof

* Represents typical product. Product may change as needed within permitted allowances.

** Actual inspection schedule may vary depending on operational needs and availability of inspectors within the inspection requirements as outlined in Rule 463(e)(3).