



South Coast Air Quality Management District

21865 Copley Drive, Diamond Bar, CA 91765-4178
(909) 396-2000 • www.aqmd.gov

June 1, 2012
via electronic submittal

Mr. Gerardo Rios
U. S. EPA, Region IX
Mail Stop A-5-2
75 Hawthorne Street
San Francisco, California 94105

Dear Mr. Rios:

**RE: Proposed De Minimus Significant Revision to Title V Permit
SFPP, L.P. (ID# 800129)**

Enclosed for your 45-day review is the proposed revision to the Title V Permit, as described below, for SFPP, L.P. located at 2359 Riverside Ave., Bloomington, CA. This revision is considered a “de minimus significant permit revision”, and a public notice is not required.

We are enclosing the revised permits, to be added to Sections D, as shown below and the engineering evaluation.

Section D: Permits to Operate

<i>New Appl. No.</i>	<i>Previous Appl. No.</i>	<i>Description</i>
530380	454673	Tank C-1 (Add throughput and vapor pressure condition, list allowable commodities)
530381	460357	Tank C-2 (Add throughput and vapor pressure condition, list allowable commodities)
530382	532703 (Permit to Construct) 334998	Tank C-4 (Add throughput and vapor pressure condition, list allowable commodities)
530384	446062	Tank C-8 (Add throughput and vapor pressure condition, list allowable commodities)
530385	444959	Tank C-21 (Add throughput and vapor pressure condition, list allowable commodities, remove recirculating line)
530388	194585	Tank C-22 (Add throughputs and allowable commodities)
530389	474542	Tank C-42 (Add biodiesel and biodiesel blend stock to

		allowable commodities)
530394	474547	Rack No. 1 (Add biodiesel and biodiesel blendstock to allowable commodities)
530395	474548	Rack No. 6 (Add biodiesel and biodiesel blendstock to allowable commodities)
530396	474546	Rack No. 7 (Add biodiesel and biodiesel blendstock to allowable commodities)
530398	335000	Rack No. 4A (Bay No. 1) (Add throughput and commodity condition, remove manufacturer name, and remove redundant condition requiring vapor recovery during switch loading since all arms are now connected to vapor recovery)
530400	335002	Rack No. 4A (Bay No. 2) (Add throughput and commodity condition, remove manufacturer name, and remove redundant condition requiring vapor recovery during switch loading since all arms are now connected to vapor recovery)

This revision is covered under A/N 532705.

This request is being made via electronic submittal in order to facilitate this review.

If you have any questions or wish to provide comments regarding this project, please contact Ms. Linda Dejbakhsh at (909) 396-2614 (email: LDejbakhsh@aqmd.gov) or Mr. Thomas Liebel at (909) 396-2554 (email: tliebel@aqmd.gov).

Very truly yours,



Jay Chen, P.E.
Senior Engineering Manager
Refinery and Waste Management Permitting

JC:CDT:LLD
Enclosures
(epacoverdeminimusrev6biodieselPhase 2 AN530380)

cc: Yijin Wang (no enclosures)
TV A/N 532705
A/N 530380