Exhibit 1




Figure 1: Facility report for Greater Lawrence Sewer District. Note that the member communities of the sewer district are co-permittees with Greater Lawrence Sewer District.




Figure 2: More of facility report for Greater Lawrence Sewer District. The listed penalty does not indicate to which permittee the violation is attributed. Note that inspection, enforcement, monitoring and compliance history are all tracked by permit number.




Figure 3: NPDES three year compliance status by quarter from facility report for Greater Lawrence Sewer District. This too is tracked by permit number, with no indication of which permittee was in violation.