Mr. Duke Pontin 66-532 Kamehameha Highway Haleiwa, Hawaii 96712

Dear Mr. Pontin:

SUBJECT: 66-532 Kamehameha Highway

Facility ID 9-202483

The Department of Health has reviewed the following report: *UST Removal and Closure Report*, dated June 17, 2018 and prepared by yourself regarding the removal of one (1) 550-gallon underground storage tank (UST) at the subject site. Please note the report has been placed with the public record.

DOH notes the UST previously stored used oil. The report states the UST was drained of used oil and stored in drums. Unitek removed the drums in November 2017. The UST was excavated and removed from the ground on May 31, 2018 and soil samples were collected from the excavation.

Laboratory analyses of the soil samples were largely non-detectable for contaminants with the exception of 4.4 mg/kg of Total Petroleum Hydrocarbons as oil (TPH-o) vs. the DOH environmental action level (EAL) of 500 mg/kg. PCBs, chlorinated solvents, and metals were non-detectable in the soil samples.

Based on the information provided, DOH concurs that a UST release has not occurred and issues a status of *No Further Work* (NFW) for the subject UST system.

Please note that Hawaii UST regulations require evidence of petroleum or other stored substances discovered in the sub-surface of current or former UST facilities to be reported to DOH UST at (808) 586-4226 within 24 hours, including contamination found at concentrations below EALs and contamination found after receiving a status of NFA or NFW.

Generally, further work will not be required if contaminant concentrations are below appropriate EALs but notification to this office is required within 24 hours. If you have any questions regarding this letter, please contact Mr. Richard Takaba of our Underground Storage Tank Section at (808) 586-4226.