

**LARGE CAPACITY CESSPOOL (LESS THAN 1,000 GPD)
BACKFILLING FINAL COMPLETION REPORT**
US Environmental Protection Agency – Region 9 Ground Water Office

Property owner: NSHE HI NARCISSUS, LLC (DUKE PONTEN)

Project address: 66-540 KAMEHAMEHA HWY, HALEIWA, HI

TMK: 1-6-2-007-019

Number of cesspools, and numbering if any: 1

Diameter(s): 5' Depth(s): 10'

Was sludge/sediment or liquid removal necessary? Yes No

Where was sludge/sediment or liquid taken or disposed of? ABC PUMPING

Was groundwater encountered? Yes No

Date of backfilling: 12/2/2021 Type of backfill material: R, C, S

Amount of backfill used (cubic yards): 8

Was the cesspool completely backfilled? Yes No

How was it compacted? VIBRATOR & HAND COMPACTION

Backfilling contractor: ANCHOR BUILDERS HAWAII LLC (BC-37198)

Please provide:

- Pictures: Attach photos of the large capacity cesspool from step-back distances of approximately 8 feet and 20 feet.
- Copy of this report to: LCC Program Coordinator
EPA Ground Water Office (WTR-9)
75 Hawthorne Street
San Francisco, CA 94105

LARGE CAPACITY CESSPOOL BACKFILLING FINAL COMPLETION REPORT (Continuation)

The backfilling work and the final completion report have been performed and completed under my supervision, and the work was properly completed:

- Architect
- Geologist
- Licensed Contractor License Number: BC-37198
- Licensed Plumber License Number: _____
- Professional Engineer Include P.E. stamp:

Printed Name: Scott Olson

Signature: 

Date: 12/2/2021

Company: Anchor Builders Hawaii LLC

Address: PO. Box 971, LASE, HI 96762

Phone: 808-421-8156 Fax: _____