




Composite 2D lines taken from the MW1 location and running adjacent to the CCS3 location in the E-W and N-S directions demonstrate that no major faults or subsurface hazards were observed in the 2D seismic data.


2D Composite Line from MW 1 well to CCS 3 well (E-W adjacent to CCS 3):



2D Composite Line from MW 1 to CCS 3 (N-S adjacent to CCS 3):



Arbitrary line from MW1 to CCS3:



Arbitrary line from J&L Steel to CCS3:

