Attachment 3 Photo Log

Figure 1: Exposed pipe and cable along shore of net depot area.

Figure 2: Shoreline Protection system in front of the landfill.

Figure 3: Exposed filter fabric on the shoreline protection system.

Figure 4: Plantings on landfill cover.

Figure 5: MW-06 Abandoned in place with bentonite grout.

Figure 6: Gas vent on landfill.

Figure 7: Standing water in perimeter drain.

Figure 8: Scott's broom on landfill cover.

Figure 9: Landfill cover.

Figure 10: West side of landfill cover.

Figure 11: Fir tree on landfill cover.

Figure 12: Horse tail growing in perimeter drain.

Figure 13: Scott's broom on landfill cap.

Figure 14: Scott's broom growing on shoreline protection system.

Figure 15: Landfill cover from south side.