

LEGEND

- Burial Trench
- Landfill Boundaries
- Facility and Zone 1 Boundary
- Perimeter Source Control Trench (PSCT)
- Plume Capture Collection Trench (PCT)
- Clay Barrier
- Creek
- Pond Outline
- RGPZ-15B — Lower HSU Piezometer
- RP-63C — Lower HSU Monitoring Well
- MET — Meteorological Station
- Gauged Measurement of DNAPL through March 2010
- Dissolved Concentrations of DNAPL Constituents greater than 1% of aqueous solubility
- Dissolved Concentrations of DNAPL Constituents greater than 10% of aqueous solubility
- Former Pond and Pad Subarea
- Historical Natural Drainage
- Dissolved Concentrations of Freon 113 greater than 1% and 10% of aqueous solubility

Note: Dissolved concentrations of DNAPL inferred surrounding areas of measurable DNAPL.

NO.	DATE	REVISIONS	BY	CHK

DRAWN:	PCB	PROJECT NO:	4088097619
ENGINEER:		SCALE:	1"= 400'
CHECKED:	NM	APPROVED:	WJF
DATE:	1/2011	DATE:	1/2011

Final Remedial Investigation Report

Casmalia Resources Superfund Site
Casmalia, California

DNAPL in Upper HSU Observed or Inferred from Groudwater Concentrations Fall 2004 and Spring 2005 RI Sampling

FIGURE **F-34**
SHEET: **1** OF **1**
REVISION NUMBER: 0
DATE: January 2011