

FigureF3-10_WL7_2001.mxd

Observed Water Levels for Layer 7
March 2001
Final Remedial Investigation Report
Casmalia Resources Superfund Site
Casmalia, California

FIGURE
F3-10

DRAWN	JOB NUMBER	APPROVED	CHECKED	DATE	REVISED DATE
TFC	0020784 00.01	BB		01/2011	