


**EXPLANATION**

- Existing cap limits
- Major (10') contour intervals, 10' to 90'
- Minor (2') contour intervals
- Zero-line
- Minor (-2') contour intervals
- Major (-10') contour intervals, -10' to -50'
- M Approximate location of former pond/pad

Note: South Borrow Area reflects 1987 vs. 2002 topography



**FIGURE W-3**  
**Cut-Fill Map**  
**1987 Versus 1998**  
**Site Topography**  
 Final Remedial Investigation Report  
 Casmalia Resources Superfund Site  
 January 2011