

Legend

- Los Angeles City Flood Control District Monitoring Well
- EPA Monitoring Well
- Facility Monitoring Well
- Production Well
- PRP Monitoring Well
- UST Monitoring Well
- Syncline
- Anticline
- Direction of Plunge

Cross Section Locations

- A — A'
- B — B'
- C — C'
- D — D'
- E — E'
- F — F'

- Faults (short dash indicates that fault impedes groundwater flow)
- [2]Fault Surface Features
- Highway
- Major Street
- Railway
- Streams
- Structural Bedrock Discontinuity
- Area 3 Site
- Spreading Ground
- [3]Alluvium (Quaternary)
- [3]Pico Formation (Pliocene)
- [3]Puente Formation (Upper Miocene)
- [3]Topanga Formation (Middle Miocene)

Notes:

1. Treiman, J.A., 1991. Whittier Fault Zone, Los Angeles and Orange Counties, California: California Division of Mines and Geology Fault Evaluation Report FER-222.
2. California Division of Mines and Geology Geologic Map of Elysian Park – Repetto Hills Area, Los Angeles Counties California. Mapped 1958-1960. Revised and Extended 1961-1965.

This figure (3-4) is the same as Figure D-7 in Appendix D.

N

0 1,750 3,500 7,000

Feet

Figure 3-4
Locations of Wells and Hydrogeologic Cross Sections
San Gabriel Valley Area 3
Superfund Site Remedial Investigation

\\galt\GIS2\EPAF\ALOU\2008\MapFiles\ALOU_GeologicXsection_v3.mxd