Appendix A
Historical Mine Photographs

HISTORIC PHOTO A-1
1952-1953 FIRST AERIAL PHOTO –
ON THE LEFT IS THE FUTURE PIT LAKE LOCATION, IN THE BACKGROUND IS WEED HEIGHTS UNDER CONSTRUCTION, AND THE LOWER RIGHT IS THE FUTURE PROCESS AREA

ANACONDA MINE SITE
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-2
1953 NOVEMBER 6
ORE STORAGE BIN
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-3
1953 LEACH VAT CONSTRUCTION
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-4
1953 LEACH VAT COMPLETION
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



HISTORIC PHOTO A-5
1953 LEACH VAT PHOTO
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-6
1953 IRON LAUNDERS AND TIN CAN PILE
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-7
1953 IRON LAUNDERS – CEMENTATION
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-8
1953 MAGNETIZING IRON FOR CEMENTATION
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-9
GANTRY CRANE AT IRON LAUNDER
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



HISTORIC PHOTO A-10
1953 OCTOBER 27 IMAGE OF ACID PLANT
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-11
1954 ACID PLANT
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



SOURCE: BROWN AND CALDWELL, 2003b

ES092209222513RDD_A-12 (1/29/10)

HISTORIC PHOTO A-12
1954 AERIAL PHOTO – YERINGTON MINE
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-13
1956 AERIAL PHOTO PIT
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-14
1956 FIRST COLOR AERIAL PHOTO
ANACONDA YEARINGTON MINE SITE
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-15
1956 AERIAL PHOTO PIT AND PROCESS AREA
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-16
1957 AERIAL PHOTO
PROCESS AREA_2

HISTORIC PHOTO A-17
1958 PRIMARY AND SECONDARY CRUSHERS AND HISTORIC ANACONDA WATER TOWER
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-18
1960 CONSTRUCTION OF SULFIDE PLANT AND TAILINGS DAM
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-19
1961 AERIAL PHOTO
PROCESS AREA
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

SOURCE: HISTORICAL DOCUMENTS ARCHIVES

HISTORIC PHOTO A-20
1962 HISTORIC SULFURIC ACID PLANT
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-21
1962 AERIAL PHOTO OF MINE SITE LOOKING WEST
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-22
1962 AERIAL PHOTO OF PROCESS AREA AND PIT LOOKING SOUTHEAST
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-23
1962 LEACH VAT PHOTO 3
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



HISTORIC PHOTO A-24
1962 LEACH VAT PROCESS AREA PHOTO
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE



HISTORIC PHOTO A-25
1962 PHOTO OF FLOTATION PLANT
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-26
1962 TAILINGS DAM
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE

HISTORIC PHOTO A-27
1963 AERIAL PHOTO MINE SITE
LOOKING WEST NORTHWEST
HISTORICAL SUMMARY REPORT
ANACONDA-YERINGTON MINE